

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 09/30/2008**

SPILL ID# 20080817NE71-1 BRRTS# 04-71-552383

04-71-552383

Incident Date & Time: 08/17/2008	Reported Date & Time: 08/17/2008 08:05	BRRTS No: 04-71-552383	Spill ID: 20080817NE71-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 09/29/2008

Location			
Region: NE	County: Winnebago	Municipality: OSHKOSH, CITY OF	
Facility/Property Name and Street Address: OSHKOSH CORP 333 W 29TH ST		Description: SOUTH PLANT YARD	
Facility Type: Industrial Facility (foundry, factory, platter, etc)			
Lat/Long:		PLSS:	WTM:
Weather Conditions: Sunny			

Responsible Parties			
Name/Address (1): OSHKOSH CORP 333 W 29TH ST OSHKOSH, WI 54902- (920) 267-1099 x Primary	Contact: BRYAN OLSON ENVIRONMENTAL ENGINEER (920) 267-1099 x primary (920) 233-9464 x secondary	Other Contact: SUE MURAWSKI SR PROJECT ENGINEER (920) 233-9592 x primary	Spill Packet:

Cause
EQUIPMENT MALFUNCTION ON VEHICLE - TRUCK PARKED ON GRAVEL HAD A LEAKING FUEL VALVE

Cause Type: LEAKING FUEL VALVE

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Diesel		25.0 Gal	25.0 Gal	LIQUID		

Environmental Impacts / Damages			
Environmental Impacts: SOIL	Resource Damages: No	Injuries: No	Evacuation: No

Cleanup Actions	
Method	Description
Absorbent (oil dry, sand, sawdust)	
Excavation	APPROXIMATELY 30 YARDS EXCAVATED

Cleanup Action Comments
20 FT X 20 FT AREA - ABSORBANT PADS APPLIED AND THE CONTAMINATED GRAVEL WAS EXCAVATED.

Contractors Hired	
Name	Description

Waste Destinations	
Location	Description
VEOLIA GLACIER RIDGE LANDFILL, HORICON WI	21.17 TONS OF CONTAMINATED SOIL

Agencies Notified / On Scene

**State of Wisconsin - Department of Natural Resources
 Substance Release Notification Report (SERTS)
 Report created on 09/30/2008**

SPILL ID# 20080817NE74-1
 BERTS# 04-71-552383

Agency	Notified	On Scene		
DHFS	X			
DIV EMERG MGT	X			
DNR	X			
Additional Comments				
08-20-08, MOELLER WAS CONTACTED BY BRYAN AND SUE (OSHKOSH CORP). THE SPILL WAS CLEANED UP RIGHT AWAY. ABSORBENT WAS PUT DOWN AND THE CONTAMINATED GRAVEL WAS SCRAPPED UP AND PLACED INTO A VEOLIA ROLL-OFF DUMSPTER. THE GRAVEL WAS EXCAVATED TO A DEPTH OF APPROXIMATELY 15 INCHES, DOWN TO CLAY, TO ENSURE THAT ALL OF THE DIESEL WAS RECOVERED. SUE WILL SEND MOELLER A CLEAN UP REPORT WHEN COMPLETE. 09-26-08, MOELLER RECIEVED CLEAN UP REPORT FROM OSHKOSH CORP.				
Enforcement Actions				
Enforcement action? No				
Case Activity Report Numbers:				
Person Reporting				
Name	Representing / Address	Primary Phone	Secondary Phone	
BRYAN OLSON	OSHKOSH CORP	(920) 267-1099 x		
Contractors Hired				
Name / Address	Zone Contractor Hired by DNR?			
	No			
Contacts				
Role	Name / Address	Office Phone	Date	Time
Prepared By:	Crystal Stace	(608) 266-2621 x	08/17/2008	
Person Notified:	JASON HIGGINS		08/17/2008	
Investigated By:	JASON MOELLER	(920) 662-5492 x	08/18/2008	
Incident Commander:				
Spill Coordinator:	NE - MOELLER, JASON [P] 920-662-5492		09/29/2008	
Electronic Attachments (list)				
Name	Type			

OSHKOSH CORPORATION

ISO 9001 CERTIFIED

2307 OREGON STREET
POST OFFICE BOX 2566
OSHKOSH, WISCONSIN 54903-2566
920-235-9151



Certified Mail, Return Receipt Requested

September 25, 2008

Jason Moeller
Wisconsin Department of Natural Resources
Northeast Regional Office
2984 Shawano Ave., P.O. Box 10448
Green Bay, WI 54307-0448




Subject: Diesel Fuel Spill, August 17, 2008

Dear Jason,

On August 17, 2008 at approximately 7:30 am, Oshkosh Corporation reported a release of diesel fuel to the DNR 24-hour Spill Hotline. The fuel was released on a gravel portion of the South Plant yard located at 333 W. 29th Ave, Oshkosh WI, 54902 due to an equipment malfunction. The spill was completely contained within the property, in an area approximately 20 feet by 20 feet. At that time, approximately five gallons of free liquid was recovered using absorbent materials.

On August 18, 2008, the impacted soil/gravel was excavated by an outside contractor to a depth of approximately 15 inches, into hard pack clay and loaded into containers supplied by Veolia Environmental Services. The area was excavated until no visual or olfactory evidence of fuel remained and was backfilled with clean gravel. Approximately 30 yards of soil, totaling 21.17 tons in weight was bio-piled at Veolia Environmental Services Glacier Ridge Landfill Facility. The certificate of disposal from the Glacier Ridge Landfill Facility is attached.

Oshkosh Corporation is respectfully requesting full closure of this spill incident. If you have any questions or concerns, please contact me at (920) 233-9464. Thank you.


Bryan Olson
Environmental Engineer

Attachment

cc. Don Draxler




CERTIFICATE OF DISPOSAL

presented to:

Oshkosh Corporation

This is to certify that 21.17 tons of Contaminated Soil,
Special Waste Profile #GRL 08070B
were properly disposed of at the
Veolia ES Glacier Ridge Landfill Facility
in accordance with License #03068.

Dated: September 12, 2008



John H. King
General Manager

Veolia ES Glacier Ridge Landfill, LLC
N7296 Highway V
Horicon, WI 53032
(920) 387-0987