

State of Wisconsin - Department of Natural Resources
 Substance Release Notification Report (SERTS)
 Report created on 10/21/2010

SPILL ID# 20100922NE71-1 BRRTS# 04-71-556207

04-71-556207

Incident Date & Time: 09/22/2010	Reported Date & Time: 09/22/2010 0840	BRRTS No: 04-71-556207	Spill ID: 20100922NE71-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 10/12/2010

Location			
Region: NE	County: Winnebago	Municipality: OSHKOSH, CITY OF	
Facility/Property Name and Street Address: OSHKOSH CORP SOUTH PLANT 333 W 29TH ST		Description: SOUTH PLANT YARD GRAVEL LOT	
Facility Type: Industrial Facility (Foundry/Factory/Plating/Manufacturing)			
Lat/Long:	PLSS:	WTM: 636512 391176	
Weather Conditions: <i>added to SDE - MGS - 06/07/11</i>			

Responsible Parties			
Name/Address (1): OSHKOSH CORP 2307 OREGON ST OSHKOSH, WI 54903- (920) 235-9151 x Primary	Contact: TOM MOSER (920) 233-9321 x primary	Other Contact: SUE MURAWSKI SR ENVIRON ENGINEER (920) 233-9582 x primary	Spill Packet:

Cause
LEAKING HYDRAULIC LINE ON A TRUCK

Cause Type: Hydraulic Line Break

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Hydraulic Oil		10.0 Gal	10.0 Gal	LIQUID		

Environmental Impacts / Damages			
Environmental Impacts: SOIL	Resource Damages: No	Injuries: No	Evacuation: No

Cleanup Actions	
Method	Description
Absorbent (oil dry, sand, sawdust)	
Excavation	EXCAVATED THE CONTAMINATED GRAVEL

Cleanup Action Comments
OSHKOSH CORP CREW CLEANED UP THE SPILLED HYDRAULIC OIL BY USING ABSORBENTS AND EXCAVATING THE CONTAMINATED GRAVEL.

Contractors Hired	
Name	Description

Waste Destinations	
Location	Description
VEOLIA GLACIER RIDGE LANDFILL	CONTAMINATED SOIL AND ABSORBENTS

Agencies Notified / On Scene		
Agency	Notified	On Scene

State of Wisconsin - Department of Natural Resources
 Substance Release Notification Report (SERTS)
 Report created on 10/21/2010

SPILL ID# 20100922NE71-1 BRRTS# 04-71-556207

DNR		X		
Additional Comments				
10-12-10, DNR RECEIVED THE CLEAN UP SUMMARY REPORT FROM OSHKOSH CORP - SUE MURAWSKI. THE SPILL WAS PROPERLY CLEANED UP, NO FURTHER CLEAN UP NEEDED.				
Enforcement Action/Citation				
Enforcement Action/Citation? No				
Case Activity Reports:				
Person Reporting				
Name	Representing / Address	Primary Phone	Secondary Phone	
TOM MOSER	OSHKOSH CORP	(920) 233-9321 x		
Contractors Hired				
Name / Address			Zone Contractor Hired by DNR?	
			No	
Contacts				
Role	Name	Office Phone	Date	Time
Prepared By:	JASON MOELLER	(920) 662-5492 x	09/22/2010	
Person Notified:	JASON MOELLER	(920) 662-5492 x	09/22/2010	
Investigated By:	JASON MOELLER	(920) 662-5492 x	09/22/2010	
Incident Commander:				
Spill Coordinator:	JASON MOELLER, NE Region <i>Jason Moeller</i>	(920) 662-5492 x	10/12/2010	
Electronic Attachments (list)				
Name			Type	

OSHKOSH CORPORATION

ISO 9001 CERTIFIED

2307 OREGON STREET
POST OFFICE BOX 2566
OSHKOSH WISCONSIN 54903-2566
920-235-9151



Certified Mail, Return Receipt Requested

October 11, 2010

Mr. Jason Moeller
Wisconsin Department of Natural Resources
Northeast Regional Office
2984 Shawano Ave., P.O. Box 10448
Green Bay, WI 54307-0448

Subject: Hydraulic Oil Release, September 22, 2010

Dear Mr. Moeller,

On September 22, 2010 at approximately 8:40 am, Oshkosh Corporation reported a release of hydraulic oil to you by telephone. As reported, approximately 10 gallons of hydraulic oil was released on a hard packed clay and gravel portion of the Oshkosh South Plant yard located at 333 West 29th, Oshkosh WI, 54903. The spill did not leave the boundaries of the plant site and was completely contained within a small area approximately 5 feet wide by 10 feet long.

The plant's spill response procedures were initiated immediately upon discovery of the spill. Free liquid was recovered using absorbent materials and the impacted clay/gravel was excavated until no visual or olfactory evidence of oil remained. The area was over excavated (approximately 7 feet by 14 feet by 1 foot deep) and the impacted soils and used absorbents were disposed of at the Veolia Glacier Ridge Landfill Facility.

Oshkosh Corporation is respectfully requesting full closure of this spill incident. If you have any questions or concerns, please contact Don Draxler at (920) 233-9592.

Sincerely,

A handwritten signature in blue ink that reads "Sue Murawski". The signature is fluid and cursive.

Sue Murawski, P.E.
Senior Environmental Engineer