

**From:** [Karl Beaster](#)  
**To:** [Sager, John E - DNR](#)  
**Subject:** Enbridge Terminal - Line 61 trap to Vac Truck release  
**Date:** Wednesday, August 21, 2013 9:58:19 AM  
**Attachments:** [Figure1 Line61 Trap Site Location 8x11.pdf](#)  
[Figure2 Line61 Trap Site Layout 8x11.pdf](#)

---

John – as promised, attached are the figures with GPS coords showing the location of the 10 gallon release of crude oil from an Enbridge vacuum/tanker truck while performing maintenance activities on the Line 61 trap.

The PLM was loading a tanker truck by Line 61 and the tanker overflowed. Barr was at the terminal at the time and investigated and reported that it was an immediate clean up. No samples were taken since it was cleaned up within minutes. The ½ yard of impacted soil/gravel was taken to the SMA pending disposal.

Let me know if you have any additional questions.

Thanks,

Karl

**Karl F. Beaster, PG**

Environmental Analyst II, LP Environment

**ENBRIDGE**

TEL: 715-398-4754 | CELL: 715-718-1040

1320 Grand Ave, Superior, WI 54880

[www.enbridgeUS.com](http://www.enbridgeUS.com)

Integrity. Safety. Respect.

---

\*\*\*\*\* IMPORTANT NOTICE\*\*\*\*\*

Unless otherwise indicated or obvious from the nature of the transmittal, the information contained in this email message is CONFIDENTIAL information intended for the use of the individual or entity named herein. If the reader of this message is not the intended recipient, or the employee or agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify the sender using the above contact information or by return email and delete this message and any copies from your computer system. Thank you.