### State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 01/06/2014

Incident Date & Time: 09/13/2013 13:00	Reported Date & Time: 09/16/2013 12:27	BRRTS No: 04-71-561399	Spill ID: 20130916NE71-2
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent?	ERP Transferred?	Incident Closed?
	No	No	Yes: 01/02/2014

Region:	County:		Loca Municipa	4				
NE NE	Winnebago		OSHKO	SH, CITY	OF			
Facility/Property N OSHKOSH CORI 333 W 29TH AVE		ss:		Descript BEHIND	ion: ) THE BUILDIN	G AT THAT A	ADDRESS	(R11 PAD)
Facility Type:	Industrial Facility (For	undry/Factory/Platir	ng/Manufa	cturing)	•			
Lat/Long:		PLSS:	49			<b>WTM</b> : X 636583	3 Y 39123	4
Weather Condition	ns: Sunny, Windy							1
		R	esponsib	le Partie	es 💮 💮			
Name/Address (1): OSHKOSH CORI 2307 OREGON S 2566 OSHKOSH, WI 5 (920) 233-9582 x	PORATION STREET, PO BOX 4903-9151	Contact: SUE MURAWSK ENVIRONMENT (920) 233-9582 x	AL MANA primary		Other Contac	t:	Spill Pac	ket:
			Cat	ise				
Cause Type: Over	rfill (storage tank, verl	nicle or equipment)					7. J. B.	*3- ADD
		学家 ( ) "整"	Subst	AND DESCRIPTION OF THE PARTY OF	<b>Mark as Part</b>			
	me	Other / Comments		Released	Amt Recovered	Туре	Color	Odor
Diesel			Gal	100.0	99.0 Gal	LIQUID		
		Environ	mental Im	pacts / l	Damages 💮			
Environmental Imp OTHER IMPACT PAD	pacts: : HARD PACKED GR	AVEL AND CLAY	Resource No			Injuries: No		Evacuation: No
	Made at		Cleanup	Actions			ALL SOLVE	
Absorbent (oil dry	Method		_	***************************************		Description	1	
Excavation	, sailu, sawuusi)		SAN	/F DAY	(20'X15'X2' DEI	=P)		
		Clea	nup Actio					
			Contracto					
	Name		Commercia			Description		out on Anna Maria
WASTE MANAG								

668125-12-60

### State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 01/06/2014

	With the second	aste Destinations					
	Location		Description		The second second		
WASTE MANAGEMENT		Berlin Landfill					
A CONTRACTOR OF STREET		es Notified / On Scene					
DMD	Agency		Notified	3.5	On Scene		
DNR	A 1	ditional Comments	X			1110	
Enforcement Action/Citation	The state of the s	ement Action/Citation					
Case Activity Reports:							
Case Activity Reports:	Pi	erson Reporting					
Name	Representing / Addres	ss Primai	ry Phone	Se	econdary Phone		
LEAST WAS	Representing / Address OSHKOSH DEFENSE	(920) 233-958		Se	econdary Phone		
Name	Representing / Address OSHKOSH DEFENSE	ss Primar (920) 233-958 ontractors Hired			econdary Phone ne Contractor Hire DNR?	ed by	
Name	Representing / Addres OSHKOSH DEFENSE	ss Primar (920) 233-958 ontractors Hired			ne Contractor Hire	ed by	
Name SUE MURAWSKI	Representing / Address OSHKOSH DEFENSE Contact Name / Address	ss Primar (920) 233-958 ontractors Hired s	2 x	Zor	ne Contractor Hire DNR?		
Name SUE MURAWSKI Role	Representing / Address OSHKOSH DEFENSE Contact Name / Address	ss Primar (920) 233-958 ontractors Hired s	2 x	No No	ne Contractor Hire DNR?	d by	
Name SUE MURAWSKI  Role  Prepared By:	Representing / Address OSHKOSH DEFENSE  Name / Address  Name / Address	ss Primar (920) 233-958 ontractors Hired s	2 x	No No	Date 09/16/2013		
Name SUE MURAWSKI  Role  Prepared By: Person Notified:	Representing / Address OSHKOSH DEFENSE C Name / Address No. DAKOTA BERG TED AMMAN O/M	ss Primar (920) 233-958 ontractors Hired s	Office Ph (608) 267-0	No none	Date 09/16/2013 09/16/2013		
Name SUE MURAWSKI  Role  Prepared By: Person Notified: Investigated By:	Representing / Address OSHKOSH DEFENSE  Name / Address  Name / Address	ss Primar (920) 233-958 ontractors Hired s	2 x	No none	Date 09/16/2013		
Name SUE MURAWSKI  Role  Prepared By: Person Notified:	Representing / Address OSHKOSH DEFENSE C Name / Address No. DAKOTA BERG TED AMMAN O/M	ss Primai (920) 233-958 ontractors Hired s  Contacts ame	Office Ph (608) 267-0	No N	Date 09/16/2013 09/16/2013		

Name

Туре



## **Oshkosh Corporation**






#### Legend

- Open Site (ongoing cleanup)
- Open Site Boundary
- Closed Site (completed cleanup)
- Closed Site Boundary
- Airport

2010 Air Photos (WROC)

- Cities
- Villages



DISCLAIMER: The information shown on these maps has been obtained from various sources, and are of varying age, reliability and resolution. These maps are not intended to be used for navigation, nor are these maps an authoritative source of information about legal land ownership or public access. No warranty, expressed or implied, is made aregarding accuracy, applicability for a particular use, completemenss, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: http://dnr.wi.gov/org/legal/

Note: Not all sites are mapped.

#### Notes

Red Dot: Spill Location

WTM: 636583, 391234

#### OSHKOSH DEFENSE A DIVISION OF OSHKOSH CORPORATION

ISO 9001 CERTIFIED

2307 OREGON STREET
POST OFFICE BOX 2566
OSHKOSH WISCONSIN 54903-2566
920-235-9151

R + R - OSH RECEIVED

NOV 0 8 2013

Certified Mail, Return Receipt Requested



November 6, 2013

Ms. Beth Erdman Wisconsin Department of Natural Resources 625 East County Road Y, Suite 700 Oshkosh, Wisconsin 54901-9731

Subject: Diesel Fuel Release, September 13, 2013

South Plant R11 Pad

333 West 29<sup>th</sup> Ave, Oshkosh, Wisconsin

Dear Ms. Erdman,

On September 13, 2013, Oshkosh Corporation had a release of diesel fuel. As reported, approximately 100 gallons of diesel fuel was released on a hard packed gravel and clay portion of the Oshkosh South Plant yard located at 333 West 29<sup>th</sup> Ave., Oshkosh WI, 54903. The spill did not leave the boundaries of the property and was completely contained.

The plant's spill response procedures were initiated immediately upon discovery of the release. Free liquid was recovered using absorbent materials and the impacted gravel was excavated until no visual or olfactory evidence of fuel remained. The area was over excavated the same day (approximately 20 feet by 15 feet by 2 feet deep). The impacted gravel was contained in a roll off container and disposed of at the Waste Management landfill in Berlin, Wisconsin. Used absorbent pads were collected in a drum and sent off site for recycling. Clean gravel was brought to fill in the depression.

Oshkosh Corporation is respectfully requesting full closure of this spill incident. If you have any questions or concerns, please contact Sue Murawski at (920) 233-9582.

Sincerely,

Sue Murawski, P.E.

Senior Environmental Manager Oshkosh Corporation – Defense

Encl.

To see all the details that are visible on the screen, use the "Print" link next to the map.

# Google

