Letter of Transmittal

Submitted to:		
Grant Neitzel WDNR - Southeast Region I	RR Program	
1701 N. 4Th Street SuperiorWI5 4880		
Date: 6/11/2020	Attached	
Job: Pizza Place Restaurant	• Under Separate Cover	

Remarks:

Attached are the well abandonment forms for the above site as requested in your email correspondence dated 5/27/20. The wells have been properly abandoned and no investigative waste remains on-site. Attached are well abandonment forms documenting that the work was completed. Following your review of this information and the closure fee's have been paid please forward the "Final Closure" letter to our client and copy METCO.

If you have any questions please call or email.

Signed: Jason Powell

cc: Douglas Potvin c/o Janet Diercks - Client

METCO 709 Gillette St., Ste 3 La Crosse, WI 54603-2382 (608)781-8879 fax (608)781-8893

709 Gillette St., Ste #3

State

WI

ZIP Code

54603-

City

La Crosse

Well / Drillhole / Borehole Filling & Sealing

Form 3300-005 (R 4/08)

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to: X Remediation/Redevelopment Watershed/Wastewater Drinking Water Verification Only of Fill and Seal Waste Management Other: Facility / Owner Information 1. Well Location Information WI Unique Well # of County Hicap # acility Name Removed Well Pizza Place Restaurant VP205 **BARRON** acility ID (FID or PWS) Lattitude / Longitude (Degrees and Minutes) Method Code (see instructions) None 23.91 icense/Permit/Monitoring # 92 8.75 Original Well Owner 1/4/1/4 Section Range SE Cownship SW E **Douglas Potvin** 14 or Gov't Lot # 30 34 W Present Well Owner Well Street Address Douglas Potvin 225 USH 8 & 63 Mailing Address of Present Owner Well City, Village or Town Well ZIP Code 611 E. Bracklin Street Turtle Lake 54889-City of Present Owner State ZIP Code Subdivision Name ot # 54868-WI Rice Lake I. Pump, Liner, Screen, Casing & Sealing Material WI Unique Well # of Replacement Well Reason For Removal From Service Yes □ No Pump and piping removed? Sampling Complete Lyes No Liner(s) removed? 3. Well / Drillhole / Borehole Information □_{Yes} [x]_{No} Screen removed? Original Construction Date (mm/dd/yyyy) [X] Monitoring Well $[x]_{Yes} \square_{No}$ 5/30/2017 Casing left in place? Water Well [X]Yes | No If a Well Construction Report is available, Was casing cut off below surface? Borehole / Drillhole please attach. [X]_{Yes} \square_{No} Did sealing material rise to surface? Construction Type: Yes [X]No Did material settle after 24 hours? X Drilled Dug If yes, was hole retopped? Driven (Sandpoint) No If bentonite chips were used, were they hydrated with water from a known safe source? Other (specify): Required Method of Placing Sealing Material Formation Type: Conductor Pipe-Pumped Conductor Pipe-Gravity X Unconsolidated Formation Bedrock Screened & Poured [X] Other (Explain): Gravity Total Well Depth From Ground Surface (ft.) Casing Diameter (in.) (Bentonite Chips) 2 Sealing Materials Lower Drillhole Diameter (in.) Clay-Sand Slurry (11 lb./gal. wt.) Casing Depth (ft.) Neat Cement Grout 43 Sand-Cement (Concrete) Grout Bentonite-Sand Slurry * * Bentonite Chips Concrete $[x]_{Yes}$ \square_{N_0} Unknown Was well annular space grouted? or Monitoring Wells and Monitoring Well Boreholes Only: Depth to Water (feet) If yes, to what depth (feet)? [X] Bentonite Chips Bentonite - Cement Grout 49.5 Granular Bentonite Bentonite - Sand Slurry 5. Material Used To Fill Well / Drillhole From (ft) To (ft.) lbs Surface Bentonite Chips 58 92 6. Comments Monitoring Well MW-1 7. Supervision of Work **DNR Use Only** Name of Person or Firm Doing Filling & Sealing Date of Filling & Sealing (mm/dd/yyyy) Date Received Noted By License # 6/11/2020 **METCO** Street or Route Telephone Number

608) 781-8879

Signature of Person Doing Work

Date Signed

6/11/2020

Street or Route

La Crosse

City

709 Gillette St., Ste #3

State

WI

ZIP Code

54603-

Well / Drillhole / Borehole Filling & Sealing

Form 3300-005 (R 4/08) Page 1 of 2 Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis, Stats., and ch. NR 141, Wis, Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to: X Remediation/Redevelopment Drinking Water Watershed/Wastewater Verification Only of Fill and Seal Waste Management Other: 1. Well Location Information Facility / Owner Information WI Unique Well # of County Hicap # acility Name Removed Well Pizza Place Restaurant VP206 **BARRON** acility ID (FID or PWS) Lattitude / Longitude (Degrees and Minutes) Method Code (see instructions) None 23.91 icense/Permit/Monitoring # 92 8.75 Original Well Owner 1/4/1/4 SE SW ection ownship Range 1E **Douglas Potvin** or Gov't Lot # 30 34 14 N x w Present Well Owner Well Street Address **Douglas Potvin** 225 USH 8 & 63 Mailing Address of Present Owner Well City, Village or Town Well ZIP Code 611 E. Bracklin Street Turtle Lake 54889-ZIP Code City of Present Owner State Subdivision Name ot # WI 54868-Rice Lake 4. Pump, Liner, Screen, Casing & Sealing Material Reason For Removal From Service WI Unique Well # of Replacement Well Pump and piping removed? Sampling Complete Yes No X N/A 3. Well / Drillhole / Borehole Information Liner(s) removed? $\square_{\text{Yes}} [x]_{\text{No}}$ Original Construction Date (mm/dd/yyyy) Screen removed? X Monitoring Well [x]_{Yes} \square_{No} 5/31/2017 Casing left in place? Water Well [X]Yes No If a Well Construction Report is available. Was casing cut off below surface? Borehole / Drillhole please attach. [X]_{Yes} \square_{No} Did sealing material rise to surface? Construction Type: $\square_{\mathsf{Yes}} [\mathbf{x}]_{\mathsf{No}}$ UN/A Did material settle after 24 hours? ∏ Dug X Drilled Driven (Sandpoint) □Yes □No If yes, was hole retopped? ∐N/A If bentonite chips were used, were they hydrated with water from a known safe source? Other (specify): [x]_{Yes} Required Method of Placing Sealing Material Formation Type: Conductor Pipe-Gravity Conductor Pipe-Pumped [X] Unconsolidated Formation Bedrock Screened & Poured (Bentonite Chips) X Other (Explain): Gravity Total Well Depth From Ground Surface (ft.) Casing Diameter (in.) ealing Materials Lower Drillhole Diameter (in.) Clay-Sand Slurry (11 lb./gal. wt.) Casing Depth (ft.) **Neat Cement Grout** 43 Bentonite-Sand Slurry " " Sand-Cement (Concrete) Grout Bentonite Chips Concrete $[x]_{Yes}$ □ No Unknown Was well annular space grouted? or Monitoring Wells and Monitoring Well Boreholes Only: If yes, to what depth (feet)? Depth to Water (feet) [X] Bentonite Chips Bentonite - Cement Grout 49. 75 39 Granular Bentonite Bentonite - Sand Slurry 5. Material Used To Fill Well / Drillhole From (ft.) To (ft.) lbs Bentonite Chips Surface 92 58 6. Comments Monitoring Well MW-2 7. Supervision of Work **DNR Use Only** Name of Person or Firm Doing Filling & Sealing Date of Filling & Sealing (mm/dd/yyyy) Date Received Noted By License # **METCO** 6/11/2020

Telephone Number

608) 781-8879

Signature of Person Doing Work

Comments

Date Signed

6/11/2020

City

La Crosse

State

WI

ZIP Code

54603-

Signature of Person Doing Work

Date Signed

6/11/2020

Well / Drillhole / Borehole Filling & Sealing

Form 3300-005 (R 4/08)

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to: X Remediation/Redevelopment Drinking Water Watershed/Wastewater Verification Only of Fill and Seal Waste Management Other: 1. Well Location Information Facility / Owner Information County WI Unique Well # of Hicap # Facility Name Removed Well Pizza Place Restaurant **BARRON** VP207 acility ID (FID or PWS) Lattitude / Longitude (Degrees and Minutes) Method Code (see instructions) None 23.91 icense/Permit/Monitoring # 92 8.75 Original Well Owner 1/4/1/4 SE SW Section ownship Range E **Douglas Potvin** or Gov't Lot # 30 34 14 x]w Present Well Owner Well Street Address **Douglas Potvin** 225 USH 8 & 63 Mailing Address of Present Owner Well City, Village or Town Well ZIP Code 611 E. Bracklin Street Turtle Lake 54889-City of Present Owner State ZIP Code Subdivision Name ot# Rice Lake WI 54868-Pump, Liner, Screen, Casing & Sealing Material Wi Unique Well # of Replacement Well Reason For Removal From Service Yes UN₀ Pump and piping removed? Sampling Complete $\square_{\text{Yes}} \square_{\text{No}} [x]_{\text{N/A}}$ 3. Well / Drillhole / Borehole Information Liner(s) removed? $\square_{\text{Yes}} [x]_{\text{No}}$ Original Construction Date (mm/dd/yyyy) Screen removed? [X] Monitoring Well $[x]_{Yes} \square_{No}$ 5/30/2017 Casing left in place? Water Well [x]_{Yes} \square_{No} If a Well Construction Report is available, Was casing cut off below surface? Borehole / Drillhole please attach. X Yes No Did sealing material rise to surface? Construction Type: □_{Yes} [x]_{No} Did material settle after 24 hours? X Drilled Driven (Sandpoint) Dug □_{Yes} □_{No} If yes, was hole retopped? If bentonite chips were used, were they hydrated with water from a known safe source? Other (specify): Required Method of Placing Sealing Material Formation Type: Conductor Pipe-Gravity Conductor Pipe-Pumped [X] Unconsolidated Formation Bedrock Screened & Poured X Other (Explain): Gravity Total Well Depth From Ground Surface (ft.) Casing Dlameter (in.) (Bentonite Chips) Sealing Materials Lower Drillhole Diameter (in.) Casing Depth (ft.) Neat Cement Grout Clay-Sand Slurry (11 lb./gal. wt.) 43 Sand-Cement (Concrete) Grout Bentonite-Sand Slurry " " Concrete **Bentonite Chips** $[x]_{Yes}$ No Unknown Was well annular space grouted? or Monitoring Wells and Monitoring Well Boreholes Only: If yes, to what depth (feet)? Depth to Water (feet) [X] Bentonite Chips Bentonite - Cement Grout 39 49.39 Granular Bentonile Bentonite - Sand Slurry 5. Material Used To Fill Well / Drillhole From (ft.) To (ft.) lbs Bentonite Chips Surface 6. Comments Monitoring Well MW-3 7. Supervision of Work **DNR Use Only** Name of Person or Firm Doing Filling & Sealing License # Date of Filling & Sealing (mm/dd/yyyy) Date Received Noted By **METCO** 6/11/2020 Street or Route Telephone Number Comments 709 Gillette St., Ste #3 608) 781-8879

Well / Drillhole / Borehole Filling & Sealing Form 3300-005 (R 4/08) Page 1 o

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to:

					rinking !	Water anageme	., [Watershed/Wastewater			X Remediation/Redevelopment		
1. Well Locati	on Infor	mation	Tapa (azi azi	WHENK	200101100110		anayeme:	The second second	Other: ity / Owner In	o all all all the sale.	angune 90		
County	OH MINOR	PARKETTA 631	ue Well #		Hicap #	NE SEE	NAME OF TAXABLE PARTY.	Facility N	AND AND DESCRIPTION OF THE PARTY OF THE PART	normation			
Removed Well					domity 14		lace Restaurant						
BARRON		<u> </u>						Facility ID	(FID or PWS)				
Lattitude / Longitude (Degrees and Minutes) Method Code (see instructions)) '	None						
<u>45</u> _ • <u>2</u>	23.91		'N	1				License/F	ermit/Monitorin	g#			
92 - 8	3.75		'W	·l									
7/17/ SE	14 S	XV	Section	Tow	nship	Range	ЭΠΕ	Original V	Vell Owner				
or Gov't Lot #			30		4	4.4	x w			ouglas Potvin			
Well Street Addr	ess					1	A VV	Present V	Vell Owner				
225 USH 8 & 6										Douglas Potvin			
Well City, Village					Well	I ZIP Co	de	-Mailing A	ddress of Prese		1.15 C4	4	
Turtle Lake					54	4889-		City of De	esent Owner	011 E. Br	State	ZIP Code	
Subdivision Nam	ne				Lot :	#		City of Pr		. Laka	WI	54868-	
								4 6		e Lake			
Reason For Ren	noval Fro	m Servic	e WI Uni	que Wel	# of R	eplacem	ent Well	4. Pum	, Liner, Scre	en, Casing & Se			
Sampling Complete						-	Pump and piping removed?				Yes No XNA		
3. Well / Drillh	role / Bo	rehole	Informati	lon	Wig ir		Nisse &	Liner(s) removed?					
Original Cons				struction Date (mm/dd/yyyy)				Screen removed?					
X Monitoring Well		6/2/2017				Casing left in place? [X]Yes No No							
			uction Report is available,			Was casing cut off below surface?							
Borehole /			please at	acn.				Did se	Did sealing material rise to surface?				
Construction Typ								Did ma	aterial settle afte	er 24 hours?		Yes X No UN/A	
X Drilled ::	_	Driven (S	Sandpoint)		L Di	18			res, was hole re		L. Bratanhau	Yes UNo UN/A	
Other (spe	cify):							with wa	ater from a knov	used, were they h vn safe source?	ydrated [x	Yes Ono On/A	
Formation Type:	*							Required	Method of Place	ing Sealing Materia	al		
[X] Unconsolid	lated Forr	nation	ſ	Bedra	ock					avity 📗 Į Conduct			
Total Well Depth			rface (ft.)	Casing	Diamet	er (in.)		☐ ☐ Scri	eened & Poured ntonite Chips)	[X] Other (E	xplain); <u>Gr</u>	avity	
		58					2	Sealing N					
Lower Drillhole Diameter (in.) Casing Depth (ft.)				(ft.)	43		at Cement Grout	ı	Clay-Sai	nd Slurry (11 lb./gal. wt.)			
		8				4	13	_ Sar	nd-Cement (Con	crete) Grout	Bentonit	e-Sand Slurry " "	
Was well annula	r snace d	routed?	Γx	Yes	□No	П	Unknown		ncrete		Bentonit	(*/	
If yes, to what de				h to Wat				For Monit	_	Monitoring Well B		•	
ii yes, to what de	HAMILIAN AND CONTRA		Pep	ii to vvai	er (reer		100		ntonite Chips		ntonile - Cen		
	J	39	1.00 × 6.50 × 1.	=4=12+	2774	49.	145	Gra	nular Bentonite	LJ Bei	ntonite - San	d Slurry	
5. Material Use	d To Fill	Well / D	rillhole		History			From (f	t) To (ft.)	lbs			
Bentonite Chi	ips							Surfac	e 58	92			
			- 19										
6. Comments				1 24	THE S	BEE	Man L			#15 17 17	(A)(A)		
Monitoring V	Well MW-	4											
7. Supervision	n of Wor	rk	13.0	-				4-6-2			DNR Use	e Only	
Name of Person	SECTION SECTION		ing & Sea	ling Lie	ense #		Date of F	illing & Sea	aling (mm/dd/yy	yy) Date Receive		oted By	
METCO		10.5001	my Santi					6/11/20		The same of the same			
Street or Route							Ti Ti	elephone N		Comments			
	709 Gil	llette St.,	Ste #3					(608)78		201 10 11 11 11 11 11 11 11 11 11 11 11 1			
City				State	ZIF	Code		Signature	of Person Doi	ng Work	D	ate Signed	
La Cros	sse	(6		WI		54603-		1	cant.	grenet		6/11/2020	

Street or Route

La Crosse

City

709 Gillette St., Ste #3

State

WI

ZIP Code

54603-

Well / Drillhole / Borehole Filling & Sealing

Form 3300-005 (R 4/08) Page 1 of 2 Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to: X Remediation/Redevelopment Drinking Water Watershed/Wastewater Verification Only of Fill and Seal Waste Management Other: 1. Well Location Information Facility / Owner Information County WI Unique Well # of licap # acility Name Removed Well Pizza Place Restaurant VP282 BARRON acility ID (FID or PWS) Lattitude / Longitude (Degrees and Minutes) Method Code (see instructions) None 23.91 ¹ N icense/Permit/Monitoring # 92 8.75 Original Well Owner 1/4/1/4 SE Section ownship Range E **Douglas Potvin** or Gov't Lot # 30 34 14 W resent Well Owner Well Street Address **Douglas Potvin** 225 USH 8 & 63 Mailing Address of Present Owner Well City, Village or Town Well ZIP Code 611 E. Bracklin Street Turtle Lake 54889-City of Present Owner State ZIP Code Subdivision Name ot# 54868-Rice Lake 1. Pump, Liner, Screen, Casing & Sealing Material Reason For Removal From Service WI Unique Well # of Replacement Well Pump and piping removed? ∐No. Sampling Complete Yes No 3. Well / Drillhole / Borehole Information Liner(s) removed? Yes [X]No Screen removed? Original Construction Date (mm/dd/yyyy) [X] Monitoring Well [X]_{Yes} \square_{No} 5/30/2018 Casing left in place? Water Well [X]_{Yes} L No If a Well Construction Report is available, Was casing cut off below surface? Borehole / Drillhole please attach. X Yes No Did sealing material rise to surface? Construction Type: Yes [X]No Did material settle after 24 hours? X Drilled Driven (Sandpoint) Dua □_{Yes} □_{No} If yes, was hole retopped? If bentonite chips were used, were they hydrated with water from a known safe source? Other (specify): $[x]_{Yes}$ Required Method of Placing Sealing Material Formation Type: Conductor Pipe-Gravity Conductor Pipe-Pumped X Unconsolidated Formation Bedrock Screened & Poured X Other (Explain): _Gravity Total Well Depth From Ground Surface (ft.) Casing Dlameter (in.) (Bentonite Chips) 2 Sealing Materials Lower Drillhole Diameter (in.) Clay-Sand Slurry (11 lb./gal. wt.) Casing Depth (ft.) **Neat Cement Grout** 75 Sand-Cement (Concrete) Grout Bentonite-Sand Slurry " " Bentonite Chips Concrete $[x]_{Yes}$ Unknown ☐ No Was well annular space grouted? or Monitoring Wells and Monitoring Well Boreholes Only: If yes, to what depth (feet)? Depth to Water (feet) X Bentonite Chips Bentonite - Cement Grout 65 49.66 Granular Bentonite Bentonite - Sand Slurry 5. Material Used To Fill Well / Drillhole From (ft.) To (ft.) lbs Surface Bentonite Chips 80 125 6. Comments Monitoring Well PZ-2 7. Supervision of Work **DNR Use Only** Date of Filling & Sealing (mm/dd/yyyy) Name of Person or Firm Doing Filling & Sealing Date Received Noted By **METCO** 6/11/2020

Telephone Number

(608) 781-8879

Signature of Person-Doing Work

Comments

Date Signed

6/11/2020

Well / Drillhole / Borehole Filling & Sealing Form 3300-005 (R 4/08) Page 1 or

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return form to the appropriate DNR office and bureau. See instructions on reverse for more information.

Route to:

Verification Only of	f Fill a	and Seal		=	rinking Water /aste Managem	ent	=	Watershed/Wa	astewater	[X] Remed	diation/Redevelopment	
1. Well Location Inform	ation	SEPHENSIS .		74.2 E	date is the steel	2.	Facility	/ Owner Inf	ormation			
* F	VI Uniq Remove			icap#		THE PARTY OF	ility Nam	0	ace Restaurant	III BEI IS NO E-IN COLU	Partial Dictaores of English	
BARRON .		VP2				Fac	ility ID (F	ID or PWS)	ace Aestaurant			
Lattitude / Longitude (Degre	es and	Minutes) V	lethod	Code	see instruction	is)	anty to (1D 01 1 110)	None			
45 23.91		'N				Lice	nse/Peri	nit/Monitoring				
92 - 8.75		·w				_						
14/14 SE 14 SW		Section	Town	ship	Range -	Orig	ginal Well					
or Gov't Lot #		30	34	N	1 4 4 5 5 1				uglas Potvin			
Well Street Address						Pre	sent Wel	-				
225 USH 8 & 63									ouglas Potvin			
Well City, Village or Town				Well	ZIP Code	Mai	ling Addr	ess of Preser				
Turtle Lake					889-	0)1	15		611 E. B	racklin Stree		
Subdivision Name				Lot #	1	—City	of Prese	ent Owner		State	ZIP Code	
						2000	estaturose.	Rice		WI	54868-	
Reason For Removal From	Service	e WI Uniqu	e Well a	of Re	placement We	4.	Pump, L	Iner, Scree	n, Casing & S	Sealing Mat	erial	
Sampling Complete					F	Pump and piping removed?						
3. Well / Drillhole / Bore	hole I	nformation	L CO			L	Liner(s) removed?					
# 3	Ic	Original Cons	struction	n Date	(mm/dd/yyyy)	– 8	Screen removed?					
X Monitoring Well . 5/31/2							Casing left in place? [x] _{Yes} \square _{No} \square _{N/A}					
Water Well		If a Well Con	structio	n Rep	ort is available.		Was casing cut off below surface? [x] _{Yes} □ No □ N/A					
Borehole / Drilihole		please attacl					Did sealing material rise to surface? [X]Yes \(\subseteq No \subseteq N/A \)					
Construction Type:								ial settle after			Jyes [x]No DN/A	
X Drilled Dr	riven (S	andpoint)	1	Du	Q	Ι,		, was hole ret		2000	Ives DNo DN/A	
Other (specify):					•	h			used, were they n safe source?	hydrated r.		
											Yes No NA	
Formation Type:						Ked	-		g Sealing Mater			
[X] Unconsolidated Forma			Bedroo			_ -		ctor Pipe-Grav led & Poured		ctor Pipe-Pun		
Total Well Depth From Grou		face (ft.) Ca	asing D	lamete		-	Screened & Poured (Bentonite Chips) [X] Other (Explain): Gravity					
	80				2	Sea	ling Mate					
Lower Drillhole Diameter (in.) Casing				Depth (ft.) 75			=	ement Grout		_	nd Slurry (11 lb./gal. wt.)	
					75	_ -	ries .	Cement (Conc	rete) Grout		te-Sand Slurry * *	
Was well annular space gro	uted?	$[\mathbf{x}]_{Y}$	es [\square_{No}	Unknov	ᄱᆝᆫ	□ Concre		nen wat se waarde	L Bentonii		
If yes, to what depth (feet)?		Depth to	. Wate	(feet)					Monitoring Well		-	
65		- span to		(1001)				ite Chips		entonile - Cer		
*THE CAN DESCRIPTION OF THE PERSON OF THE PE	U.S. U.S. KI				50.36		J Granul	ar Bentonite	⊔В	entonite - Sar	d Slurry	
5. Material Used To Fill W	/ell / Dr	rillhole		2017		Fr	om (ft.)	To (ft.)	lbs			
Bentonite Chips			S	urface	80	12:	5					
		5										
						- 1	- 1.00					
6. Comments	Line of							E-12 5/3 1/25				
Monitoring Well PZ-3								W. Stepperson Markette Co.	The second second			
7. Supervision of Work	CARY-F					100	ng syli	THE ROLL OF		DNR Us	e Only	
Name of Person or Firm Do	_	ng & Sealing	Lice	nse#	Dale of	Filling	& Sealing	g (mm/dd/yyy	y) Date Receiv		oted By	
METCO	140	J			J		11/2020			abs. Up and		
Street or Route							one Nun		Comments		ALTHOUGH STEEL	
709 Gillet	tte St., S	Ste #3					781-8					
City			State	ZIP	Code				Work M	Ь	ate Signed	
La Crosse	3		WI		4603-		0	enti,	fourth of		6/11/2020	