

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 02/18/2015**

SPILL ID# 20150121WC42-1 BRRTS# 04-42-563335

Incident Date & Time: 01/21/2015 15:12	Reported Date & Time: 01/21/2015 17:07	BRRTS No: 04-42-563335	Spill ID: 20150121WC42-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 02/18/2015

Location			
Region: WC	County: Monroe	Municipality: FORT MCCOY, UNINCORPORATED	
Facility/Property Name and Street Address: FORT MCCOY LA CROSSE RIVER ALDERWOOD DAM		Description: FORT MCCOY PROPERTY	
Facility Type: Military Installation (Base/Fort/Post)			
Lat/Long:		PLSS:	WTM:
Weather Conditions:			

Responsible Parties			
Name/Address (1): MICHELS CORP P.O. BOX 128, 817 W MAIN ST BROWNSVILLE, WI 53006-0128 (920) 538-3132 x Primary	Contact: JON ZIELIEKE ENV COORDINATOR (920) 539-6497 x primary	Other Contact:	Spill Packet:

Cause
HOSE FAILURE 1 1/2 GALLONS INTO SOIL/ LESS THAN 1/2 GALLON INTO LACROSSE RIVER

Cause Type: Hydraulic Line Break

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Hydraulic Oil		2.0 Gal	0.0 Gal	LIQUID		

Environmental Impacts / Damages			
Environmental Impacts: SOIL SURFACE WATER - Name : LACROSSE RIVER	Resource Damages: No	Injuries: No	Evacuation: No

Cleanup Actions	
Method	Description
Absorbent (oil dry, sand, sawdust)	
Boom	

Cleanup Action Comments
UTILIZED MATERIAL PADS AND BOOMS IN THE RIVER. IN THE SOIL TIMBER MATS. T. KENDZIERSKI RECEIVED A PHONE CALL ON 1/22/15 FROM FT. MCCOY ENVIRONMENTAL SUPERVISOR CRAIG BARTHOLOMEW REGARDING THIS INCIDENT. BATHOLOMEW WILL SEND THEIR USUAL REPORT. TK CALLED ZIELIEKE AT MICHELS ON 2/17/15 AND LEFT A VOICEMAIL FOR A CALL-BACK ON THE REPORT. HOSE ON A VIBRATORY HAMMER INSTALLING SHEET PILING FAILED. HYDRAULIC OIL WAS MOSTLY ON WOODEN WORK MATS BUT SOME ENTERING THE RIVER WERE CAPTURED BY A TURBIDITY BARRIER, OIL WAS RECOVERED WITH ABSORBENTS. SEE THE MICHELS CORP REPORT SUBMITTED BY J. ZIELIEKI ON 2/18/2015 IN THE SPILL FILE

Contractors Hired	
Name	Description

Waste Destinations	
Location	Description
OSI ENVIRONMENTAL	KAUKAUNA, WI

State of Wisconsin - Department of Natural Resources
 Substance Release Notification Report (SERTS)
 Report created on 02/18/2015

SPILL ID# 20150121WC42-1 BRRTS# 04-42-563335

Agencies Notified / On Scene				
Agency	Notified	On Scene		
DNR	X			
Additional Comments				
*** SUBMITTED VIA SERTS WEB FORM REF # 8902... SEE THE MICHELS CORP REPORT SUBMITTED BY J. ZIELIEKI ON 2/18/2015 IN THE SPILL FILE...LAT 44 05' 14.00" N LONG 90 39' 33.00" W				
Enforcement Action/Citation				
Enforcement Action/Citation? No				
Case Activity Reports:				
Person Reporting				
Name	Representing / Address	Primary Phone	Secondary Phone	
JON ZIELIEKE	MICHELS CORP	(920) 539-6497 x		
Contractors Hired				
Name / Address			Zone Contractor Hired by DNR?	
			No	
Contacts				
Role	Name	Office Phone	Date	Time
Prepared By:	LUKAS WIERSEMA	(608) 267-0844 x	01/21/2015	
Person Notified:	JEREMY PLAUTZ-DO		01/21/2015	
Investigated By:	TOM KENDZIERSKI		01/21/2015	
Incident Commander:				
Spill Coordinator:	THOMAS KENDZIERSKI, WC Region	(715) 839-1604 x	02/18/2015	
Electronic Attachments (list)				
Name		Type		

Kendzierski, Thomas J - DNR

From: Jon Zielieke <jzieliek@michels.us>
Sent: Wednesday, February 18, 2015 9:34 AM
To: Kendzierski, Thomas J - DNR
Subject: Michels Corp Spill Report Alderwood
Attachments: Spill Report Jan 21 2015_ Alderwood.pdf

Tom, attached is the spill report for the hydraulic oil release on Jan 21, 2015. If you have any questions, feel free to contact me.

Thank You,

Jon Zielieke | HSE-Environmental Coordinator

MICHELS Corporation

cell: 920.539.6497

jzieliek@michels.us | www.michels.us

PO Box 128 | 817 West Main Street

Brownsville, WI 53006


Lead Safely. Others Will Follow.

THE INFORMATION CONTAINED IN THIS COMMUNICATION MAY BE CONFIDENTIAL, IS INTENDED ONLY FOR THE USE OF RECIPIENT(S) NAMED ABOVE, AND MAY BE LEGALLY PRIVILEGED. IF THE READER OF THIS MESSAGE IS NOT THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY DISSEMINATION, DISTRIBUTION, OR COPYING OF THIS COMMUNICATION, OR ANY OF ITS CONTENTS, IS STRICTLY PROHIBITED.



Spill Report

Project: Alderwood Dam, Fort McCoy, WI



INCIDENT SUMMARY

INCIDENT DATE: January 21, 2015

INCIDENT TIME: 1512 Hours

INCIDENT LOCATION: NW corner of Alderwood Lake
Fort McCoy Military Base, WI
44 05' 14.00" N
90 39' 33.00" W

INCIDENT TYPE: Hydraulic Oil Release

AMOUNT RELEASED: Less than 2 gallons

SOURCE: Hydraulic Hose on piece of equipment

AFFECTED AREA(S): Timber Mats and Lacrosse River

WASTE GENERATED: One 55 gallon drum of Non Hazardous Waste

WDNR SERTS SPILL ID: 20150121WC42-1

INCIDENT NARRATIVE

Michels Corporation (Michels) is working at the Fort McCoy Military Base on a civil construction project. On January 21, 2015, Michels was in the process of installing sheeting in the Alderwood Lake basin. Michels was utilizing a John Deere 470 Excavator with a vibratory hammer to install the steel sheeting. Timber mats had been placed in the lake basin to support the weight of the excavator. At approximately 15:12, a hydraulic line began leaking on the vibratory hammer. The excavator was shut down upon notice of leak.

The hydraulic oil had leaked onto the timber mats. It was estimated that less than two gallons of hydraulic oil had been released from the leaking hose. An estimated 0.5 gallon of hydraulic oil had flowed off the edge of the timber mat and into the Lacrosse River. Turbidity barrier had been placed in the river prior to the civil construction. The turbidity barrier was approximately 100 feet downstream of the hydraulic oil release. The turbidity barrier contained the hydraulic oil that had been released to the waterway.

The onsite crew utilized on site spill kits to begin cleanup of the spill. Absorbent pads were utilized to clean the hydraulic oil off of the timber mats. Absorbent pads and booms were utilized to remove the hydraulic oil from the waterway. All contaminated absorbents were placed into a 55 gallon drum. Absorbent boom was placed downstream of the spill to catch any residual hydraulic oil. Pictures of the release are below.

The one drum of waste was transported to Michels Brownsville Facility for staging. On February 2, 2015, OSI Environmental, Inc. transported the drum (along with other waste) to the OSI Environmental, Inc. facility in Kaukauna, WI for disposal processing. Manifest is following this report.

All information presented in this report has been submitted with good intent and to the best of my knowledge.

REPORT COMPLETED BY: Jon Zielieke – HSE Environmental Coordinator



SIGNATURE: _____ DATE: 2/18/15



Turbidity Barrier downstream of hydraulic oil release



Slight Sheen visible downstream of hydraulic oil release

NON-HAZARDOUS WASTE MANIFEST 1. Generator ID Number **W I D 9 8 8 5 8 1 6 6 6** 2. Page 1 of **1** 3. Emergency Response Phone **(800) 860-8003** 4. Waste Tracking Number **36CB94**

5. Generator's Name and Mailing Address **Michels Corporation**
P.O. Box 128, Brownsville, WI 53006-0128
 Generator's Phone: **(920) 583-1480**
 Generator's Site Address (if different than mailing address)
Michels Corporation
817 W. Main Street
Brownsville, WI 53006

6. Transporter 1 Company Name **OSI Environmental, Inc.** U.S. EPA ID Number **W I R 0 0 0 1 1 7 0 3 6**

7. Transporter 2 Company Name U.S. EPA ID Number

8. Designated Facility Name and Site Address **OSI Environmental, Inc.**
2253 Progress Way, Kaukauna, WI 54130
 Facility's Phone: **(920) 759-0252** U.S. EPA ID Number **W I R 0 0 0 1 1 7 0 3 6**

9. Waste Shipping Name and Description	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	
	No.	Type			
1. Non-Hazardous Solids (Mixed Oil Absorbents), Non-Regulated	010	DM	02000	P	NONE
2. Non-Hazardous Petroleum Grease Non-Regulated	01	DM	0100	P	NONE
3. Non-Hazardous Concrete Curing Compound Non-Regulated	03	DM	01200	P	NONE
4. Non-Hazardous Solids (Mixed Oil Absorbents, Gravel, Dirt), Non-Regulated	03	DM	01500	P	NONE

13. Special Handling Instructions and Additional Information
 1. Non-Haz- Oil Contaminated Absorbents (Pads, Oil Dry Mix)
 2. Non-Haz- Petroleum Grease
 3. Non-Haz- W/B Concrete Cure 4. Non-Haz- Oil Contaminated Absorbents (Pads, Oil Dry, Gravel, D)
OSI Job #: 40-3005 Michels P.O. #: MTO 99885

14. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations.

Generator's/Offlor's Printed/Typed Name **Travis Mahnte** Signature *[Signature]* Month **12** Day **21** Year **15**

15. International Shipments Import to U.S. Export from U.S. Port of entry/exit: Date leaving U.S.:

16. Transporter Acknowledgment of Receipt of Materials
 Transporter Signature (for exports only):
 Transporter 1 Printed/Typed Name **Jon L. Burkert** Signature *[Signature]* Month **02** Day **02** Year **15**

Transporter 2 Printed/Typed Name Signature Month Day Year

17. Discrepancy
 17a. Discrepancy Indication Space Quantity Type Residue Partial Rejection Full Rejection
 Manifest Reference Number: U.S. EPA ID Number

17b. Alternate Facility (or Generator) U.S. EPA ID Number

Facility's Phone:
 17c. Signature of Alternate Facility (or Generator) Month Day Year

18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in Item 17a
 Printed/Typed Name **Jon L. Burkert** Signature *[Signature]* Month **02** Day **02** Year **15**

GENERATOR
INT'L
TRANSPORTER
DESIGNATED FACILITY