


Print Date: 1/27/2023
Printed By: chafidahi, File: G:\211218912\1891000\Environmental Figures\GIS\21891000 Chippewa QMart Figures.aprx

ATTACHMENT B.2.b

RESIDUAL SOIL CONTAMINATION

**FORMER CHIPPEWA QUICK MART
122 EAST BROADWAY
GLIDDEN, ASHLAND COUNTY,
WISCONSIN**



- Site Boundary
- Parcel Boundary
- Former Store Layout
- Former Dispenser Island
- Former Underground Storage Tank
- Former Tank Basin Excavation Area
- Soil Contamination Exceeding Groundwater Pathway RCLs
- Historically Documented Soil Contamination
- Approximate Sanitary Sewer Line
- Approximate Water Line
- Former Piping
- 2008-2009 Glidden Amoco Sampling Locations - Northern Environmental
- 2017 Post UST Removal (TSSA) Sample Locations - MSA Professional Services
- ▲ 2022 Soil Vapor or Sub-Slab Vapor Sample Location - MSA Professional Services
- 2022 Boring Location - MSA Professional Services

APPROXIMATE EXTENT OF HISTORICALLY DOCUMENTED SOIL CONTAMINATION (BRRS #03-02-552129)

ESTIMATED EXTENT OF SOIL CONTAMINATION EXCEEDING GROUNDWATER PATHWAYS RCLs

All data shown in this exhibit is approximate for display purposes only and does not reflect actual survey data.
Data Sources: Ashland County, Esri Community Maps Contributors, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA