Spill Notification for WRR Environmental Services Co., Inc.

EPA ID# WID990829475 FID# 618026530 Spill ID# Unknown

ID 20210312WC18-1 – Paint related material

Per Condition 86 of WRR Environmental Services' current Feasibility and Plan of Operations Report (FPOR), WRR is making the following spill report to the Department's designated Hazardous Waste Inspector assigned to WRR, to the Department's designated Hazardous Waste plan review staff person assigned to WRR and to the Department's designated Spills Coordinator.

This notification, required by Condition 86 of the WRR FPOR and NR 706.05(1), contains the following information to the extent practicable or applicable:

1. Name, address, and telephone number of the person reporting the discharge.

Becky Anderson – Director of Compliance WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

2. Name, address, and telephone number of the discharger, or owner and operator of the UST system and any other potentially responsible persons.

WRR Environmental Services Co Inc. 5200 Ryder Road Eau Claire WI 54701 715-834-9624

3. Date, time, and duration of the discharge.

March 11, 2021 at 8:45 pm. Time to clean up the release was 1.0 hour.

Location of the discharge including street address, county, town, city or village

WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

Town of Washington

- 4. Identity, physical state, and quantity of the material discharged.
  - ~10 gallons of waste paint related material liquid.

The hazardous waste codes associated with this waste is D001.

Spill Notification for WRR Environmental Services Co - Paint container spill 03112021

Two 5 gallon pails fell from a pallet as the material was being transported by forklift to be processed inside the Fuels Building.

5. Physical, chemical, hazardous, and toxicological characteristics of the substance.

The release is paint related material containing pigments and flammable solvents.

6. Cause of the discharge.

The load on the pallet shifted with the forklift went over a bump. The load strap was not being used to secure the load.

7. Immediate actions being taken and the name of the contractor or other person performing the action.

Shovels, brooms, clay absorbent and pads were used to pick up the bulk of the release.

All cleanup activities were conducted by WRR personnel.

8. Source, speed of movement, and destination or probable destination of the discharged hazardous substance.

The release was contained to the black topped area. No material impacted soil or contaminated the WRR stormwater collection area.

Included with this report is a facility map with the release location marked with a red arrow.

9. Actual or potential impacts to human health or the environment, including actual or potential impacts to drinking water supplies.

No drinking water supplies were impacted by the spill.

This waste contained.


10. Weather conditions existing at the scene, including presence of precipitation and wind direction and velocity.

The release occurred outside. The temperature at the time of the spill was 43F with an 8 mph wind. There was no precipitation. Approximately 2.7 pounds of volatile solvents were emitted during the release and clean up activities.

11. Other agencies on—scene during the discharge incident.


Spill Notification for WRR Environmental Services Co - Paint container spill 03112021

No agencies were on-site during the discharge or clean-up.	






## 20210312WC18-1 WRR ENVIRONMENTAL SERVICES





## Legend

- Open Site
- Closed Site
- Continuing Obligations Apply
  - Facility-wide Site



DISCLAIMER: The information shown on these maps has been obtained from various sources and are of varying age, reliability and resolution. These maps are not intended to be used for navigation, nor are these maps an authoritative source of information about legal land ownership or public access. No warranty, expressed or implied, is made aregarding accuracy, applicability for a particular use, completemenss, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: http://dnr.wi.gov/org/legal/

Note: Not all sites are mapped.

## Notes

PAINT EAU CLAIRE EAU CLAIRE CO.