

Memorandum

11156937

Ref. No.:

June 12, 2018

To: David Morrison, United States Environmental Protection Agency

Kristina Miller, United States Environmental Protection Agency
James Mitchell, United States Environmental Protection Agency
Jacob Hassan, United States Environmental Protection Agency
Robert Thiboldeau, Wisconsin Department of Health Services

John Sager, Wisconsin Department of Natural Resources

Pat Schanen, Douglas County
Kathy Ronchi, Douglas County
Dave Longsdorf, Douglas County

From: GHD/dh/179 Tel: 501-224-1926

cc: Dyron Hamlin, MS, PE, CIH; Bradley Free

Subject: Summary of Perimeter Air Monitoring Results: June 11, 2018 – Between 00:00 and 23:59

The purpose of this memorandum is to provide Superior Refining Company LLC (SRC) site management and local, state and federal regulators a summary of GHD's site perimeter air monitoring activities and results at the Husky Superior Refinery conducted from June 11, 2018 between 00:00 and 23:59 Central Daylight Time (CDT). Air monitoring activities were conducted in accordance with the Air Monitoring Plan, as amended, developed in consultation with the United States Environmental Protection Agency, Wisconsin Department of Natural Resources, Wisconsin Department of Health Services, Douglas County Emergency Management Agency, and Douglas County Health and Human Services.

GHD continued to monitor air quality with 15 AreaRAE monitors located at the refinery site perimeter. Monitor maintenance was conducted by GHD following the Site protocols. The AreaRAE monitors were equipped with a photo ionization detector (PID) (10.6 eV lamp) for monitoring volatile organic compounds (VOCs) and electrochemical sensors specific for carbon monoxide (CO), hydrogen sulfide (H_2S), sulfur dioxide (SO_2) and flammability (LEL). GHD monitored meter status and continuous air quality monitoring results via telemetry from the refinery control room. Results were documented through data logging.

H₂S detections were logged above the community action level at one monitor on June 11, 2018. The detections were not sustained above the community action level. Therefore, the detections do not constitute as an exceedance of community action levels.



Perimeter monitoring locations and status with respect to community action levels over the period of June 11, 2018 between 00:00 and 23:59 are presented on Figure 1.

Perimeter air monitoring results for VOCs, H₂S, and SO₂ over this period are presented on Figures 2 through 4, respectively.

The information contained in this memorandum will be considered preliminary until a final Quality Assurance/Quality Control (QA/QC) review of the data is completed. At the completion of the project, all data collected through real-time monitoring will be compiled, summarized, and reported to SRC. Data contained in the final report will go through GHD's final QA/QC process, including review by a GHD Certified Industrial Hygienist (CIH).



Sources: 2015 TIGER/Line Shapefiles, prepared by the U.S. Census Bureau, 2015; U.S. Geological Survey, National Geospatial Technical Operations Center - National Elevation Dataset, 2015; Imagery @ Goo.



Coordinate System: NAD 1983 HARN StatePlane Wisconsin North FIPS 4801 Feet



<u>Legend</u>

Perimeter Monitoring Locations

• COIs Above Community Action Levels

COIs Below Community Action Levels




HUSKY ENERGY – SUPERIOR REFINERY FIRE SUPERIOR, WISCONSIN

11156937-00 Jun 12, 2018

SUMMARY OF PERIMETER ZONE AIR MONITORING RESULTS JUNE 11, 2018 - 00:00 TO 23:59

FIGURE 1



Sources: 2015 TIGER/Line Shapefiles, prepared by the U.S. Census Bureau, 2015; U.S. Geological Survey, National Geospatial Technical Operations Center - National Elevation Dataset, 2015; Imagery @ Google.

0 250 500 750 Feet

Coordinate System: NAD 1983 HARN StatePlane Wisconsin North FIPS 4801 Feet



Legend

Perimeter Monitoring Locations

COIs Above Community Action Levels

COIs Below Community Action Levels




HUSKY ENERGY – SUPERIOR REFINERY FIRE SUPERIOR, WISCONSIN

11156937-00 Jun 12, 2018

PERIMETER ZONE AIR MONITORING RESULTS - VOCS (PPM) JUNE 11, 2018 - 00:00 TO 23:59

FIGURE 2



Sources: 2015 TIGER/Line Shapefiles, prepared by the U.S. Census Bureau, 2015; U.S. Geological Survey, National Geospatial Technical Operations Center - National Elevation Dataset, 2015; Imagery @ Google.

0 250 500 750 Feet

Coordinate System: NAD 1983 HARN StatePlane Wisconsin North FIPS 4801 Feet



<u>Legend</u>

Perimeter Monitoring Locations

COIs Above Community Action Levels


COIs Below Community Action Levels




HUSKY ENERGY – SUPERIOR REFINERY FIRE SUPERIOR, WISCONSIN

11156937-00 Jun 12, 2018

PERIMETER ZONE AIR MONITORING RESULTS - H2S (PPM) JUNE 11, 2018 - 00:00 TO 23:59



Sources: 2015 TIGER/Line Shapefiles, prepared by the U.S. Census Bureau, 2015; U.S. Geological Survey, National Geospatial Technical Operations Center - National Elevation Dataset, 2015; Imagery @ Google.



Coordinate System: NAD 1983 HARN StatePlane Wisconsin North FIPS 4801 Feet



<u>Legend</u>

Perimeter Monitoring Locations

COIs Above Community Action Levels

OOIs Below Community Action Levels



HUSKY ENERGY – SUPERIOR REFINERY FIRE SUPERIOR, WISCONSIN

11156937-00 Jun 12, 2018

PERIMETER ZONE AIR MONITORING RESULTS - SO2 (PPM) JUNE 11, 2018 - 00:00 TO 23:59

FIGURE 4