Spill Notification for WRR Environmental Services Co., Inc.

EPA ID# WID990829475 FID# 618026530 WI SPILL# 13612

ID 20190221WC18-1 - Acetone

Per Condition 86 of WRR Environmental Services' current Feasibility and Plan of Operations Report (FPOR), WRR is making the following spill report to the Department's designated Hazardous Waste Inspector assigned to WRR, to the Department's designated Hazardous Waste plan review staff person assigned to WRR and to the Department's designated Spills Coordinator.

This notification, required by Condition 86 of the WRR FPOR and NR 706.05(1), contains the following information to the extent practicable or applicable:

1. Name, address, and telephone number of the person reporting the discharge.

Becky Anderson – Director of Compliance WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

2. Name, address, and telephone number of the discharger, or owner and operator of the UST system and any other potentially responsible persons.

WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

3. Date, time, and duration of the discharge.

February 21 at 1:45 am. Time to clean up the release was 0.5 hours.

Location of the discharge including street address, county, town, city or village

WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

Town of Washington

- 4. Identity, physical state, and quantity of the material discharged.
 - 5-10 gallons of a flammable acetone product.

5. Physical, chemical, hazardous, and toxicological characteristics of the substance.

The material that spilled is hazardous due to flammability with a flash point of less than 73F.

6. Cause of the discharge.

The release occurred inside the E1 building next to the E1 Thin Film Evaporator. At the beginning of each solvent recycling run, a small flush tank is filled with product. The contents of the flush tank is used at the end of the recycling run to flush out the thin film evaporator. The operator filled the flush tank with product acetone and then forgot to close the valve. With the valve open, the flush tank continued to fill and overfilled product into the area.

7. Immediate actions being taken and the name of the contractor or other person performing the action.

The operator shutdown the thin film that was sending acetone to the flush tank and radioed for assistance. The acetone was cleaned up with clay absorbents.

All clean up activities were conducted by WRR personnel.

8. Source, speed of movement, and destination or probable destination of the discharged hazardous substance.

The spill area was indoors and not affected by precipitation or wind. None of the released material impacted WRR's stormwater collection system or any grassy areas.

9. Actual or potential impacts to human health or the environment, including actual or potential impacts to drinking water supplies.

No drinking water supplies were impacted by the spill. Air emissions from the spill were calculated to be less than 0.05 lbs based on the indoor conditions at the time of the release and cleanup activities.

10. Weather conditions existing at the scene, including presence of precipitation and wind direction and velocity.

Weather conditions did not impact the emissions from the release.


11. Other agencies on—scene during the discharge incident.

No agencies were on-site during the discharge or clean-up.

Spill Notification For WRR Environmental Services Co - El Acetone Release 02212019.Docx



WRR



1:495

0



Legend

- Open Site
 - Closed Site
- Continuing Obligations Apply
- Facility-wide Site

Notes

DISCLAIMER: The information shown on these maps has been obtained from various sources, and are of varying age, reliability and resolution. These maps are not intended to be used for navigation, nor are these maps an authoritative source of information about legal land ownership or public access. No warranty, expressed or implied, is made aregarding accuracy, applicability for a particular use, completemenss, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: http://dnr.wi.gov/org/legal/

Note: Not all sites are mapped.

NAD_1983_HARN_Wisconsin_TM

© Latitude Geographics Group Ltd.

0.0

Note: