Vapor Mitigation System Vacuum Readings Log

707-45.586961

Date:	12-1-21
P-3	
Readings 1 & 2	-1.21-1.~
Acceptable Operating Range:	
EP-2	
Readings 1 & 2	-1.5 /-1.5
Acceptable Operating Range:	
EP- /	
Readings 1 & 2	-1.5 1-1.5
Acceptable Operating Range:	
ss-3	
Readings 1 & 2	0.00-10.000
ss- 2	
Readings 1 & 2	-0.0H1-0.0F
SS- 4	
Readings 1 & 2	-0.633-0.039
SS-	
Readings 1 & 2	
05 1 10055655	able - Dlatform built on top of it-see photo

SS-1 inaccessable - Platform built on top of it see pr



Former Donaldson's Cleaners

1835 Edgewood Drive, Appleton, WI

BRRTS: 02-45-586961

Looking at the location of SSV-1 toward the north wall. SSV-1 is covered by the platform built against the wall.

Former Donaldson's 1835 Edgewood dr Appleton 02-45-586961

## Vapor Mitigation System Inspection Log

vapor winigation system inspected and				
Inspection Date	Inspector Name	Company/Phone #	Inspection Result	
12-1-21	R Brown	Envirofaensio	Inspection Result	
			-	