

Vapor Mitigation System Inspection Log

Inspection Date	Inspector Name	Company/Phone #	Inspection Result
12/20/22	R. Hoverman R. Brown	EnviroForensics 866-888-7911	System appears in good shape and operating as installed. No new floor cracks and seals around EPs are good. SS-1 is still inaccessible due to salom build out.