

Spill ID Number
04-55-043599
Y Y M M D D 0-99

Date of Incident 4-19-89	Day of Week WEDS	Time of Incident 11:15	☒ A.M. ☐ P.M.	Reported By (Name) JAMES DYE	Telephone Number (612) 738-8143
Date Reported 4-19-89	Day of Week WEDS	Time Reported 11:15	☒ A.M. ☐ P.M.	Agency or Firm Reporting JAMES DYE	Reported thru Div. Emergen. Gov't. ☐ Yes ☒ No
Substance Involved GASOLINE		Quantity UNKNOWN	Units	Person or Firm Responsible JAMES DYE	
Substance Involved		Quantity	Units	Contact Name JAMES DYE	Telephone Number (612) 738-8143
Physical Characteristics				Address - Street or Route 2152 FAUCON AVE.	
☐ Solid		☐ Liquid		City, State, Zip Code ST. PAUL, MN 55119	
☐ Semisolid		☐ Gas		Odor GASOLINE	
Cause of Incident Look under pump island - NOT LEAK				Action Taken By Spiller	
Exact Location Description (intersection, mileage, etc.) NE CORNER OF JCT WSH 40 & CTH A				☐ No Action Taken ☐ No Notification ☐ Investigate	
County Location Rusk		1/4, 1/4, Section, Town, Range SE. SW. 34. T 36 N, R 02 W		☐ Containment; Type	
DNR Dist NW	DNR Area PKF	Groundwaters Affected ☐ Yes ☐ No ☒ Potential		☒ Cleanup; Method REMOVE CONTAMINATED SOIL	
Surface Waters Affected ☐ Yes ☐ No ☒ Potential		Name of Surface Water CHIPPWA R.		☐ Amount Recovered	
Date District Area Notified 4-19-89	Day of Week WEDS	Time District Notified 11:47		☒ Monitor	
District Person Notified MIKE RINDLERSCH		Telephone Number (715) 762-3204		☐ Contractor Hired; Name TWIN CITY TESTING	
Date Investigated 4-19-89	Day of Week WEDS	Time Investigated 11:15		☐ Other Action	
Person Investigating JOHN POHLMAN		Telephone Number (715) 532-3911		Spill Location	
Action Taken By DNR				☐ Industrial Facility/Paper Mill/Chem. Co.	
☐ No Action Taken ☒ Investigation ☐ Supervise/Conduct Cleanup				☐ Gas/Service Station Garage, Auto Dealer, Repair Shop	
Spiller Required To Take Action; Type				☐ Ag Coop/Facility/Cheese Factory/Creamery	
☐ Contractor Hired By DNR; Name				☒ Other Small Business (bank, grocery, insurance co., etc.) FORMER TAVERN	
☐ Amount Recovered				☐ Public Property (city, county, state, church, school, etc.)	
☐ 29.29 Enforcement				☐ Utility Co., Power Generating/Transfer Facility	
Other Agencies on Scene				☐ Private Property (home/farm)	
Local				☐ Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler	
State				☐ Transportation Accident, Fuel Supply Tank Spill	
Federal				☐ Transportation Accident, Load Spill	
Additional Comments:				☐ Construction, Excavation, Wrecking, Quarry, Mine	
Old Tank will be salvaged at Max Phillips, Eau Claire. Soil under pump island contaminated with > 100 PPM gasoline by vapor. Twin City Testing taking soil samples; will handle recovery operations. Soil is sand; contamination extends at least 10' below surface.				☐ Other	
				Spilled Substance Destination	
				☐ Air	
				☒ Soil	
				☐ Groundwater	
				☐ Surface Water	
				☐ Storm Sewer	
				☐ Sanitary Sewer	
				☐ Contained/Recovered	
				☒ Other Contaminated Soil to go to SARONA Landfill	
				Person Filing This Report (print name) JOHN R. POHLMAN II	
				Signature John R. Pohlman	
				Date Signed 4-20-89	