State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921 dnr.wi.gov

## Site Investigation Sample Results Notification

Form 4400-249 (R 03/14)

Page 1 of 2

**Notice:** This form may be used to comply with the requirements of s. NR 716.14 (2), Wis. Adm. Code; however, use of this form is not required. An alternate format may be used. The rule requires that notification be provided to 1) property owners when someone else is conducting the sampling, 2) to occupants of property belonging to the responsible person, and 3) to owners and occupants of property that does not belong to the responsible person but has been affected by contamination arising on his or her property. Notification is required within 10 business days of receiving the sample results. Personal information collected will be used for program administration and may be provided to requesters to the extent required by Wisconsin's Open Records law [ss. 19.31-19.39, Wis. Stats.].

**NOTE:** Under s. NR 716.14, Wis. Adm. Code, the responsible party must also submit sample results and other required information to the DNR. We recommend that copies of the sample results notifications be included with that submittal, along with all attachments. Using the same format used for data presentation for a closure request may be helpful to all parties. See s. NR 716.14, Wis. Adm. Code for the full list of information to be submitted to the DNR.

#### Notification of Property Owners and Occupants:

This notification form has been provided to you in order to provide the results of environmental sampling that has been conducted on property that you own or occupy. Samples were collected in accordance with the methods identified in the site investigation work plan, in accordance with s. NR. 716.09 and 716.13, Wis. Adm. Code. This sampling was conducted as a result of contamination originating at the following location.

Site Information							
Site Name	1				DNR II	D # (BRRTS #)	
Former Navistar/RMC	Foundry				02-68-	-098404	
Address	*		City		State	ZIP Code	
1401 Perkins Avenue			Waukesha	- CTITT	WI	53186	
Responsible Party				RECEIV			1
The person(s) responsible	e for completing t	this environmental in	vestigation is:				
Property Owner				SEP 01 20	20		
Navistar, Inc.				JLI VI 20	7.0		
Address			City		State	ZIP Code	
2701 Navistar Drive			Lisle	BY:	IL	60532	
Contact Person				Phor		include area code)	)
Ferdinand Alido					(331)	332-6364	
Person or company that	collected sample:	s		· with			
KPRG and Associates	, Inc.						
Sample Results (Resu		对在10年常见发展6				<b>计图图图图</b>	
Reason for Sampling:	O = "	_					911
Reason for Sampling.	Routine	<ul><li>Other (define)</li></ul>	Site Investigati	on			3
	O						8
The contaminants that ha	O	ed at this time on pro					3
	ave been identifie	ed at this time on pro oil? In Grou No Yes	perty that you owr ndwater? <u>No</u>				8
The contaminants that ha	ave been identifie	ed at this time on propoil?	perty that you owr	or occupy include:  This sampling event	included sa	mpling of a	
The contaminants that have	ave been identifie  In So  Yes  O	ed at this time on propoil?  In Grou  No  Yes  O	perty that you owr ndwater? - No	n or occupy include:	included sa	mpling of a	?
The contaminants that have a contaminant Gasoline	ave been identifie In So Yes  O	ed at this time on proposed in Group oil? In Group Yes O	perty that you owr ndwater? No	This sampling event drinking water well.	<ul><li>No</li></ul>		?
The contaminants that have a contaminant Gasoline Diesel or Fuel Oil	ave been identifie  In So  Yes  O	ed at this time on propoil?  In Grou  No  Yes  O	perty that you owr ndwater? - No	This sampling event drinking water well.  Yes  If yes, the sampled of	No Irinking wate		3
The contaminants that have a contaminant.  Gasoline Diesel or Fuel Oil Solvents	ave been identifie In So Yes  O	ed at this time on proposed in Group oil? In Group Yes O	perty that you owr ndwater? No	This sampling event drinking water well.  Yes  If yes, the sampled of detectable contamin	No No Irinking wate		?
The contaminants that have Contaminant Gasoline Diesel or Fuel Oil Solvents Heavy Metals	ave been identifie In So Yes  O	ed at this time on propoil?  In Grou  No  Yes  O  O  O  O  O  O  O  O  O  O  O  O  O	perty that you owr ndwater? - No	This sampling event drinking water well.  Yes  If yes, the sampled of	No Irinking wate		
The contaminants that have Contaminant Gasoline Diesel or Fuel Oil Solvents Heavy Metals Pesticides	ave been identifie  In So  Yes  O  O  O	ed at this time on proportion oil? In Group No Yes O O O O O O O O O O O O O O O O O O O	perty that you owr ndwater? No	This sampling event drinking water well.  Yes  If yes, the sampled of detectable contamin	No No Irinking wate		*
The contaminants that have Contaminant Gasoline Diesel or Fuel Oil Solvents Heavy Metals Pesticides	ave been identifie  In So  Yes  O  O  O	ed at this time on proportion oil? In Group No Yes O	perty that you owr ndwater? No	This sampling event drinking water well.  Yes  If yes, the sampled of detectable contamin	No No Irinking wate		2
The contaminants that have Contaminant Gasoline Diesel or Fuel Oil Solvents Heavy Metals Pesticides	ave been identifie  In So  Yes  O  O  O	ed at this time on proportion oil?  In Grou  Yes  O  O  O  O  O  Contaminants in Va	perty that you owr ndwater? No	This sampling event drinking water well.  Yes  If yes, the sampled of detectable contamin	No No Irinking wate		
The contaminants that he Contaminant Gasoline Diesel or Fuel Oil Solvents Heavy Metals Pesticides Other:	ave been identifie  In So  Yes  O  O  O	ed at this time on propoil? In Grou  No Yes  O O  O O  O O  Contaminants in Variable Model  Yes No	perty that you owr ndwater? No	This sampling event drinking water well.  Yes  If yes, the sampled of detectable contamin	No No Irinking wate		

## **Site Investigation Sample Results Notification**

Form 4400-249 (R 03/14)

Page 2 of 2

#### Attached are:


- A map that shows the locations from which samples were collected. (The map needs to meet the requirements of s. NR 716.15 (4), Wis. Adm. Code.)
- A data table with specific contaminant levels at each sample location and whether or not the sample results exceed state standards.
- A copy of the laboratory results.

mark.drews@wisconsin.gov

You are not identified as the person that is responsible for this contamination. However, your cooperation is important. Property owners may become legally responsible for contamination if they do not allow access to the person that is responsible so that person may complete the environmental investigation and clean up activities.

Option for written exemption: You have the option of requesting a written liability exemption from the DNR for contamination that originated on another property, or on property that you lease. To do this, you must present an adequate environmental assessment of your property and pay a \$700 fee for review of this information. If you are interested in this option, please see DNR publication # RR 589, "When Contamination Crosses a Property Line - Rights and Responsibilities of Property Owners", available at: <a href="https://dnr.wi.gov/files/PDF/pubs/rr/rr589.pdf">dnr.wi.gov/files/PDF/pubs/rr/rr589.pdf</a>.

Contact Information		100						
Please address questions regarding this notificatior of the following contacts:	n, or requests for	additional information	on to the contact per	rson list	ed above, or to one			
Environmental Consultant								
Company Name	Contact Person	n Last Name	First Name	9				
KPRG and Associates, Inc.	Gnat		Richard					
Address		City		State	ZIP Code			
14665 W. Lisbon Rd., Suite 1A		Brookfield		WI	53005			
Phone # (inc. area code) Email richardg@kprgine	c.com							
Select which agency:	0 0	Trade and Consume	er Protection					
Contact Person Last Name	First I	Vame		Phone # (inc. area code)				
Drews	Mark	(		(262) 574-2146				
Address		City		State	ZIP Code			
141 NW Barstow Street, Room 180		Waukesha		WI	53188			
Email								



ENVIRONMENTAL CONSULTATION & REMEDIATION

KPRG and Associates, Inc.

August 27, 2020

Robert Armstrong 1222 Lombardi Way Waukesha, WI 53186

SUBJECT: Ambient Air Sampling Data Transmittal – 1222 Lombardi Way

Dear Residents,

KPRG and Associates, Inc. (KPRG) completed a follow-up round of indoor air sampling for trichloroethene (TCE) within the basement of your residence on August 19, 2020 (an outdoor air sample was also collected at the same time). We recently received the analytical results from the laboratory for the sampling. In accordance with our Access Agreement for this sampling, attached is Table 1 which summarizes the indoor air results along with the initial sampling results from prior to the installation of a sub-slab depressurization system (SSDS). The table also includes the applicable comparison vapor action level (VAL) for indoor air. The post-SSDS installation sampling data indicates that TCE was not detected above the established VAL within the interior basement air. This indicates that the SSDS installation is working as designed.

Thank you for allowing access to your property for this study. If you have any questions please call me at 262-781-0475. You can also contact the WDNR Project Manager, Mark Drews, with any questions at 262-574-2146.

Sincerely,

KPRG and Associates, Inc.

Richard R. Gnat, P.G.

Principal

Enclosures: Summary Data Table

Richard R gnot

Table 1. Indoor and Outdoor Air Sample Results for 1222 Lombardi Way

	Sample ID	WDNR VAL	1222 Lombardi Way IA-1	1222 Lombardi Way IA-1	1222 Lombardi Way OA-1	1222 Lombardi Way OA-1
Parameter	Date	Residential	10/11/2019	8/19/2020	10/11/2019	8/19/2020
Trichloroethene		2.1	5.9	0.33J	<0.38	<0.25

Notes: All values are in ug/m3.

VAL - Indoor air Vapor Action Level

IA - Indoor Air

OA - Outdoor Air

J - Below reporting limit but above detection limit. Value is estimated.

BOLD - Exceeds established VAL.





August 26, 2020

Richard Gnat KPRG and Associates 14665 W. Lisbon Rd. Suite 1A Brookfield, WI 53005

RE:

Project: 11717 RMG/NAVISTAR

Pace Project No.: 10529403

Dear Richard Gnat:

Enclosed are the analytical results for sample(s) received by the laboratory on August 21, 2020. The results relate only to the samples included in this report. Results reported herein conform to the applicable TNI/NELAC Standards and the laboratory's Quality Manual, where applicable, unless otherwise noted in the body of the report.

The test results provided in this final report were generated by each of the following laboratories within the Pace Network:

• Pace Analytical Services - Minneapolis

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kirsten Hogberg

King Haffrey

kirsten.hogberg@pacelabs.com (612)607-1700

Project Manager

Enclosures

cc: Patrick Allenstein, KPRG and Associates Tim Stohner, KPRG and Associates







#### **CERTIFICATIONS**

Project: 11717 RMG/NAVISTAR

Pace Project No.: 10529403

Pace Analytical Services - Minneapolis MN

A2LA Certification #: 2926.01 Alabama Certification #: 40770

Alaska Contaminated Sites Certification #: 17-009

Alaska DW Certification #: MN00064 Arizona Certification #: AZ0014 Arkansas DW Certification #: MN00064 Arkansas WW Certification #: 88-0680 California Certification #: 2929

California Certification #: 2929
CNMI Saipan Certification #: MP0003
Colorado Certification #: MN00064
Connecticut Certification #: PH-0256

EPA Region 8+Wyoming DW Certification #: via MN 027-

053-137

Georgia Certification #: E87605
Georgia Certification #: 959
Guam EPA Certification #: MN00064
Hawaii Certification #: MN00064
Idaho Certification #: MN00064
Illinois Certification #: C-MN-01
Indiana Certification #: C-MN-01
Iowa Certification #: 368
Kansas Certification #: E-10167
Kentucky DW Certification #: 90062

Kentucky WW Certification #: 90062 Louisiana DEQ Certification #: 03086 Louisiana DW Certification #: MN00064

Maine Certification #: MN00064 Maryland Certification #: 322

Massachusetts DWP Certification #: via MN 027-053-137

Michigan Certification #: 9909 Minnesota Certification #: 027-053-137

Minnesota Dept of Ag Certification #: via MN 027-053-137

Minnesota Petrofund Certification #: 1240
Mississippi Certification #: MN00064
Missouri Certification #: 10100
Montana Certification #: CERT0092
Nebraska Certification #: NE-OS-18-06
Nevada Certification #: MN00064
New Hampshire Certification #: 2081
New Jersey Certification #: MN002
New York Certification #: 11647

North Carolina DW Certification #: 27700 North Carolina WW Certification #: 530 North Dakota Certification #: R-036 Ohio DW Certification #: 41244 Ohio VAP Certification #: CL101 Oklahoma Certification #: 9507

Oregon Primary Certification #: MN300001
Oregon Secondary Certification #: MN200001
Pennsylvania Certification #: 68-00563
Puerto Rico Certification #: MN00064
South Carolina Certification #:74003001
Tennessee Certification #: TN02818
Texas Certification #: T104704192
Utah Certification #: MN00064
Vermont Certification #: VT-027053137
Virginia Certification #: 460163
Washington Certification #: C486
West Virginia DEP Certification #: 382
West Virginia DW Certification #: 9952 C

Wyoming UST Certification #: via A2LA 2926.01

Wisconsin Certification #: 999407970

## REPORT OF LABORATORY ANALYSIS



## **SAMPLE SUMMARY**

Project:

11717 RMG/NAVISTAR

Pace Project No.: 10529403

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10529403001	1222 Lombardi IA-1	Air	08/19/20 12:25	08/21/20 11:00
10529403002	1222 Lombardi OA-1	Air	08/19/20 12:27	08/21/20 11:00



#### **SAMPLE ANALYTE COUNT**

Project:

11717 RMG/NAVISTAR

Pace Project No.: 10529403

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10529403001	1222 Lombardi IA-1	TO-15	MJL	1
10529403002	1222 Lombardi OA-1	TO-15	MJL	1

PASI-M = Pace Analytical Services - Minneapolis



### **ANALYTICAL RESULTS**

Project:

11717 RMG/NAVISTAR

Results

<0.25

Units

ug/m3

Pace Analytical Services - Minneapolis

Analytical Method: TO-15

Pace Project No.:

Parameters

TO15 MSV AIR

Trichloroethene

Date: 08/26/2020 02:18 PM

10529403

Sample: 1222 Lombardi IA-1	Lab ID:	10529403001	Collected	l: 08/19/2	0 12:25	Received: 08/	21/20 11:00 M	atrix: Air	
Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
TO15 MSV AIR	•	Method: TO-15 lytical Services		is					
Trichloroethene	0.33J	ug/m3	0.79	0.25	1.44		08/24/20 16:34	79-01-6	
Sample: 1222 Lombardi OA-1	Lab ID:	10529403002	Collected	i: 08/19/2	0 12:27	Received: 08/	21/20 11:00 M	atrix: Air	

LOD

0.25

DF

1.44

Prepared

Analyzed

08/24/20 17:45 79-01-6

CAS No.

Qual

LOQ

0.79



#### **QUALITY CONTROL DATA**

Project:

11717 RMG/NAVISTAR

Pace Project No.:

QC Batch Method:

10529403

QC Batch:

694600

Analysis Method:

TO-15

TO-15

Analysis Description:

TO15 MSV AIR Low Level

Laboratory:

Pace Analytical Services - Minneapolis

Associated Lab Samples:

10529403001, 10529403002

METHOD BLANK: 3711931

Associated Lab Samples:

10529403001, 10529403002

Matrix: Air

Parameter

Blank Result Reporting Limit

49.1

Dup

Analyzed

Qualifiers

Trichloroethene

Units ug/m3

Units

ug/m3

Units

ug/m3

< 0.18

0.55 08/24/20 08:39

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

3711932

Spike Conc.

LCS Result

LCS % Rec

87

% Rec Limits

70-132

Max

25

25

Qualifiers

Trichloroethene

SAMPLE DUPLICATE: 3712817

10529403001 Result

56.3

0.33J

< 0.25

RPD Result

0.37J

RPD

Qualifiers

Trichloroethene

Trichloroethene

Date: 08/26/2020 02:18 PM

SAMPLE DUPLICATE: 3712818

Parameter Units ug/m3 10529403002 Result

Dup Result <0.25

**RPD** 

Max **RPD** 

Qualifiers

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALIFIERS**

Project: 11717 RMG/NAVISTAR

Pace Project No.: 10529403

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above LOD.

J - Estimated concentration at or above the LOD and below the LOQ.

LOD - Limit of Detection adjusted for dilution factor, percent moisture, initial weight and final volume.

LOQ - Limit of Quantitation adjusted for dilution factor, percent moisture, initial weight and final volume.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected at or above the adjusted LOD.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

Date: 08/26/2020 02:18 PM





## **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project:

11717 RMG/NAVISTAR

Pace Project No.: 10529403

Date: 08/26/2020 02:18 PM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
10529403001	1222 Lombardi IA-1	TO-15	694600		
10529403002	1222 Lombardi OA-1	TO-15	694600		



## AIR: CHAIN-OF-CUSTO

WO#:10529403

Section Requi	on A ired Client Inf	ormation:			Section Requirements	on B red Proje	ct Inforn	nation:				Sectio Invoice	n C Informatio	n:		North agent	-2-5	k 1	12.5	y						41	.3	07	7	Page:	of	
Comp	any: KRV	GANDT	155 cc.	425	Report	To: 5	4ME	: 1 <sup>1</sup> 1.22	** :	₽Ū.	addili	Attentio	n: 5	AME	- • Z3.±2-	L. 1,24	. :		May 30	<u> </u>	:					F	rogra	am	त्या व	11 gr	· 400 - 1	435 3412
Addre	ss:14665	W. LISBE	J 2D.	14	Copy 7	Го:						Compa	ny Name:		· · · · · ·	<del></del>			•	<del></del>			F	์ บรา		Superf	und	T E	missio	ns [	Clean A	ir Act
		D, WI 530					13 121	- ( · ·			:	Address		• * * * * * * * * * * * * * * * * * * *		ere de	,	٠		, .			F	Volun	tary C	lean U	<sub>p</sub> r	Dry C	lean: l	RCRA	4.J., C	Other
Email	الأر صمة	2000	PEGIN	CIGA	Purcha	se Orde	r No.:						uote Refer					• 1, 1, 1		٠.			1.00	ation	of					Reporting		
Phone	-6475	722-7	21-66	175	Project	t Name:	DMG	-/~	Lal	157	AP_	Pace P	roject Man	ager/Sales												State	1	11		ug/m³ PPBV Other	PPMV_	
Reque	ested Due Da	ate/TAT: STA	HOSE	5	Project	Number	· ((-	717	) : :	1 1		Pace P	rofile #:		(37)	1 25 1		· .	1.47		÷.		Rep	ort L	evel	11	III	IV		Other_	1 21/11	
		n D Required C				dia Codes	CODE	Π		Γ		COLL	ECTED		ure	6 ø E			17.	-			Met	hod:	1	77	7	//	11	00/	7	
	/	AIR SAME	PLE I	)	Tedlar Ba		TB		llent o						ر د د ا	insse		Sun	nma		Fle	ow		,	//,		[ [	\s <sup>*</sup> /.				
1	Sar	mple IDs MUST I	BE UNIQU	IE	Low Volu		LVP	MEDIA CODE	Reading (Client only)		1 of	10,000	a gra	ជាធ្វា អ	er Pres	. 65 11		Ca	in 🐇			itrol	A A A A A A A A A A A A A A A A A A A	$\mathcal{L}$	\#\  \$\!		//		10.15 John 1/81 Ch	**************************************		
ITEM #					High Vol		HVP PM10	JA CC	Read	СОМ	OSITE STA	RT		MPOSITE - ND/GRAB	Canist	Canist		Num			Nun	nber	1/	/ /ź	\$ \ E			10/0		/	-	
E						·		MEC	G.		ATE	TIME								1	· ·		Va.	13/	<u> 3/2</u>	3/2/	<u> 2</u> /2	3/2/	2/		Pace La	b ID
1		- LOMBA					_6	4			18	1123	8-19	1225			1	23	8 3	1		49						X		<i>C</i>	<u> </u>	:
2	1222	- LOMBA	COI	BA	-1	7.53	6	10		8	-19	1125	8-19	122	1.30	0	1	26	96	0	2	75	5					X		U	10Z	
3																																
4					• • •	14 (1)	15 A		٠.			. 14	137.41				-	: : :														
5		į																									T					
6							• • • •		1				2.1.1	4 172		1 1.	. 1	11.		1	1								1	1 12 - 2 1		1
7	1		*		. ,, .	· .			1	1			1	1 11												1.				-		1 1.
8										1.							1				$\top$											,
9				i	· · · · · · · · · · · · · · · · · · ·	· · ·						1								$\top$					1			$\Box$				
10								ļ	1	广			<u> </u>				$\top$		-	1	$\top$	† †			1	$\sqcap$	1			<u></u>		
11			-:	:	5.	- <del></del>				1					1		1		+	_	1				$\top$		1					
12			:							-		1		1 - 42 - 7			17			1	1			_	-	$\Box$	+	1	+			
Comm	nents:		-				RE	LINC	UIŚI	HED	BY / A	FFILIA	TION	DATE		IME	A	CCEP	TEDE	Y/A	EEIL	IOITAI		DAT	E		IME	i i	SAM	PLE CO	ITIONC	ONS
		1							14			KPQ		9/19/	1	636			. 7		-			7/1	,	1	32			Z.	N.	N.
* '	TCE	ONLY					-	ANY.	V	_	/	<u>kt k</u>	ķ.	7 17	20 4	عده	+	7	50		K	7 . CO	3/2				100		~	É		(2)
71-				1		• • • •	·		-			<u> </u>	<u> </u>	+	+-	<u> </u>	+	41	<u> </u>	نسا	\$ 4	0	0/0	<u> </u>	<u> </u>	11	, 0,			N.	N.	
							$\vdash$				<del> </del>		<u>.</u>	1	1	17	+			•			-			<del> </del>				N.	N. X.	> N X
						:	. L_	:	,		+-		CAMPI	CO NIAME	AND O	NIATI E														-		
ָּטֶ					•						'	•		ER NAME						. 1									i S	ned on	Cool	s Inta
ge :			OF	RIGIN	IAI								SIGNATUR	E of SAMPLE		RICA	<u>'\</u>	سع	157	<del>المرار</del>	TE Sign	ed (MM/D	D/YY) A	۹ .	_			$\dashv$	Temp in	Received Ice	Custody : Sealed Cooler	Samples Intact
Page 9 of 10			J,										L		14/	$\forall$	_	•				ed (MM/D	ع	<u>5-</u> !	4-	115				Œ.	<u>~</u>	Sa
10																_																

nicologi programa, rates i selli sessili sassili sa sike-edi.

# Pace Analytical

**Document Name:** 

Document Revised: 24Mar2020

Sample Condition Upon Receipt (SCUR) - Air

Document No.:

Page 1 of 1

ENV-FRM-MIN4-0113 Rev.00

Pace Analytical Services -Minneapolis

Air Sample Condition Upon Receipt	Client Name	: KPR	1	F	Project #:		HUM	<u>: 10</u>	<b>5294</b>	<b>03</b>	
	Fed Ex	UPS SpeeDee ラルリ の	USPS Comm	Clinercial See			PM: KNI CLIENT:	ł		: 08/28/	20
Custody Seal on Coole	r/Box Present?	∐Yes	Mo	Seals Inta	t? Ye	25	Mo			the second	
Packing Material:	Bubble Wrap	Bubble B	ags <b>F</b> oa	m [No	ne 🔲 Tii	n Can	☐Other:	····	Temp	Blank rec: [	]Yes [X]No
Temp. (TO17 and TO13 sa Temp should be above fr Type of ice Received	eezing to 6°C	Correction Fact	Corrected Ten	np (°C):		)ate & 1	Initials of Pe		meter Used: ing Contents:	□G87A9170 □G87A9151	
	_		·-^			T.		····	Comments:		
Chain of Custody Present		<u>.</u>	<u> X</u>			1.					
Chain of Custody Filled O			<u>Z</u>			2.					
Chain of Custody Relinqui						3.					
Sampler Name and/or Sig	nature on COC?					4.					
Samples Arrived within H						5.					
Short Hold Time Analysis				es No		6.					<del></del>
Rush Turn Around Time I	Requested?			es XXX		7.					
Sufficient Volume?		·		es 🔲 No	)	8.					<del></del>
Correct Containers Used? (Tediar bags not acce		ner for TO-1									
TO-15 or APH) -Pace Containers Used	?		( <u>P</u> )	***************************************		9.	_				
Containers Intact?			`								
(visual inspection/no	leaks when p	ressurized)	⊠y	′es □No	1	10.					
Media: Air Can	Airbag	Filter	TDT P	assive		11.	Indiv	idually Cert	ified Cans Y	N (list whi	ch samples)
Is sufficient information a	yailable to reco	ncile samples t	:o <b>\\\\</b> \\	∕es ∏No		12.					
Do cans need to be press (DO NOT PRESSURI		M 1946!!!)	7°			13.					
		Gauge #	10AIR26	T 10AIR	34 🗀 1	LOAIR	R35 [74]	097			
					<u>-                                    </u>	111	<u></u>				
	Cani	sters Flow	Initial	Final					anisters Flow	Initial	Final
Sample Number	Can ID	Controller	Pressure	Pressure	Sar	mple N	lumber	Can ID	Controller	Pressure	Pressure
<u> 7A-1</u>	7383	1949	-Z	+5							
0A-1	76960	7.75	-Z-	11	ļ						
	-										
											<b> </b>
-											
CLIENT NOTIFICATION, Person Co Comments/Re	ntacted:								ita Required?		
Project Manager Revie			Jerg				Date: 8/2			Pag	e 10 of 10

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e out of hold, incorrect preservative, out of temp, incorrect containers)