

Detailed Information for Dam Fish Lake Wla County Hwy O

Seq No		1020	Field File No	07.31
Size	SMALL		NID	1135
Popular Name	Alstad		Former Name	

Location

County	Burnett	Longitude	-92.799230
Latitude	45.683220		
Permitted PLSS	NWNW2437N20W		

Owners

Type	State Agency	Name	Wisconsin Department of Natural Resources
------	--------------	------	---

Waterbody

Drainage Basin (sq mi)	1.60		
Stream		Impoundment	
Local Name	COWEN CREEK	Local Name	COUNTY TRUNK O FLOWAGE
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	150.00
When was navigability determined?		Maximum Depth (ft)	4.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	200.00	Max Storage (acre-ft)	650.00
Structural Height (ft)	5.80	Hydraulic Height (ft)	2.50
Crest Length (ft)	11,200.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	80.00	Width/Diameter of Principal Spillway (ft)	3.00
Total Discharge Through All Spillways (cfs)	80.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Structure Purposes	Other - Cranberry, Wetland Restoration, Waste		

Detailed Information for Dam Fish Lake Wla County Hwy O

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
WI DNR		1977

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
		None
6/17/2003	8/13/2003	Inspection conducted by DNR under Ch. 31.19(2)decennial

Followups

Type of Followup	Due Date	Extension Date	Completion Date
Spillway outlet conduit	07/30/2004		
Vegetation	07/30/2004		

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.