

## Detailed Information for Dam Gollon, Bill

Seq No		1075	Field File No	60.39
Size	LARGE		NID	1189
Popular Name			Former Name	

### Location

County	Taylor	Longitude	-90.853966
Latitude	45.042637		
Permitted PLSS	NENW3430N04W		

### Owners

Type	Private	Name	Doro, Adam
------	---------	------	------------

### Waterbody

Drainage Basin (sq mi)		0.60		
<b>Stream</b>			<b>Impoundment</b>	
Local Name	WOLF RIVER		Local Name	GOLLON BAIT FARM
Row and Official Name			Row and Official Name	
Navigable?	non-navigable		Size (acres)	45.00
When was navigability determined?	1966		Maximum Depth (ft)	6.00

### Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Normal Operation	Low Head Dam Assessment	No
<b>Compliance Status</b>			
Ch. 31.19 Owner Inspection	Compliant	Ch 31.19 DNR Inspection	Compliant
NR 333 Standards	Required		
<b>NR 333 Compliance Items</b>			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year	1995	Stability NR 333 Year	1990
D/S NR 333 Year	2024		

### Construction Characteristics

Normal Storage (acre-ft)	260.00	Max Storage (acre-ft)	350.00
Structural Height (ft)	11.00	Hydraulic Height (ft)	7.00
Crest Length (ft)	1,445.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	41.30	Width/Diameter of Principal Spillway (ft)	2.00
Total Discharge Through All Spillways (cfs)	343.50	Total Width/Diameter of All Spillways (ft)	47.00
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Structure Purposes	Fish Pond, Aquaculture and Wildlife		

## Detailed Information for Dam Gollon, Bill

### Geomarks

No data found.

### Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

### Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
SCS		1966

### Outlet Gates

No data found.

### Inspection History

Inspection Date	Inspection Report Date	Inspection Type
11/14/2024	7/16/2025	Transfer Inspection
4/18/2017	9/18/2017	Inspection by Owner/Engineering Consultant under Ch. 31.19(2)(ag)
9/20/2007	9/24/2007	Inspection conducted by DNR under Ch. 31.19(2)decennial
6/14/2001		Informal Inspection to check on status or progress on work directives
10/24/1990		None

### Followups

Type of Followup	Due Date	Extension Date	Completion Date
Benchmarks	09/30/2010	08/01/2026	
Water levels	09/01/2025		
Embankment repairs	08/01/2026		
Inspection, Operation & Maintenance Manual	08/01/2026		
Emergency Action Plan	08/01/2026		
Monitoring	12/31/2034		

### Approvals

Approval Date	Approval Type
7/29/2025	Dam Transfer; Stat 31.185B
8/16/1999	Dam Transfer; Stat 31.185B
9/1/1995	Dam Failure Analysis
1/1/1990	Plan Appr. Repair/Recon; Stat 31.18
4/28/1966	Plan Appr. New Dam on Non-Nav Str; Stat 31.33

### Orders

No data found.

### Inspection Schedule

Inspection Year	Inspection Type
2034	Owner
2044	Owner

### Analysis

No data found.