

## Detailed Information for Dam Gollon, Bill

Seq No	1075	Field File No	60.39
Size	LARGE	NID	1189
Popular Name		Former Name	

### Location

County	Taylor	Longitude	-90.853966
Latitude	45.042637		
Permitted PLSS	NENW3430N04W		

### Owners

Type	Private	Name	Shaw, Tim
------	---------	------	-----------

### Waterbody

Drainage Basin (sq mi)	0.60		
<b>Stream</b>		<b>Impoundment</b>	
Local Name	WOLF RIVER	Local Name	GOLLON BAIT FARM
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	45.00
When was navigability determined?		Maximum Depth (ft)	6.00

### Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Normal Operation	Low Head Dam Assessment	Not Evaluated
<b>Compliance Status</b>			
Ch. 31.19 Owner Inspection	Compliant	Ch 31.19 DNR Inspection	Compliant
NR 333 Standards	Required		
<b>NR 333 Compliance Items</b>			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year	1995	Stability NR 333 Year	1990
D/S NR 333 Year			

### Construction Characteristics

Normal Storage (acre-ft)	260.00	Max Storage (acre-ft)	350.00
Structural Height (ft)	11.00	Hydraulic Height (ft)	7.00
Crest Length (ft)	1,445.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	41.30	Width/Diameter of Principal Spillway (ft)	2.00
Total Discharge Through All Spillways (cfs)	343.50	Total Width/Diameter of All Spillways (ft)	47.00
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Structure Purposes	Fish Pond, Aquaculture and Wildlife		

## Detailed Information for Dam Gollon, Bill

### Geomarks

No data found.

### Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

### Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
SCS		1966

### Outlet Gates

No data found.

### Inspection History

Inspection Date	Inspection Report Date	Inspection Type
4/18/2017	9/18/2017	Inspection by Owner/Engineering Consultant under Ch. 31.19(2)(ag)
9/20/2007	9/24/2007	Inspection conducted by DNR under Ch. 31.19(2)decennial
6/14/2001		Informal Inspection to check on status or progress on work directives
10/24/1990		None

### Followups

Type of Followup	Due Date	Extension Date	Completion Date
Benchmarks	09/30/2010		
Other	05/01/2018		

### Approvals

Approval Date	Approval Type
9/1/1995	Dam Failure Analysis
1/1/1990	Plan Appr. Repair/Recon; Stat 31.18

### Orders

No data found.

### Inspection Schedule

Inspection Year	Inspection Type
2027	Owner

### Analysis

No data found.