

Detailed Information for Dam Berlin

Seq No	1207	Field File No	24.01
Size	UNKNOWN	NID	10163
Popular Name	Wi Dnr	Former Name	

Location

County	Green Lake	Longitude	-88.959340
Latitude	43.951998		
Permitted PLSS	NWNE1617N13E		

Owners

Type	State Agency	Name	Wisconsin Department of Natural Resources
------	--------------	------	---

Waterbody

Drainage Basin (sq mi)	1,340.00		
Stream		Impoundment	
Local Name	FOX	Local Name	
Row and Official Name		Row and Official Name	
Navigable?	navigable	Size (acres)	
When was navigability determined?		Maximum Depth (ft)	

Regulation

Regulatory Authority	Wisconsin	Legal Status	Not Clear
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)		Max Storage (acre-ft)	
Structural Height (ft)	1.00	Hydraulic Height (ft)	0.00
Crest Length (ft)	200.00	Spillway Type	Uncontrolled
Discharge Through Principal Spillway (cfs)	9,790.00	Width/Diameter of Principal Spillway (ft)	201.00
Total Discharge Through All Spillways (cfs)	9,790.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Gravity, Earth		
Structure Purposes	Navigation		

Detailed Information for Dam Berlin

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
5796	1345-A	100	Local	Verified (Surveyed)	9/8/1969	BM 1345-A IS A CORPS OF ENGINEERS BRASS CAP IN THE RIGHT UPSTREAM ABUTMENT OF GATE CULVERT THRU FILL

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
		1915

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
9/8/1969	9/12/1969	Inspection for the purpose of setting or checking water levels
5/18/1961		General Dam Inspection (Usually prior to 1986)
5/18/1961	5/23/1961	Inspection for the purpose of setting or checking water levels

Followups

No data found.

Approvals

No data found.

Orders

Issue Date	Complied On Date	Docket ID	Order Description
10/20/1981		3-SD-81-926	Warning Signs

Inspection Schedule

No data found.

Analysis

No data found.