

Detailed Information for Cranberry Dam Janke

Seq No	257	Field File No	27.16
Size	LARGE	NID	
Popular Name		Former Name	

Location

County	Jackson	Longitude	-90.734956
Latitude	44.186846		
Permitted PLSS	NENE2820N03W		

Owners

Type	Name	BIBLE CRANBERRY MARSH
------	------	-----------------------

Waterbody

Drainage Basin (sq mi)	60.00		
Stream		Impoundment	
Local Name	ROBINSON CREEK	Local Name	
Row and Official Name	Robinson Creek	Row and Official Name	
Navigable?	not determined	Size (acres)	10.00
When was navigability determined?		Maximum Depth (ft)	8.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	25.00	Max Storage (acre-ft)	65.00
Structural Height (ft)	13.00	Hydraulic Height (ft)	9.00
Crest Length (ft)	30.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	1,720.00	Width/Diameter of Principal Spillway (ft)	25.00
Total Discharge Through All Spillways (cfs)	1,720.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Gravity, Earth		
Structure Purposes	Irrigation, Recreation		

Detailed Information for Cranberry Dam Janke

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
6623	736-C	107.22	Local	Verified (Surveyed)	9/10/1937	BM 736-C IS A BRONZE TABLET MARKED PUBLIC SERVICE COMMISSION OF WISCONSIN SET IN TOP OF UPSTREAM END OF LEFT UPSTREAM ABUTMENT OF DAM.
6624	736-E	110.12	Local	Verified (Surveyed)	7/17/1952	BM 736-E IS A SQUARE CUT IN TOP OF RIGHT ABUTMENT OF DAM. IT IS LOCATED 0.5 FT UPSTREAM FROM THE GATES.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site 1930

Designer	Construction Firm	Completed (year)
		1937

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
6/2/1981	6/2/1981	General Dam Inspection (Usually prior to 1986)
6/5/1962	6/11/1962	Inspection for the purpose of setting or checking water levels
7/17/1952	8/21/1952	Inspection for the purpose of setting or checking water levels
7/11/1940	7/20/1940	Inspection for the purpose of setting or checking water levels
7/11/1940	7/11/1940	Inspection for the purpose of setting or checking water levels
9/10/1937	3/17/1938	Inspection for the purpose of setting or checking water levels
7/24/1931	7/25/1931	Inspection for the purpose of setting or checking water levels

Followups

No data found.

Approvals

Approval Date	Approval Type
10/1/1931	Permit to Construct on Nav Str; Stat 31.06

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.