

Detailed Information for Cranberry Dam Perry Creek

Seq No	258	Field File No	27.25
Size	LARGE	NID	
Popular Name		Former Name	

Location

County	Jackson	Longitude	-90.790208
Latitude	44.257116		
Permitted PLSS	SWNE3121N03W		

Owners

Type	Name	PERRY CREEK CRANBERRY CO
------	------	--------------------------

Waterbody

Drainage Basin (sq mi)	7.00		
Stream		Impoundment	
Local Name	PERRY CREEK	Local Name	LAKE 31 3
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	25.00
When was navigability determined?		Maximum Depth (ft)	7.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	60.00	Max Storage (acre-ft)	120.00
Structural Height (ft)	14.00	Hydraulic Height (ft)	9.00
Crest Length (ft)	500.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	1,160.00	Width/Diameter of Principal Spillway (ft)	17.00
Total Discharge Through All Spillways (cfs)	1,160.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type		Foundation Certainty	
Structural Types	None		
Structure Purposes	Earth, Other Irrigation		

Detailed Information for Cranberry Dam Perry Creek

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
6599	1040	106.73	Local	Verified (Surveyed)	6/7/1962	BM 1040 IS A SQUARE NOTCH IN THE RIGHT DOWNSTREAM WINGWALL, 1 FT. UPSTREAM FROM THE END.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site 1905

Designer	Construction Firm	Completed (year)
		1936

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
6/7/1962	6/12/1962	Inspection for the purpose of setting or checking water levels

Followups

No data found.

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.