

Detailed Information for Dam North Scott Township

Seq No	553	Field File No	41.22
Size	SMALL	NID	581
Popular Name	Scott Flowage	Former Name	Timber Dam No.4

Location

County	Monroe	Longitude	-90.379073
Latitude	44.142376		
Permitted PLSS	NWNE0919N01E		

Owners

Type	Federal Agency	Name	U.S. Department of the Interior
------	----------------	------	---------------------------------

Waterbody

Drainage Basin (sq mi)	5.00		
Stream		Impoundment	
Local Name	DEAD CREEK DRAINAGE DITCH	Local Name	SCOTT FLOWAGE
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	45.00
When was navigability determined?		Maximum Depth (ft)	6.00

Regulation

Regulatory Authority	Federal	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	300.00	Max Storage (acre-ft)	600.00
Structural Height (ft)	5.80	Hydraulic Height (ft)	5.00
Crest Length (ft)	2,400.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	130.00	Width/Diameter of Principal Spillway (ft)	3.00
Total Discharge Through All Spillways (cfs)	130.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Earth, Other		
Structure Purposes	Irrigation, Recreation, Water Supply		

Detailed Information for Dam North Scott Township

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
10016	894-C	100	Local	Verified (Surveyed)	6/11/1981	BM 894-C IS THE CENTER OF STEEL BAR ACROSS DROP INLET GATE.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	966.5 ft Datum: MSL	Not established

Construction History

First Dam at Site 1937

Designer	Construction Firm	Completed (year)
RESETTLEMENT ADMIN.		1950

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
6/11/1981		Inspection for the purpose of setting or checking water levels
8/23/1947	8/25/1947	Inspection for the purpose of setting or checking water levels
7/20/1940		General Dam Inspection (Usually prior to 1986)
7/12/1940	7/20/1940	Inspection for the purpose of setting or checking water levels

Followups

No data found.

Approvals

Approval Date	Approval Type
6/1/1998	Plan Appr. Repair/Recon; Stat 31.18

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.