# Detailed Information for Cranberry Dam North Tomah Cranberry Co.

Seq No Size Popular Name	LARGE	598	Field File No NID Former Name			41.34
Location						
County Latitude Permitted PLSS	Monroe 44.019158 SENW2218N01W		Longitude		-90.484768	
Owners						
Туре			Name	NORTH TOM	/AH CRANBERRY C	0
Waterbody						
Drainage Basin (sq mi) <b>Stream</b> Local Name Row and Official Name Navigable? When was navigability determined?	MUD CREEK	7.00	Impoundment Local Name Row and Offici Size (acres) Maximum Dep	al Name		30.00 3.00
Regulation						
Regulatory Authority Physical Status Operational Status <b>Compliance Status</b> Ch. 31.19 Owner Inspection NR 333 Standards	Wisconsin On Landscape Not Applicable Not Applicable Not Required		Legal Status Hazard Rating Low Head Dan Ch 31.19 DNR		Authorized (31.04) Low Not Evaluated Not Applicable	
NR 333 Compliance Items EAP NR 333 Year Capacity NR 333 Year D/S NR 333 Year			IOM NR 333 Y Stability NR 33			
Construction Characteristic	cs					
Normal Storage (acre-ft) Structural Height (ft) Crest Length (ft) Discharge Through Principal Spillway (cfs) Total Discharge Through All		8.00 1,000.00 170.00	Max Storage (a Hydraulic Heig Spillway Type Width/Diamete Spillway (ft) Total Width/Dia	ht (ft) r of Principal	Controlled	150.00 8.00 4.00
Spillways (cfs) Core Type Power Output (mW) Foundation Type Structural Types Sturcture Purposes	None None Earth Irrigation, Water Su	ıpply	Spillways (ft) Core Position Foundation Ce	rtainty	None	

# Detailed Information for Cranberry Dam North Tomah Cranberry Co.

## Geomarks

No data found.

## Water Levels

1	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

#### **Construction History**

First Dam at Site		
Designer	Construction Firm	Completed (year)
		1970

#### **Outlet Gates**

No data found.

#### Inspection History

No data found.

## Followups

No data found.

Approvals	
Approval Date	Approval Type
1/1/1970	Permit to Construct on Nav Str; Stat 31.06

#### Orders

No data found.

## Inspection Schedule

No data found.

#### Analysis

No data found.