

Detailed Information for No Waterway Lower Clam Lake

Seq No	622	Field File No	57.15
Size	LARGE	NID	
Popular Name		Former Name	

Location

County	Sawyer	Longitude	-90.939502
Latitude	46.135734		
Permitted PLSS	NWSE1242N05W		

Owners

Type	Private	Name	Best, Barbara
------	---------	------	---------------

Waterbody

Drainage Basin (sq mi)	16.00		
Stream		Impoundment	
Local Name	WEST FORK CHIPPEWA	Local Name	LOWER CLAM LAKE
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	229.00
When was navigability determined?		Maximum Depth (ft)	22.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	1,680.00	Max Storage (acre-ft)	2,100.00
Structural Height (ft)	15.00	Hydraulic Height (ft)	7.00
Crest Length (ft)	30.00	Spillway Type	Uncontrolled
Discharge Through Principal Spillway (cfs)	265.00	Width/Diameter of Principal Spillway (ft)	28.00
Total Discharge Through All Spillways (cfs)	265.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Rockfill, Other		
Structure Purposes	Recreation		

Detailed Information for No Waterway Lower Clam Lake

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
13042	859-B	100	Local	Verified (Surveyed)	8/22/1962	BM 859-B IS A BRONZE TABLET MARKED PUBLIC SERVICE COMMISSION OF WISCONSIN, SET IN THE RIGHT UPSTREAM WINGWALL OF THE TWIN BOX CULVERT. CULVERT IS IN HIGHWAY 77.
13043	859-C	113.17	Local	Verified (Surveyed)	7/23/1968	BM 859-C IS A BRONZE TABLET STAMPED DEPARTMENT OF NATURAL RESOURCES, SET IN THE TOP OF A CONCRETE POST. IT IS 140 FT. SW OF THE W END OF THE WOODEN BRIDGE OVER THE DAM, 24 FT. NW OF THE NW CORNER OF AN OUTHUSE, AND 9 FT. NW OF A CLUMP OF 3 6 INCH ELM TREES.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
		1977

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
6/9/1993		General Dam Inspection (Usually prior to 1986)
6/4/1987		Inspection for the purpose of setting or checking water levels
7/28/1980		General Dam Inspection (Usually prior to 1986)
7/1/1974		Inspection for the purpose of setting or checking water levels
8/13/1968	9/19/1968	Inspection for the purpose of setting or checking water levels
7/23/1968	9/20/1968	Inspection for the purpose of setting or checking water levels
8/22/1962	9/13/1962	General Dam Inspection (Usually prior to 1986)
8/1/1950		General Dam Inspection (Usually prior to 1986)
7/29/1938	8/1/1939	Inspection for the purpose of setting or checking water levels
5/29/1926	6/7/1926	General Dam Inspection (Usually prior to 1986)

Followups

No data found.

Approvals

Approval Date	Approval Type
5/4/2016	Dam Transfer; Stat 31.185B

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.