

## Detailed Information for Dam Lake Irogami

Seq No	6266	Field File No	69.00
Size	UNKNOWN	NID	
Popular Name	Weir on Lake Irogami	Former Name	

### Location

County	Waushara	Longitude
Latitude		
Permitted PLSS	518N11E	

### Owners

Type	Sanitary District	Name	Silver Lake Sanitary District
------	-------------------	------	-------------------------------

### Waterbody

Drainage Basin (sq mi)			
<b>Stream</b>		<b>Impoundment</b>	
Local Name		Local Name	Lake Irogami
Row and Official Name		Row and Official Name	Irogami Lake
Navigable?	not determined	Size (acres)	290.00
When was navigability determined?		Maximum Depth (ft)	5.00

### Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
<b>Compliance Status</b>			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
<b>NR 333 Compliance Items</b>			
EAP NR 333 Year		IOM NR 333 Year	2019
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

### Construction Characteristics

Normal Storage (acre-ft)		Max Storage (acre-ft)	
Structural Height (ft)	5.60	Hydraulic Height (ft)	1.50
Crest Length (ft)		Spillway Type	Uncontrolled
Discharge Through Principal Spillway (cfs)		Width/Diameter of Principal Spillway (ft)	
Total Discharge Through All Spillways (cfs)		Total Width/Diameter of All Spillways (ft)	
Core Type	Unlisted or Unknown	Core Position	Unlisted or Unknown
Power Output (mW)			
Foundation Type	Unlisted or Unknown	Foundation Certainty	
Structural Types			
Structure Purposes			

## Detailed Information for Dam Lake Irogami

### Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
18343		869.12	NGVD 29	Verified (Surveyed)	7/25/2018	60-D nail at north side of power pole north of gravel drive and west of 20th Lane

### Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

### Construction History

First Dam at Site 1993

Designer	Construction Firm	Completed (year)
		1993

### Outlet Gates

No data found.

### Inspection History

Inspection Date	Inspection Report Date	Inspection Type
7/2/2019		Informal Inspection to check on status or progress on work directives

### Followups

No data found.

### Approvals

Approval Date	Approval Type
8/21/2019	Plan Appr. Repair/Recon; Stat 31.18

### Orders

Issue Date	Complied On Date	Docket ID	Order Description
11/29/1995		3-LM-95-224	Order issued by Administrative Law Judge

### Inspection Schedule

No data found.

### Analysis

No data found.