

Detailed Information for Dam Resettlement Admin. 20

Seq No	784	Field File No	27.18
Size	SMALL	NID	846
Popular Name	Seated Old Woman Flowage	Former Name	Sq___ Mound Flowage

Location

County	Jackson	Longitude	-90.658501
Latitude	44.282385		
Permitted PLSS	NWSW2021N02W		

Owners

Type	State Agency	Name	Wisconsin Department of Natural Resources
------	--------------	------	---

Waterbody

Drainage Basin (sq mi)	4.00		
Stream		Impoundment	
Local Name		Local Name	
Row and Official Name	Levis Creek	Row and Official Name	
Navigable?	navigable	Size (acres)	14.00
When was navigability determined?	1998	Maximum Depth (ft)	7.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	30.00	Max Storage (acre-ft)	70.00
Structural Height (ft)	5.70	Hydraulic Height (ft)	4.40
Crest Length (ft)	534.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	735.00	Width/Diameter of Principal Spillway (ft)	2.00
Total Discharge Through All Spillways (cfs)	735.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Earth, Other		
Structure Purposes	Recreation		

Detailed Information for Dam Resettlement Admin. 20

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
6643	851-20	922.85	MSL	Verified (Surveyed)	7/12/1938	BM 851-20 IS THE TOP OF CAP OF 2 IN. IRON PIPE ABOUT 200 FT. W OF S END OF DIKE NEAR BLAZED 12 IN. JACK PINE TREE. PIPE EXTENDS 6 IN. ABOVE THE GROUND.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site 1936

Designer	Construction Firm	Completed (year)
USDA RESETTLEMENT ADMIN.		1938

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
9/15/2004	12/17/2004	Inspection conducted by DNR under Ch. 31.19(2)decennial
8/19/1998	8/26/1998	Informal Inspection to check on status or progress on work directives
5/19/1998		Informal Inspection to check on status or progress on work directives
7/12/1938	11/23/1938	Inspection for the purpose of setting or checking water levels

Followups

Type of Followup	Due Date	Extension Date	Completion Date
Embankment repairs	09/30/2005		

Approvals

Approval Date	Approval Type
3/15/2000	Plan Appr. Repair/Recon; Stat 31.18
1/1/1939	Permit to Construct on Nav Str; Stat 31.06

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.