# Detailed Information for Dam Oconto Marsh Wildlife Area

| | | | |
|---|---|---|---|
| Seq No | 823 | Field File No | 42.00 |
| Size | SMALL | NID | 886 |
| Popular Name | | Former Name | |

## Location

| | | | |
|---|---|---|---|
| County | Oconto | | |
| Latitude | 44.906386 | Longitude | -87.844620 |
| Permitted PLSS | NENE1728N22E | | |

## Owners

| | | | |
|---|---|---|---|
| **Type** | State Agency | **Name** | Wisconsin Department of Natural Resources |

## Waterbody

| | | | |
|---|---|---|---|
| Drainage Basin (sq mi) | 1.00 | | |
| **Stream** | | **Impoundment** | |
| Local Name | TR-GREEN BAY | Local Name | LABBIES SLOUGH |
| Row and Official Name | | Row and Official Name | |
| Navigable? | not determined | Size (acres) | 20.00 |
| When was navigability determined? | | Maximum Depth (ft) | 6.00 |

## Regulation

| | | | |
|---|---|---|---|
| Regulatory Authority | Wisconsin | Legal Status | Authorized (31.04) |
| Physical Status | On Landscape | Hazard Rating | Low |
| Operational Status | Not Applicable | Low Head Dam Assessment | Not Evaluated |
| **Compliance Status** | | | |
| Ch. 31.19 Owner Inspection | Not Applicable | Ch 31.19 DNR Inspection | Not Applicable |
| NR 333 Standards | Not Required | | |
| **NR 333 Compliance Items** | | | |
| EAP NR 333 Year | | IOM NR 333 Year | |
| Capacity NR 333 Year | | Stability NR 333 Year | |
| D/S NR 333 Year | | | |

## Construction Characteristics

| | | | |
|---|---|---|---|
| Normal Storage (acre-ft) | 30.00 | Max Storage (acre-ft) | 100.00 |
| Structural Height (ft) | 5.60 | Hydraulic Height (ft) | 4.50 |
| Crest Length (ft) | 15,000.00 | Spillway Type | Controlled |
| Discharge Through Principal Spillway (cfs) | 45.00 | Width/Diameter of Principal Spillway (ft) | 4.00 |
| Total Discharge Through All Spillways (cfs) | 45.00 | Total Width/Diameter of All Spillways (ft) | |
| Core Type | None | Core Position | None |
| Power Output (mW) | 0.00 | | |
| Foundation Type | None | Foundation Certainty | |
| Structural Types | Earth | | |
| Sturcture Purposes | Fish Pond, Aquaculture and Wildlife | | |

# Detailed Information for Dam Oconto Marsh Wildlife Area

## Geomarks

No data found.

## Water Levels

| | Normal | Winter |
|---|---|---|
| Minimum | Not established | Not established |
| Normal | Not established | Not established |
| Maximum | Not established | Not established |

## Construction History

First Dam at Site

| Designer | Construction Firm | Completed (year) |
|---|---|---|
| WI DNR | | 1968 |

## Outlet Gates

No data found.

## Inspection History

| Inspection Date | Inspection Report Date | Inspection Type |
|---|---|---|
| | | None |
| 9/10/2001 | | Inspection conducted by DNR under Ch. 31.19(2)decennial |

## Followups

No data found.

## Approvals

| Approval Date | Approval Type |
|---|---|
| 7/13/2022 | Plan Appr. Repair/Recon; Stat 31.18 |

## Orders

No data found.

## Inspection Schedule

No data found.

## Analysis

| Analysis Seq No | Date | Type | Project | WIDNR Status | FEMA Status |
|---|---|---|---|---|---|
| 2943 | 9/1/1991 | Dam Failure Analysis | | Approved | NotRequired |