

Detailed Information for Dam Hilgendorf

Seq No	886	Field File No	35.34
Size	SMALL	NID	965
Popular Name		Former Name	

Location

County	Lincoln	Longitude	-89.574488
Latitude	45.459246		
Permitted PLSS	SWNE1134N07E		

Owners

Type	Private	Name	Hilgendorf, Rita
------	---------	------	------------------

Waterbody

Drainage Basin (sq mi)	2.00		
Stream		Impoundment	
Local Name	TR GREEN MEADOW CREEK	Local Name	
Row and Official Name		Row and Official Name	
Navigable?	non-navigable	Size (acres)	10.00
When was navigability determined?	1986	Maximum Depth (ft)	18.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	38.40	Max Storage (acre-ft)	44.10
Structural Height (ft)	15.30	Hydraulic Height (ft)	14.30
Crest Length (ft)	325.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	12.00	Width/Diameter of Principal Spillway (ft)	2.50
Total Discharge Through All Spillways (cfs)	56.00	Total Width/Diameter of All Spillways (ft)	12.50
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Structure Purposes	Recreation, Recreation		

Detailed Information for Dam Hilgendorf

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
OWNER	OWNER	1970

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
10/28/2010		Inspection related to a formal enforcement action at a dam
8/25/2010		Inspection related to a formal enforcement action at a dam
8/16/2010		Inspection related to a formal enforcement action at a dam
6/29/2010		Inspection related to a formal enforcement action at a dam
4/16/2010		Inspection related to a formal enforcement action at a dam
3/18/2010		Inspection related to a formal enforcement action at a dam
11/20/2009		Inspection related to a formal enforcement action at a dam
10/16/2009		Inspection related to a formal enforcement action at a dam
9/24/2009		Inspection related to a formal enforcement action at a dam
9/17/2009		Inspection related to a formal enforcement action at a dam
9/11/2009		Inspection related to a formal enforcement action at a dam
9/4/2009		Inspection related to a formal enforcement action at a dam
8/28/2009		Inspection related to a formal enforcement action at a dam
8/26/2009		Inspection related to a formal enforcement action at a dam
8/24/2009		Inspection related to a formal enforcement action at a dam
8/21/2009		Inspection related to a formal enforcement action at a dam
8/14/2009		Inspection related to a formal enforcement action at a dam
8/29/2008		Inspection related to a formal enforcement action at a dam
11/10/2006		Inspection conducted under Ch. 31.19(3) complaint or (4) discretionary
9/25/2006		Inspection conducted under Ch. 31.19(3) complaint or (4) discretionary
6/9/1976		None

Followups

No data found.

Approvals

Approval Date	Approval Type
7/1/2009	Plan Appr. Repair/Recon; Stat 31.18

Orders

Issue Date	Complied On Date	Docket ID	Order Description
4/29/2009	7/1/2009	ENF-NO-2007-35101UW	Remanded order following contested case hearing
9/12/2007	7/1/2009	ENF-NO-2007-35101UW	Prepare plans to breach dam 12/07, breach 6/08 till repaired /removed

Inspection Schedule

No data found.

Analysis

No data found.