

## Detailed Information for Dam Corner Marsh Control

|              |           |               |                            |
|--------------|-----------|---------------|----------------------------|
| Seq No       | 936       | Field File No | 71.31                      |
| Size         | SMALL     | NID           | 1026                       |
| Popular Name | A Flowage | Former Name   | A,B,C,D,F Flowage Controls |

### Location

|                |              |           |            |
|----------------|--------------|-----------|------------|
| County         | Wood         | Longitude | -90.133285 |
| Latitude       | 44.311729    |           |            |
| Permitted PLSS | NWSE1021N03E |           |            |

### Owners

|      |              |      |                                           |
|------|--------------|------|-------------------------------------------|
| Type | State Agency | Name | Wisconsin Department of Natural Resources |
|------|--------------|------|-------------------------------------------|

### Waterbody

|                                   |                   |                       |                            |
|-----------------------------------|-------------------|-----------------------|----------------------------|
| Drainage Basin (sq mi)            | 0.30              |                       |                            |
| <b>Stream</b>                     |                   | <b>Impoundment</b>    |                            |
| Local Name                        | UNNAMED TR YELLOW | Local Name            | CORNER,MIDDLE MARSHES ETC. |
| Row and Official Name             |                   | Row and Official Name |                            |
| Navigable?                        | not determined    | Size (acres)          | 170.00                     |
| When was navigability determined? |                   | Maximum Depth (ft)    | 4.00                       |

### Regulation

|                                |                |                         |                    |
|--------------------------------|----------------|-------------------------|--------------------|
| Regulatory Authority           | Wisconsin      | Legal Status            | Authorized (31.04) |
| Physical Status                | On Landscape   | Hazard Rating           | Low                |
| Operational Status             | Not Applicable | Low Head Dam Assessment | Not Evaluated      |
| <b>Compliance Status</b>       |                |                         |                    |
| Ch. 31.19 Owner Inspection     | Not Applicable | Ch 31.19 DNR Inspection | Not Applicable     |
| NR 333 Standards               | Not Required   |                         |                    |
| <b>NR 333 Compliance Items</b> |                |                         |                    |
| EAP NR 333 Year                |                | IOM NR 333 Year         |                    |
| Capacity NR 333 Year           |                | Stability NR 333 Year   |                    |
| D/S NR 333 Year                |                |                         |                    |

### Construction Characteristics

|                                             |                                                           |                                            |              |
|---------------------------------------------|-----------------------------------------------------------|--------------------------------------------|--------------|
| Normal Storage (acre-ft)                    | 230.00                                                    | Max Storage (acre-ft)                      | 400.00       |
| Structural Height (ft)                      | 5.20                                                      | Hydraulic Height (ft)                      |              |
| Crest Length (ft)                           | 20.00                                                     | Spillway Type                              | Uncontrolled |
| Discharge Through Principal Spillway (cfs)  | 200.00                                                    | Width/Diameter of Principal Spillway (ft)  | 4.00         |
| Total Discharge Through All Spillways (cfs) | 200.00                                                    | Total Width/Diameter of All Spillways (ft) |              |
| Core Type                                   | None                                                      | Core Position                              | None         |
| Power Output (mW)                           | 0.00                                                      |                                            |              |
| Foundation Type                             | None                                                      | Foundation Certainty                       |              |
| Structural Types                            | Earth                                                     |                                            |              |
| Structure Purposes                          | Recreation, Other - Cranberry, Wetland Restoration, Waste |                                            |              |

## Detailed Information for Dam Corner Marsh Control

### Geomarks

No data found.

### Water Levels

|         | Normal          | Winter          |
|---------|-----------------|-----------------|
| Minimum | Not established | Not established |
| Normal  | Not established | Not established |
| Maximum | Not established | Not established |

### Construction History

First Dam at Site 1969

| Designer | Construction Firm | Completed (year) |
|----------|-------------------|------------------|
|          |                   | 1969             |

### Outlet Gates

No data found.

### Inspection History

| Inspection Date | Inspection Report Date | Inspection Type                                         |
|-----------------|------------------------|---------------------------------------------------------|
|                 |                        | None                                                    |
| 10/5/2004       | 11/15/2004             | Inspection conducted by DNR under Ch. 31.19(2)decennial |

### Followups

No data found.

### Approvals

No data found.

### Orders

No data found.

### Inspection Schedule

No data found.

### Analysis

No data found.