Detailed Information for Dam County Forest Crop Land 3

Seq No	945	Field File No	09.00
Size	SMALL	NID	1041
Popular Name		Former Name	

Location

County	Chippewa		
Latitude	45.208861	Longitude	-91.229168
Permitted PLSS	NESW3432N07W		

Owners

Type	County	**Name**	Chippewa County

Waterbody

Drainage Basin (sq mi)	0.80		
Stream		**Impoundment**	
Local Name	INTERM TR CRANBERRY CREEK	Local Name	HORSESHOE FLOWAGE
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	6.00
When was navigability determined?		Maximum Depth (ft)	6.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	9.00	Max Storage (acre-ft)	36.00
Structural Height (ft)	7.40	Hydraulic Height (ft)	3.00
Crest Length (ft)	265.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	30.00	Width/Diameter of Principal Spillway (ft)	2.00
Total Discharge Through All Spillways (cfs)	109.00	Total Width/Diameter of All Spillways (ft)	66.00
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Sturcture Purposes	Other - Cranberry, Wetland Restoration, Waste		

Detailed Information for Dam County Forest Crop Land 3

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
		1959

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
		None
7/25/2007		Inspection conducted by DNR under Ch. 31.19(2)decennial

Followups

No data found.

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.