

Detailed Information for No Waterway Horicon Marsh-Redhead

Seq No	981	Field File No	14.00
Size	LARGE	NID	
Popular Name	Wi Dnr	Former Name	

Location

County	Dodge	Longitude	-88.593178
Latitude	43.510288		
Permitted PLSS	NWSE1612N16E		

Owners

Type	State Agency	Name	Wisconsin Department of Natural Resources
------	--------------	------	---

Waterbody

Drainage Basin (sq mi)	0.20		
Stream		Impoundment	
Local Name	E.BRANCH ROCK OFFSTREAM	Local Name	REDHEAD FLOWAGE
Row and Official Name		Row and Official Name	
Navigable?	not determined	Size (acres)	15.00
When was navigability determined?		Maximum Depth (ft)	3.00

Regulation

Regulatory Authority	None	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	15.00	Max Storage (acre-ft)	60.00
Structural Height (ft)	8.00	Hydraulic Height (ft)	8.00
Crest Length (ft)	2,000.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	80.00	Width/Diameter of Principal Spillway (ft)	3.00
Total Discharge Through All Spillways (cfs)	80.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Structure Purposes	Other - Cranberry, Wetland Restoration, Waste		

Detailed Information for No Waterway Horicon Marsh-Redhead

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
		1959

Outlet Gates

No data found.

Inspection History

No data found.

Followups

No data found.

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.