



32
1011

EQUIPMENT RECORDING SONAR MAPPED OCT. 1974
MONTH YEAR
LAKE BOTTOM SYMBOLS

- | | | | |
|-----------------------|-------------------------------|---------------------|-----------------------------|
| TOPOGRAPHIC SYMBOLS | | LAKE BOTTOM SYMBOLS | |
| (B) Brush | () Steep slope | P. Peat | B Boulders |
| (PW) Partially wooded | (---) Indefinite shoreline | Mk. Muck | o Stumps & Snags |
| (W) Wooded | (---) Marsh | C. Clay | ⊗ Rock danger to navigation |
| (C) Cleared | (---) Spring | M. Marl | T Submergent vegetation |
| (P) Pastured | (---) Intermittent stream | Sd. Sand | I Emergent vegetation |
| (A) Agricultural | (---) Permanent inlet | St. Silt | ⊠ Floating vegetation |
| B.M. Bench Mark | (---) Permanent outlet | Gr. Gravel | ⊕ Brush shelters |
| (■) Dwelling | (---) Dam | R. Rubble | |
| (□) Resort | (---) D.N.R. State owned land | Br. Bedrock | |
| (⊠) Camp | | | |



Access Access with Parking Boat Livery
 Drawn by: G. Thuesen
 Field work by: J. Smith, K. Kaplan

SPECIES OF FISH	Abundant		Present
	Common	Present	
Muskie			
N. Pike			
Walleye			X
L.M. Bass	X		
S.M. Bass			
Panfish	X		
Trout			

WATER AREA 177.16 ACRES
 UNDER 3 FT. 6.51 %
 OVER 20 FT. 0 %
 MAX. DEPTH 14 FEET.
 TOTAL ALK. 49 P.P.M.
 VOLUME 1192.21 ACRE FT.
 MAIN SHORELINE 2.22 MI.
 ISLAND SHORELINE 0 MI.

B.M. 1857-A is a railroad spike in an oak tree at a boat landing on the southwest side of Jungle lake. B.M. is 10 feet north of centerline of old roadway, 32 feet west of 4 inch iron pipe, and 24 feet south of Benchmark 1857-B. Assumed elevation= 100.00' Water level= 91.98'

Source: Wisconsin Department of Natural Resources 608-266-2621
Jungle Lake – Forest County, Wisconsin DNR Lake Map
Date – Oct 1974 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.