


LAKE SURVEY MAP


WILLOW RESERVOIR LAKE

COUNTY

SEC. <u>5.6.7.8.17.18</u> T. <u>-37.38</u>-N. R. <u>-4.5</u>-E.\.

(Sheet 3 of 4)





EQ	UIPMENT RE			PPED_	JUNI MONT LAKE	'H - '	1983 YEAR Symbols
B) PW	Brush Pertially woods		Steep slope Indefinite shoreline		Peat Muck	3	Boulders Stumps & Snags
(寒)(∪)(♠)	Wooded Cleared	ر المستقدة حدم	Marsh		Clay Mari		Rock danger to navigation Submergent vegetation
			Intermittent stream		Sand	1	Emergent vegetation
Ā	Agricultural		Permanent inlet		Silt		Floating vegetation
•	Bench Mork Dwelling Resort Comp	\ ± /	Permanent outlet Dam State owned land	R.	Gravel Rubble Bedroc		Brush sheiters

1,000'	1,000	2,000'	3,000	4,000		
SCALE SCALE Access Access with Porking Boat Livery						
Orawn by:	E. Eaton	nn roiking	— BOO 1	L. 4 E: J		

Field work by <u>K.Arnold J.Smith W.Jahns R</u>.Steuck, D. Peterson

PECIES OF	FFISH	
	÷ ;	WATER
	n de n m d	UND
	Com	OVE
uskie	+-+-X	MAX. DEF
Pike	<u> </u>	
<u>lalleye</u>	X	TOTAL A
, M. Boss	[X	VOLUME
.M.Bass	X	VOLUME
anfish	X	MAIN SHO
rout		
		ISLAND S

WATER AREA 6,306,3	_ACRES
UNDER 3 FT. 15	%
OVER 20 FT. 10	
MAX. DEPTH30	FEET.
TOTAL ALK. 25	P. P. M
VOLUME 64,643.6 AC	RE FT.
MAIN SHORELINE 79.17	Mi.
ISLAND SHORELINE 19.27	Mi.

B.M. Bench Mork

Dwelling

Résort

📵 Comp

Permanent outlet

D.N.R. State owned land

∖ Dam

Gr. Gravel

R. Rubble

Br. Bedrock

😛 Brush shelters

<u>WILLOW RESERVOIR</u> LAKE

ONEIDA COUNTY

P. P. M

VOLUME 64,643.6 ACRE FT.

MAIN SHORELINE 79.17 MI.


ISLAND SHORELINE 19.27 MI

Trout

SEC. 3,4,9,10,15,16,22 T. - 37- N. R. - 5- E. (Sheet 4 of 4)

Access with Parking Boat Livery

Field work by <u>K.Arnold, J.Smith, W.Jahns</u>, R.Steuck, D.Peterson



Access

Drawn by: <u>E_Eaton</u>

Source: Wisconsin Department of Natural Resources 608-266-2621 Willow Reservoir – Oneida County, Wisconsin - DNR Lake Map Date – Jun 1983 - Historical Lake Map - Not for Navigation A Public Document - Please Identify the Source when using it.