



Silver Lake - Vilas County

July 26, 2010



Eurasian Water Milfoil

Rake Fullness Rating









-  Visual
-  1
-  2
-  3
-  Not Sampled
-  NO EWM

Illustration of Rake Fullness Rating



<http://dnr.wi.gov>