→ Dist. Director - Rhinelander 04-72-037920

DEPARTMENT OF NATURAL RESOURCES

JKR

TOXIC AND HAZARDOUS INCIDENT REPORT FORM

FORM 3200—49 11-78

DATE OF INCIDENT (Y/M/D)	TIME OF INCIDENT (24 HR)	DATE INCIDENT REPORTED	TIME INCIDENT REPORTED
80-3-5	1500-1600	80-3-6	1445

INCIDENT REPORTED BY (NAME)	AGENCY OR FIRM	TELEPHONE NUMBER
Diane Kobler	Emerg. Gov.	608 1264-3232

SUBSTANCE OR TRADE NAME OF MATERIAL(S) INVOLVED: Formaldehyde

QUANTITY LOST	UNITS	COUNTY OF INCIDENT LOCATION
445 gal		Wood

EXACT LOCATION DESCRIPTION (HIGHWAY INTERSECTION, MILEAGE, ETC.): 700 Dura Beauty Lane

CAUSE OF INCIDENT

☐ TRANSPORTATION RELATED

☐ FACILITY RELATED

Unloading truck it coupling broke

PERSON OR FIRM RESPONSIBLE FOR INCIDENT		TELEPHONE NUMBER
Consoweld Corp.		715 1422- 3693

P.O. BOX, STREET OR ROUTE	CITY	STATE	ZIP CODE
700 Dura Beauty Lane	Wis. Rapids	Wis	

INCIDENT INVESTIGATED BY	AGENCY TELEPHONE NUMBER	DATE INCIDENT INVESTIGATED	TIME INCIDENT INVESTIGATED
	/ –		

DNR DISTRICT	DNR AREA	TOWN, RANGE, SECTION, ¼, ¼¼ SECTION	SURFACE WATERS AFFECTED	GROUND WATERS AFFECTED
NC	Wis. Rapids	T ___N, R___, ___, ___, ___	☐ YES ☐ NO ☐ POTENTIAL	☐ YES ☐ NO ☐ POTENTIAL

DISTANCE TO NEAREST WELL	DISTANCE TO NEAREST SURFACE WATERS	NAME OF SURFACE WATER AFFECTED	DRAINAGE BASIN
FT.	FT.		

LIST HAZARDS, INJURIES OR DEATHS TO HUMANS	LIST HAZARDS TO VEGETATION, FISH, BIRDS OR WILDLIFE

ACTION TAKEN BY DNR:
- ☐ No Action Taken
- ☐ Investigation
- ☐ Containment
- ☐ Supervise Cleanup
- ☐ Cleanup
- ☐ Disposal
- ☐ Enforcement
- ☐ Spiller Required to Take Action
- ☐ Contractor Hired by DNR
- ☐ Spiller Billed for Expenses

ACTION TAKEN BY SPILLER:
- ☐ No Action Taken
- ☐ No Notification Made
- ☒ Delayed Notification
- ☐ Containment
- ☐ Supervise Cleanup
- ☐ Cleanup
- ☐ Disposal
- ☐ Contractor Hired by Spiller
- ☒ Other Action Flushed & soaked in.
- ☐ Yes ☐ No ☐ N/A SPCC Plan

ADDITIONAL REMARKS TO BE COMPUTER STORED:

OK to close. 10/24/19 MK

ADDITIONAL REMARKS NOT TO BE COMPUTER STORED:

Reported to Russel De Brock at DNR-Rhinelander on 3-7-80 at 1450 by
Called Albers at Rapids -
Called Cem-Tran

Harley J Lichtenwalner

RECEIVED
Wis. Dept. of Natural Resources
MAR 10 1980
N. C. Dist. Hdqtrs.
RHINELANDER, WIS.

04-72-037920 700 DURA BEAUTY LN [HISTORIC SPILL]

Location Name: NEW PAGE SUPPORT SERVICES
Activity Start Date: 1980-03-05
Activity End Date:

Address: 700 DURA BEAUTY LN
Activity Type: SPILL

Muni: WISCONSIN RAPIDS **Zip:** 54495
File Location:

Region: WC **Region of Management:** WC
DSPS No:

County: Wood
DATCP Case No:
DATCP Spill No:

FID: 772009590 **EPA Cerclis ID:**
Acres: ☐ Right-of-Way ☐ Acres > 100

Activity Address:

PLSS: ? 1/4 of the ? 1/4 of Sec ?, T?N, R??
Latitude:
Longitude:

Location Comment: NON GEN FOR 2010 ONLY PER EXEMPTION FORM & MANIFEST CHECK - SLB; NON GEN FOR 2009 ONLY PER EXEMPTION FORM & MANIFEST CHECK - SLB; SITE ID FORM REC'D 3/3/08; NEW OWNER - NEWPAGE WISCONSIN SYSTEM INC AS OF 1/1/2008 - SLB: FKA: STORA ENSO NW SUPPORT SERVICES; PER 2004 ANNUAL REPORT WAS NON GEN IN 2004 - EXEMPT THIS YEAR ONLY WAS CHECKED SO LEFT STATUS AS SQG - SLB; FKA: CONSOLIDATED PAPERS INC; SQG PER NEW NOTIF FORM SUBMITTED 4/93; FKA: STERLING

Activity Comment: OLD SPILL ID: 800305-04 HISTORIC SPILL. FURTHER ACTION MAY NOT BE NECESSARY. PLEASE CONTACT DNR SPILL COORDINATOR IN WC REGION FOR FILE INFORMATION.

☐ Transferred to DSPS ☐ Transferred to DATCP ☐ Transferred to WMM ☐ Tracked by DSPS ☐ Created by DSPS
☐ PECFA Eligible ☐ PECFA 80K ☐ PECFA 80K Failure ☐ Above Ground Storage Tank ☐ Co-Contamination
☐ VPLE at Location ☐ VPLE Inactive ☐ General Property at Location ☐ Drycleaner ☐ Superfund ☐ Superfund NPL
☐ Status Unclear (Mask BOTW) ☐ Geo-Located ☐ On GIS Registry

Other Activities at this Location

Activity Detail No	Type	Activity Detail Name	Start Date	End Date
04-72-050204	SPILL	700 DURA BEAUTY LN [HISTORIC SPILL]	1994-12-20	
04-72-543394	SPILL	CONSOLIDATED PAPERS INC	1999-03-22	1999-03-26
04-72-551162	SPILL	NEW PAGE SPILL	2008-03-13	2008-03-26

Actions

Action Date	Code	Action Name / Comment	Audit
1980-03-05	777	Historic Spill	Added 06/23/2004 by S71584
1980-03-05	5	Spill Reported to DNR	Added 09/14/2006 by S71584
1980-03-05	1	Spill Incident Occurred Auto populated via migration process	Added 05/30/1997 by S71584

Documents

Energy Act Details

Impacts

Soil Contamination Added 05/30/1997 by S71584
SOIL

Priority

Risk

Substances

Spill Details

04-72-037920 700 DURA BEAUTY LN [HISTORIC SPILL]

Incident Time: 03/05/1980 00:00:00 **Reported Time:** Added 05/30/1997 by S71584

Spill Cause: BROKEN COUPLING

Substance Color:

Substance Odor:

Spill Source: Industrial Facility (Foundry/Factory/Plating/Manufacl

Source Comment:

☐ Resource Damages?

☐ Notify Immediate?

DNR Investigator: LICHTENWULNER

Physical Char:

Comment:

Spill Substance

Who

Former Project Manager is JOHN GRUMP

Title: HYDROGEOLOGIST SPILLS COORDINATOR
Address: 1300 W CLAIREMONT AVE
EAU CLAIRE WI 54702-4001
Phone: (735) 839-3775
Fax: (715) 839-6076
E-Mail: john.grump@wisconsin.gov

Project Manager is THOMAS KENDZIERSKI

Title: HYDROGEOLOGIST
Address: 1300 W CLAIREMONT AVE
PO BOX 4001
EAU CLAIRE WI 54702-4001
Phone: (715) 839-1604
Fax: (715) 839-6076
E-Mail: thomas.kendzierski@wisconsin.gov

CASE NAME: CONSOWELD CORP.
COUNTY: WOOD
LOCATION: SE,NE,07,T22N,R06E

CONTACT NAME:
ADDRESS: 700 DURA BEAUTY LAND
WIS RAPIDS, WI 54494
PHONE: 715-422-3693

STATUS
CASE # 427
PMN #
LUST NO
ACTIVE/INACTIVE: INA
DATE OF INCIDENT: 800305
DATE OF REPORT: 800305
DATE FILE UPDATED: 0

SUBSTANCE: FORMALDEHYDE
QUANTITY: 445 GALLONS
CAUSE: COUPLING BROKE WHILE UNLOADING TRUCK

ACTION BY SPILLER: FLUSHED AND SOAKED IN
ACTION BY DNR:
FIRST RESPONDER: TELEPHONE:
PROJECT LEADER: TELEPHONE:

GROUNDWATER AFFECTED:
SURFACE WATER AFFECTED:
NAME OF SURFACE WATER:

COUPLING BROKE WHILE UNLOADING TRUCK. MATERIAL WAS FLUSHED AND SOAKED IN.

==========