FID # 268013130
ERR/ERP

MagneTek

May 9, 1995

Ms. Margaret M. Graefe
Environmental Repair Section
Wisconsin Dept. Of Natural Resources
2300 N. Martin Luther King, Jr. Drive
Milwaukee, WI 53212

Dear Ms. Graefe:

During a routine due diligence investigation for a corporate transaction, another party's consultant, Golder Associates, has reported indications of several chlorinated compounds in groundwater moving under a portion of our property at 400 S. Prairie Avenue in Waukesha. I am enclosing the data as reported by Golder. I understand that Golder collected water samples primarily at a depth of approximately 15 feet using a geoprobe. I would emphasize that Golder was not acting under the direction of MagneTek, and MagneTek makes no representations concerning the validity of the reported data.

Golder Associates found no evidence that our facility is a source of chlorinated compounds and the compounds reportedly were found at the southern-southeastern boundary of our property, which is distinctly upgradient of our facility. Accordingly, the source of the detected compounds appears to be offsite to the south or southeast. If you are aware of a source of chlorinated compounds in the area upgradient of our facility, we would appreciate receiving information concerning such source.

Please contact me if you have any questions.

Sincerely,

N. Aversa
Senior Vice President
& General Manager

NA/jl
Enclosures

cc: Dennis Hatfield
John Hahn
Al Swenton
Steve Howarth

400 S. Prairie Avenue • Waukesha, WI 53186-5937
(414) 547–0121 • FAX (414) 521–0196 [–0190(Purchasing) –0198(Transformers)]



MagneTek Electric, Inc.
400 S. Prairie Avenue
Waukesha, WI 53186

Golder Associates Chicago, Illinois	TITLE: TETRACHLOROETHENE DETECTIONS IN GROUNDWATER (UG/L)		
CLIENT/PROJECT: GENERAL SIGNAL/PHASE II/WI	DRAWN: DMC	DATE: 4-24-95	JOB NO. 953-8227
	CHECKED:	SCALE: AS SHOWN	DWG NO.
	REVIEWED:	FILE NAME: GW_PCE.SRF	FIGURE NO. 3



MagneTek Electric, Inc.
400 S. Prairie Avenue
Waukesha, WI 53186

Golder Associates Chicago, Illinois	TITLE: TRICHLOROETHENE DETECTIONS IN GROUNDWATER (UG/L)		
CLIENT/PROJECT: GENERAL SIGNAL/PHASE II/WI	DRAWN: DMC	DATE: 4-24-95	JOB NO. 953-8227
	CHECKED:	SCALE: AS SHOWN	DWG NO.
	REVIEWED:	FILE NAME: GW_TCE.SRF	FIGURE NO. 4



MagneTek Electric, Inc.
400 S. Prairie Avenue
Waukesha, WI 53186

Golder Associates Chicago, Illinois

TITLE: CIS 1,2-DICHLOROETHENE DETECTIONS IN GROUNDWATER (UG/L)

CLIENT/PROJECT: GENERAL SIGNAL/PHASE II/WI

DRAWN	DMC	DATE	4-24-95	JOB NO.	953-8227
CHECKED		SCALE	AS SHOWN	DWG NO.	
REVIEWED		FILE NAME	GW_CIS.SRF	FIGURE NO.	5