A Copy of The Field Log
Sent To Dom Tor.
on 11/07/08

SITE INSPECTION REPORT

Site Name: PE Fire Dept site	Co. Wood	No. 03-72-000906
St. Address:	Mun.: Port Edwards	1/4 1/4,Sec. ,T ,R
Date: 10/03/08 Time: 10:30	Weather: Clear, 55°F	
Purpose of Visit: Inspect repairs to cap		
Persons Contacted: Dave Ulrich	Phone Nos.:	
Photos: 2 photos of cap	Sketch:	
Summary:		

- The cracks in the concrete cap were filled with tar
- Dave told me, during a phone conversation with him earlier today, that they are meeting with their consultant, STS, to determine what to do with the remaining monitoring wells

Signature: Tom Kim

Follow Up:

2
3
4
5
6
7
8
9
10
11
12
13
14
15