State of Wisconsin
Department of Natural Resources

04-05-047199

BRRTS Duplicate

State Div. Emergency Gov't. (608) 266-3232
U.S. Nat'l. Response Center (800) 424-8802
Chemtrec/Pesticides/Chlorine (800) 424-9300

TOXIC AND HAZARDOUS SPILL REPORT

Form 4400-91 Rev. 6-86

Spill ID Number 92052808
Y Y M M D D 0-99

04-05-047199

Date of Incident	Day of Week	Time of Incident		Reported By (Name)	Telephone Number
5-28-92	Thurs.	3:00	☐ A.M. ☒ P.M.	Jim Forst	(414) 494-5233
Date Reported	**Day of Week**	**Time Reported**		**Agency or Firm Reporting**	**Reported thru Div. Emergen. Gov't.**
5-29-92	Fri.	1:25	☐ A.M. ☒ P.M.	ANAMAX	☐ Yes ☒ No

Substance Involved	Quantity	Units	Person or Firm Responsible
Diesel Fuel	est. 10-20	gal.	ANAMAX
Substance Involved	**Quantity**	**Units**	**Contact Name / Telephone Number**
			Jim Forst (414) 494-5233

Physical Characteristics

☐ Solid ☒ Liquid Color _____
☐ Semisolid ☐ Gas Odor _____

Address — Street or Route: 2099 Shawano Ave.
City, State, Zip Code: Green Bay, WI 54303

Cause of Incident
Unknown

Exact Location Description (intersection, mileage, etc.) Green Bay NE of truck garage at 2099 Shawano Ave.

County Location	¼¼, ¼, Section, Town, Range
Brown	__ __, __ __, __ __, T__ __ N, R__ __ __

DNR Dist	DNR Area	Groundwaters Affected
LMD	GBA	☐ Yes ☐ No ☒ Potential

Surface Waters Affected	Name of Surface Water
☐ Yes ☐ No ☐ Potential	

Date District Notified	Day of Week	Time District Notified
		☐ A.M. ☐ P.M.

District Person Notified	Telephone Number
	( )

Date Investigated	Day of Week	Time Investigated		Person Investigating	Telephone Number
5-29-92	Fri.	3:22	☐ A.M. ☒ P.M.	Thomas R. Hansen	(414) 448-5132

Action Taken By DNR

☐ No Action Taken ☒ Investigation ☐ Supervise/Conduct Cleanup
☐ Spiller Required To Take Action; Type _____
☐ Contractor Hired By DNR; Name _____
☐ Amount Recovered _____
☐ 29.29 Enforcement

Other Agencies on Scene

Local _____
State _____
Federal _____

Action Taken By Spiller

☐ No Action Taken ☐ No Notification ☐ Investigate
☐ Containment; Type _____
☒ Cleanup; Method Excavated soil
☒ Amount Recovered Estimated 95%
☐ Monitor _____
☐ Contractor Hired; Name _____
☐ Other Action _____

Spill Location

☐ Industrial Facility/Paper Mill/Chem. Co.
☐ Gas/Service Station/Garage, Auto Dealer, Repair Shop
☐ Ag Coop/Facility/Cheese Factory/Creamery
☒ Other Small Business (bank, grocery, insurance co., etc.)
☐ Public Property (city, county, state, church, school, etc.)
☐ Utility Co., Power Generating/Transfer Facility
☐ Private Property (home/farm)
☐ Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler
☐ Transportation Accident, Fuel Supply Tank Spill
☐ Transportation Accident, Load Spill
☐ Construction, Excavation, Wrecking, Quarry, Mine
☐ Other _____

Spilled Substance Destination

☐ Air
☐ Soil
☐ Groundwater
☐ Surface Water
☐ Storm Sewer
☐ Sanitary Sewer
☐ Contained/Recovered
☒ Other Soil to landfill

Person Filing This Report (print name): Thomas R. Hansen

Signature: Thomas R Hansen Date Signed: 7/6/92

Additional Comments:

6-1-92 Forst called to advise that contaminated soil had been dug out and placed on tarps. Piles will be covered until test results are back. JAVCO has pumped about 150 gal. of water and scum from storm sewer baffle system.

7-2-92 Warden T. Hansen inspected area and approved filling in hole. Contaminated material was piled on plastic awaiting disposal approval.

CLOSED 7-6-92

CENTRAL OFFICE COORDINATOR

RNC 11-5-09