Hanson, David L - DNR

From: Christy Rosenberger <christy.rosenberger@gza.com>
Sent: Thursday, June 22, 2023 2:06 PM
To: Hanson, David L - DNR; Martinez, Joseph J - DNR
Cc: Heidi Woelfel; John Osborne
Subject: Building 2 - FW: Proj. Name: Bayshore B2, Project ID: 27670, Project #: 20.0150985.27, Final Report: WO# 2306407, Eurofins Air Toxics, LLC
Attachments: 2306407_d.pdf; 2306407COC.pdf; ATLSTDEDD_2306407.xls

CAUTION: This email originated from outside the organization.
Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good afternoon-

Attached, on behalf of Heidi, is the Building 2 sub-slab lab report.

Thank you-
Christy

****

Christy Rosenberger
Lead Word Processor

GZA | 17975 West Sarah Lane, Suite 100 | Brookfield, WI 53045
o: 262.754.2575 | c: 262-395-6670 | general: 262.754.2560 | christy.rosenberger@gza.com | www.gza.com

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

From: Heidi Woelfel <Heidi.Woelfel@gza.com>
Sent: Thursday, June 22, 2023 1:51 PM
To: John Osborne <John.Osborne@gza.com>; Christy Rosenberger <christy.rosenberger@gza.com>
Subject: Fwd: Proj. Name: Bayshore B2, Project ID: 27670, Project #: 20.0150985.27, Final Report: WO# 2306407, Eurofins Air Toxics, LLC

Get Outlook for iOS

From: Jade.White@et.eurofinsus.com <Jade.White@et.eurofinsus.com>
Sent: Thursday, June 22, 2023 12:38:05 PM
To: Heidi Woelfel <Heidi.Woelfel@gza.com>
Subject: [EXTERNAL] Proj. Name: Bayshore B2, Project ID: 27670, Project #: 20.0150985.27, Final Report: WO# 2306407, Eurofins Air Toxics, LLC

Proj. Name: Bayshore B2, Project ID: 27670, Project #: 20.0150985.27, Final Report: WO# 2306407, Eurofins Air Toxics, LLC

Dear Ms. Heidi Woelfel ,

Thank you for choosing Eurofins Air Toxics, LLC to provide your analytical services.

Your final report information appears below.

Project Name: Bayshore B2
Date Received: 6/14/2023
Date Promised: 6/21/2023

Sample Listing

Sample	Analysis	Collection Date	Pressure
SS-1	TO-15	6/7/2023	8.6 "Hg
SS-2	TO-15	6/7/2023	6.9 "Hg
SS-3	TO-15	6/7/2023	6.9 "Hg
SS-4	TO-15	6/7/2023	6.5 "Hg
SS-5	TO-15	6/7/2023	1 "Hg
SS-6	TO-15	6/7/2023	7.6 "Hg
OAS-1	TO-15	6/7/2023	1 "Hg

Attached to this email are your Final Report and Chain of Custody. These documents are provided in Adobe PDF Format for your convenience. Additionally, we are pleased to provide the data as an EXCEL Report for your added convenience.

If you are expecting a Client Specific Electronic Data Deliverable (EDD) or Data Validation Package (eCVP), you will receive a separate notification when it is complete.

If you have any questions or concerns please contact me at your earliest convenience. My goal is to ensure that your project expectations are met with early and prompt resolution.

Your Final Report and EXCEL Report (as well as all project related documents) can also be accessed at https://airtoxics.eurofins.com. Please contact me if you eed assistance accessing this service.

Thank you for your continued business.

Sincerely,

Jade White

Project Manager
Eurofins Air Toxics, LLC
180 Blue Ravine Road, Ste. B
Folsom, CA 95630

916-985-1000
Jade.White@et.eurofinsus.com
www.airtoxics.com

KAK

This electronic message is intended to be viewed only by the individual or entity to which it is addressed and may contain privileged and/or confidential information intended for the exclusive use of the addressee(s). If you are not the intended recipient, please be aware that any disclosure, printing, copying, distribution or use of this information is prohibited. If you have received this message in error, please notify the sender immediately and destroy this message and its attachments from your system.

For information about GZA GeoEnvironmental, Inc. and its services, please visit our website at www.gza.com.

eurofins | Air Toxics

6/22/2023
Ms. Heidi Woelfel
GZA GeoEnvironmental, Inc.
17975 West Sarah Lane
Suite 150
Brookfield WI 53045

Project Name: Bayshore B2
Project #: 20.0150985.27
Workorder #: 2306407

Dear Ms. Heidi Woelfel

The following report includes the data for the above referenced project for sample(s) received on 6/14/2023 at Eurofins Air Toxics LLC.

The data and associated QC analyzed by TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Eurofins Air Toxics LLC. for your air analysis needs. Eurofins Air Toxics Inc. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Jade White at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Jade White

Project Manager

eurofins | Air Toxics

WORK ORDER #: 2306407

Work Order Summary

CLIENT:	Ms. Heidi Woelfel GZA GeoEnvironmental, Inc. 17975 West Sarah Lane Suite 150 Brookfield, WI 53045	**BILL TO:**	Accounts Payable-Waukesha GZA GeoEnvironmental, Inc. 20900 Swenson Drive Suite 150 Waukesha, WI 53186
PHONE:	262-754-2560	**P.O. #**	
FAX:	262754-9711	**PROJECT #**	20.0150985.27 Bayshore B2
DATE RECEIVED:	06/14/2023	**CONTACT:**	Jade White
DATE COMPLETED:	06/22/2023		

FRACTION #	NAME	TEST	RECEIPT VAC./PRES.	FINAL PRESSURE
01A	SS-1	TO-15	8.6 "Hg	1.9 psi
02A	SS-2	TO-15	6.9 "Hg	1.9 psi
03A	SS-3	TO-15	6.9 "Hg	1.9 psi
04A	SS-4	TO-15	6.5 "Hg	1.9 psi
05A	SS-5	TO-15	1 "Hg	1.9 psi
06A	SS-6	TO-15	7.6 "Hg	1.8 psi
07A	OAS-1	TO-15	1 "Hg	1.9 psi
08A	Lab Blank	TO-15	NA	NA
09A	CCV	TO-15	NA	NA
10A	LCS	TO-15	NA	NA
10AA	LCSD	TO-15	NA	NA

CERTIFIED BY: Heidi Hayes DATE: 06/22/23

Technical Director

Certification numbers: AZ Licensure AZ0775, FL NELAP – E87680, LA NELAP – 02089, NH NELAP – 209222, NJ NELAP - CA016, NY NELAP - 11291, TX NELAP – T104704434-22-18, UT NELAP – CA009332022-14, VA NELAP - 12240, WA ELAP - C935
Name of Accreditation Body: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program) CA300005-017
Eurofins Environment Testing Northern California, LLC certifies that the test results contained in this report meet all requirements of the 2016 TNI Standard.

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, LLC.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 95630
(916) 985-1000 . (800) 985-5955 . FAX (916) 351-8279

LABORATORY NARRATIVE
EPA Method TO-15
GZA GeoEnvironmental, Inc.
Workorder# 2306407

Seven 6 Liter Summa Canister samples were received on June 14, 2023. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

Receiving Notes

The Chain of Custody was missing method information. EATL proceeded with the analysis as per the original contract or verbal agreement.

The Chain of Custody (COC) was not relinquished properly. A signature with date and time was not provided by the field sampler.

The Chain of Custody (COC) information for sample SS-6 and OAS-1 did not match the information on the canister with regard to canister identification. The samples labeled 6L1625 and 611995 on the COC are labeled as 1625 and 6L1995 on the canister. The client was notified of the discrepancy and the information on the canister was used to process and report the samples.

There was a difference (greater than or equal to 5.0" Hg) between the measured canister receipt vacuum and that which was reported on the Chain of Custody (COC) for sample OAS-1. A leak test indicated that the valve was functioning properly.

Analytical Notes

Dilution was performed on samples SS-1, SS-3, SS-4 and SS-6 due to the presence of high level non-target species.

Definition of Data Qualifying Flags

Ten qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.

Q - Exceeds quality control limits.

U - Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.

UJ- Non-detected compound associated with low bias in the CCV

N - The identification is based on presumptive evidence.

M - Reported value may be biased due to apparent matrix interferences.

CN - See Case Narrative.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified

b-File was quantified by a second column and detector

r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

Summary of Detected Compounds
EPA METHOD TO-15 GC/MS FULL SCAN

Client Sample ID: SS-1

Lab ID#: 2306407-01A

No Detections Were Found.

Client Sample ID: SS-2

Lab ID#: 2306407-02A

No Detections Were Found.

Client Sample ID: SS-3

Lab ID#: 2306407-03A

No Detections Were Found.

Client Sample ID: SS-4

Lab ID#: 2306407-04A

No Detections Were Found.

Client Sample ID: SS-5

Lab ID#: 2306407-05A

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Trichloroethene	0.58	1.1	3.1	5.9

Client Sample ID: SS-6

Lab ID#: 2306407-06A

No Detections Were Found.

Client Sample ID: OAS-1

Lab ID#: 2306407-07A

No Detections Were Found.

eurofins | Air Toxics

Client Sample ID: SS-1

Lab ID#: 2306407-01A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062114**	**Date of Collection: 6/7/23 9:44:00 AM**	
Dil. Factor:	**31.7**	**Date of Analysis: 6/21/23 07:09 PM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	16	Not Detected	40	Not Detected
1,1-Dichloroethene	16	Not Detected	63	Not Detected
trans-1,2-Dichloroethene	16	Not Detected	63	Not Detected
1,1-Dichloroethane	16	Not Detected	64	Not Detected
cis-1,2-Dichloroethene	16	Not Detected	63	Not Detected
1,1,1-Trichloroethane	16	Not Detected	86	Not Detected
1,2-Dichloroethane	16	Not Detected	64	Not Detected
Trichloroethene	16	Not Detected	85	Not Detected
1,1,2-Trichloroethane	16	Not Detected	86	Not Detected
Tetrachloroethene	16	Not Detected	110	Not Detected
1,1,2,2-Tetrachloroethane	16	Not Detected	110	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	106	70-130
1,2-Dichloroethane-d4	110	70-130
4-Bromofluorobenzene	114	70-130

eurofins | Air Toxics

Client Sample ID: SS-2

Lab ID#: 2306407-02A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062111**	**Date of Collection:**	**6/7/23 10:10:00 AM**
Dil. Factor:	**1.47**	**Date of Analysis:**	**6/21/23 05:49 PM**

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.74	Not Detected	1.9	Not Detected
1,1-Dichloroethene	0.74	Not Detected	2.9	Not Detected
trans-1,2-Dichloroethene	0.74	Not Detected	2.9	Not Detected
1,1-Dichloroethane	0.74	Not Detected	3.0	Not Detected
cis-1,2-Dichloroethene	0.74	Not Detected	2.9	Not Detected
1,1,1-Trichloroethane	0.74	Not Detected	4.0	Not Detected
1,2-Dichloroethane	0.74	Not Detected	3.0	Not Detected
Trichloroethene	0.74	Not Detected	4.0	Not Detected
1,1,2-Trichloroethane	0.74	Not Detected	4.0	Not Detected
Tetrachloroethene	0.74	Not Detected	5.0	Not Detected
1,1,2,2-Tetrachloroethane	0.74	Not Detected	5.0	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	101	70-130
1,2-Dichloroethane-d4	112	70-130
4-Bromofluorobenzene	115	70-130

eurofins | Air Toxics

Client Sample ID: SS-3

Lab ID#: 2306407-03A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062112**	**Date of Collection: 6/7/23 10:27:00 AM**	
Dil. Factor:	**5.87**	**Date of Analysis: 6/21/23 06:16 PM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	2.9	Not Detected	7.5	Not Detected
1,1-Dichloroethene	2.9	Not Detected	12	Not Detected
trans-1,2-Dichloroethene	2.9	Not Detected	12	Not Detected
1,1-Dichloroethane	2.9	Not Detected	12	Not Detected
cis-1,2-Dichloroethene	2.9	Not Detected	12	Not Detected
1,1,1-Trichloroethane	2.9	Not Detected	16	Not Detected
1,2-Dichloroethane	2.9	Not Detected	12	Not Detected
Trichloroethene	2.9	Not Detected	16	Not Detected
1,1,2-Trichloroethane	2.9	Not Detected	16	Not Detected
Tetrachloroethene	2.9	Not Detected	20	Not Detected
1,1,2,2-Tetrachloroethane	2.9	Not Detected	20	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	103	70-130
1,2-Dichloroethane-d4	111	70-130
4-Bromofluorobenzene	116	70-130

eurofins | Air Toxics

Client Sample ID: SS-4

Lab ID#: 2306407-04A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062113**	**Date of Collection: 6/7/23 10:49:00 AM**	
Dil. Factor:	**14.4**	**Date of Analysis: 6/21/23 06:42 PM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	7.2	Not Detected	18	Not Detected
1,1-Dichloroethene	7.2	Not Detected	28	Not Detected
trans-1,2-Dichloroethene	7.2	Not Detected	28	Not Detected
1,1-Dichloroethane	7.2	Not Detected	29	Not Detected
cis-1,2-Dichloroethene	7.2	Not Detected	28	Not Detected
1,1,1-Trichloroethane	7.2	Not Detected	39	Not Detected
1,2-Dichloroethane	7.2	Not Detected	29	Not Detected
Trichloroethene	7.2	Not Detected	39	Not Detected
1,1,2-Trichloroethane	7.2	Not Detected	39	Not Detected
Tetrachloroethene	7.2	Not Detected	49	Not Detected
1,1,2,2-Tetrachloroethane	7.2	Not Detected	49	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	105	70-130
1,2-Dichloroethane-d4	111	70-130
4-Bromofluorobenzene	112	70-130

eurofins | Air Toxics

Client Sample ID: SS-5

Lab ID#: 2306407-05A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062126**	**Date of Collection: 6/7/23 11:05:00 AM**	
Dil. Factor:	**1.17**	**Date of Analysis: 6/22/23 01:53 AM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.58	Not Detected	1.5	Not Detected
1,1-Dichloroethene	0.58	Not Detected	2.3	Not Detected
trans-1,2-Dichloroethene	0.58	Not Detected	2.3	Not Detected
1,1-Dichloroethane	0.58	Not Detected	2.4	Not Detected
cis-1,2-Dichloroethene	0.58	Not Detected	2.3	Not Detected
1,1,1-Trichloroethane	0.58	Not Detected	3.2	Not Detected
1,2-Dichloroethane	0.58	Not Detected	2.4	Not Detected
Trichloroethene	0.58	1.1	3.1	5.9
1,1,2-Trichloroethane	0.58	Not Detected	3.2	Not Detected
Tetrachloroethene	0.58	Not Detected	4.0	Not Detected
1,1,2,2-Tetrachloroethane	0.58	Not Detected	4.0	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	101	70-130
1,2-Dichloroethane-d4	111	70-130
4-Bromofluorobenzene	98	70-130

eurofins | Air Toxics

Client Sample ID: SS-6

Lab ID#: 2306407-06A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062127**	**Date of Collection: 6/7/23 11:20:00 AM**	
Dil. Factor:	**30.1**	**Date of Analysis: 6/22/23 02:19 AM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	15	Not Detected	38	Not Detected
1,1-Dichloroethene	15	Not Detected	60	Not Detected
trans-1,2-Dichloroethene	15	Not Detected	60	Not Detected
1,1-Dichloroethane	15	Not Detected	61	Not Detected
cis-1,2-Dichloroethene	15	Not Detected	60	Not Detected
1,1,1-Trichloroethane	15	Not Detected	82	Not Detected
1,2-Dichloroethane	15	Not Detected	61	Not Detected
Trichloroethene	15	Not Detected	81	Not Detected
1,1,2-Trichloroethane	15	Not Detected	82	Not Detected
Tetrachloroethene	15	Not Detected	100	Not Detected
1,1,2,2-Tetrachloroethane	15	Not Detected	100	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	105	70-130
1,2-Dichloroethane-d4	106	70-130
4-Bromofluorobenzene	113	70-130

eurofins | Air Toxics

Client Sample ID: OAS-1

Lab ID#: 2306407-07A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062110**	**Date of Collection:**	**6/7/23 12:04:00 PM**
Dil. Factor:	**1.17**	**Date of Analysis:**	**6/21/23 05:23 PM**

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.58	Not Detected	1.5	Not Detected
1,1-Dichloroethene	0.58	Not Detected	2.3	Not Detected
trans-1,2-Dichloroethene	0.58	Not Detected	2.3	Not Detected
1,1-Dichloroethane	0.58	Not Detected	2.4	Not Detected
cis-1,2-Dichloroethene	0.58	Not Detected	2.3	Not Detected
1,1,1-Trichloroethane	0.58	Not Detected	3.2	Not Detected
1,2-Dichloroethane	0.58	Not Detected	2.4	Not Detected
Trichloroethene	0.58	Not Detected	3.1	Not Detected
1,1,2-Trichloroethane	0.58	Not Detected	3.2	Not Detected
Tetrachloroethene	0.58	Not Detected	4.0	Not Detected
1,1,2,2-Tetrachloroethane	0.58	Not Detected	4.0	Not Detected

Container Type: 6 Liter Summa Canister

Surrogates	%Recovery	Method Limits
Toluene-d8	101	70-130
1,2-Dichloroethane-d4	110	70-130
4-Bromofluorobenzene	115	70-130

eurofins | Air Toxics

Client Sample ID: Lab Blank

Lab ID#: 2306407-08A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062106d**	**Date of Collection: NA**	
Dil. Factor:	**1.00**	**Date of Analysis: 6/21/23 01:50 PM**	

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.50	Not Detected	1.3	Not Detected
1,1-Dichloroethene	0.50	Not Detected	2.0	Not Detected
trans-1,2-Dichloroethene	0.50	Not Detected	2.0	Not Detected
1,1-Dichloroethane	0.50	Not Detected	2.0	Not Detected
cis-1,2-Dichloroethene	0.50	Not Detected	2.0	Not Detected
1,1,1-Trichloroethane	0.50	Not Detected	2.7	Not Detected
1,2-Dichloroethane	0.50	Not Detected	2.0	Not Detected
Trichloroethene	0.50	Not Detected	2.7	Not Detected
1,1,2-Trichloroethane	0.50	Not Detected	2.7	Not Detected
Tetrachloroethene	0.50	Not Detected	3.4	Not Detected
1,1,2,2-Tetrachloroethane	0.50	Not Detected	3.4	Not Detected

Container Type: NA - Not Applicable

Surrogates	%Recovery	Method Limits
Toluene-d8	100	70-130
1,2-Dichloroethane-d4	109	70-130
4-Bromofluorobenzene	117	70-130

eurofins | Air Toxics

Client Sample ID: CCV

Lab ID#: 2306407-09A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062103**	**Date of Collection: NA**	
Dil. Factor:	**1.00**	**Date of Analysis: 6/21/23 12:07 PM**	

Compound	%Recovery
Vinyl Chloride	111
1,1-Dichloroethene	106
trans-1,2-Dichloroethene	99
1,1-Dichloroethane	90
cis-1,2-Dichloroethene	86
1,1,1-Trichloroethane	84
1,2-Dichloroethane	86
Trichloroethene	87
1,1,2-Trichloroethane	84
Tetrachloroethene	104
1,1,2,2-Tetrachloroethane	82

Container Type: NA - Not Applicable

Surrogates	%Recovery	Method Limits
Toluene-d8	104	70-130
1,2-Dichloroethane-d4	93	70-130
4-Bromofluorobenzene	114	70-130

eurofins | Air Toxics

Client Sample ID: LCS

Lab ID#: 2306407-10A

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062104**	**Date of Collection: NA**	
Dil. Factor:	**1.00**	**Date of Analysis: 6/21/23 12:33 PM**	

Compound	%Recovery	Method Limits
Vinyl Chloride	113	70-130
1,1-Dichloroethene	103	70-130
trans-1,2-Dichloroethene	100	70-130
1,1-Dichloroethane	91	70-130
cis-1,2-Dichloroethene	90	70-130
1,1,1-Trichloroethane	87	70-130
1,2-Dichloroethane	88	70-130
Trichloroethene	91	70-130
1,1,2-Trichloroethane	87	70-130
Tetrachloroethene	106	70-130
1,1,2,2-Tetrachloroethane	85	70-130

Container Type: NA - Not Applicable

Surrogates	%Recovery	Method Limits
Toluene-d8	104	70-130
1,2-Dichloroethane-d4	92	70-130
4-Bromofluorobenzene	114	70-130

eurofins | Air Toxics

Client Sample ID: LCSD

Lab ID#: 2306407-10AA

EPA METHOD TO-15 GC/MS FULL SCAN

File Name:	**91062105**	**Date of Collection: NA**	
Dil. Factor:	**1.00**	**Date of Analysis: 6/21/23 01:00 PM**	

Compound	%Recovery	Method Limits
Vinyl Chloride	117	70-130
1,1-Dichloroethene	107	70-130
trans-1,2-Dichloroethene	102	70-130
1,1-Dichloroethane	94	70-130
cis-1,2-Dichloroethene	95	70-130
1,1,1-Trichloroethane	89	70-130
1,2-Dichloroethane	93	70-130
Trichloroethene	92	70-130
1,1,2-Trichloroethane	83	70-130
Tetrachloroethene	106	70-130
1,1,2,2-Tetrachloroethane	82	70-130

Container Type: NA - Not Applicable

Surrogates	%Recovery	Method Limits
Toluene-d8	106	70-130
1,2-Dichloroethane-d4	96	70-130
4-Bromofluorobenzene	116	70-130

eurofins | Air Toxics

Analysis Request /Canister Chain of Custody

For Laboratory Use Only

PID: _____ Workorder #: _____

2306407

200-68590 Chain of Custody

180 Blue Ravine Rd. Suite B, Folsom, CA 95630
Phone (800) 985-5955; Fax (916) 351-8279

Client: Bayshore
Project Name: Bayshore B2
Project Manager: Heidi Woelfel Project # 20.0150885.27
Sampler: TBH
Site Name:

Special Instructions/Notes:

Turnaround Time (Rush surcharges may apply)
Standard X Rush _____(specify)

Lab ID	Field Sample Identification(Location)	Can #	Flow Controller #	Start Sampling Information		Stop Sampling Information		Canister Vacuum/Pressure		Lab Use Only		Requested Analyses			
				Date	Time	Date	Time	Initial (in Hg)	Final (in Hg)	Receipt	Final (psig) Gas: N_2 / He				
01A	SS-1	6L1754	23412	6/7/23	0912	6/7/23	0944	-27	-7						
02A	SS-2	6L1258	24067		0933		1010	-27	-5.5						
03A	SS-3	6L2169	24373		0952		1027	-28.5	-5						
04A	SS-4	6L0890	23218		1008		1049	-28	-5.5						
05A	SS-5	6L0157	23563		1028		1105	-28.5	-5.5						
06A	SS-6	6L1625	23542		1046		1120	-29.5	-7						
07A	OAS-1	6L1995	24951		1129		1204	-28	-6.5						

Relinquished by: (Signature/Affiliation)	Date	Time	Received by: (Signature/Affiliation)	Date	Time
[signature]	6/7/23	1330	ETA Bus	6/8/23	10:50
Relinquished by: (Signature/Affiliation)	Date	Time	Received by: (Signature/Affiliation)	Date	Time
			[signature] FedEx	6/14/23	10:58
Relinquished by: (Signature/Affiliation)	Date	Time	Received by: (Signature/Affiliation)	Date	Time

Lab Use Only:

Shipper Name: FedEx | Custody Seals Intact? | Yes | No | None

Sample Transportation Notice: Relinquishing signature on this document indicates that samples are shipped in compliance with all applicable local, State, Federal, and international laws, regulations, and ordinances of any kind. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Eurofins Air Toxics against any claim, demand, or action, of any kind, related to the collection, handling, of shipping of samples. D.O.T Hotline (800) 467-4922