FLINT HILLS
resources

September 14, 2017

Mr. Rick Joslin
Remediation and Redevelopment Program
Wisconsin Department of Natural Resources
625 East County Road Y, Suite 700
Oshkosh, WI 54901

RE: Spill Notification Follow-Up Report (SERTS # 20170817NE20-1)
Flint Hills Resources Pine Bend, LLC – Waupun Terminal
N4240 Highway 26
Waupun, WI 53963

Dear Mr. Joslin:

Flint Hills Resources Pine Bend, LLC (FHR) is submitting this report in response to your email on August 21, 2017, regarding the spill of approximately five (5) gallons of gasoline to asphalt and soil at the FHR – Waupun Terminal on August 17, 2017.

- Summary of the spill Incident:

  At approximately 12:00 pm on August 17, 2017, an empty gasoline tanker truck entered FHR – Waupun terminal from the east side of the terminal. When the driver was making a turn to the north onto the asphalt driveway, the truck was too close to one of the bollards and a dry break coupler on the truck struck the bollard and cracked a portion of the pipe behind it located on the truck. Approximately 5 gallons of gasoline residue in the cracked pipe spilled onto the asphalt driveway and migrated up to 2 ft toward the adjacent soil. The total area covered by the spill was approximately 15 ft by 2 ft. The spill did not reach the Terminal storm water pond on the east side of the driveway. The location of the spill is marked as the red stripe on the attached site map and redlined in the attached pictures.

- Reporting:

  FHR reported this spill incidence to the WDNR at 12:20 pm on August 17, 2017 by calling the spill hotline.

- Remediation activities:

  Immediately upon discovery of the spill, FHR started remediation activities. Twenty pounds of absorbent was applied to the impacted asphalt. The impacted soil was excavated about 6 inches deep. The excavation and cleanup activities were completed by 4 pm on August 17, 2017. The excavated area was filled with clean soil. The used absorbent and excavated soil were contained in three DOT 55-gallon drums and analyzed for the purpose of waste determination. The waste will be disposed of per RCRA requirements.

If you have any questions about this report or need any additional information related to this spill incident, please contact me at (651) 438-1572 at by email at Ling.Li@fhr.com.
Sincerely,

Flint Hills Resources, LP

Ling Li
Environmental Engineer

cc: Mr. Joe Sliper, FHR Waupun Terminal Manager (electronic)

Attachment: Site Location Map
Pictures of the Spill Location before and after Cleanup

N4240 WI-26
Spill Location
N

Picture 1.FHR- Waupun Terminal Gasoline Spill: Initial Location

Picture 2. FHR- Waupun Terminal Gasoline Spill: Impacted Driveway and Soil

Picture 3. FHR- Waupun Terminal Gasoline Spill: Impacted Driveway and Soil after Cleanup

(Picture taken from the south)

Picture 4. FHR- Waupun Terminal Gasoline Spill: Impacted Driveway and Soil after Cleanup

(Picture taken from the north)