


14 13  
23 24

13 18  
24 19

Oxford 3 Mi.


82

T.B.M. "X" is a square nail driven into the base of a 3" diameter willow tree growing at the waters edge 18' East of the public boat landing on the North shore of the lake.  
Assumed Elevation = 100.00'  
Water Level = 99.00'



EQUIPMENT RECORDING SONAR MAPPED SEPT. 1978

TOPOGRAPHIC SYMBOLS		LAKE BOTTOM SYMBOLS	
(B) Brush	Steep slope	P. Peat	B Boulders
(PW) Partially wooded	~ Indefinite shoreline	Mk. Muck	⊙ Stumps & Snags
(W) Wooded	Marsh	C. Clay	⊙ Rock danger to navigation
(C) Cleared	Spring	M. Marl	T Submergent vegetation
(P) Pastured	Intermittent stream	Sd. Sand	⊥ Emergent vegetation
(A) Agricultural	Permanent inlet	Sl. Silt	⊥ Floating vegetation
B.M. Bench Mark	Permanent outlet	Gr. Gravel	⊥ Brush shelters
■ Dwelling	Dam	R. Rubble	
■ Resort	D.N.R. State owned land	Br. Bedrock	
■ Comp			



Access Access with Parking Boat Livery

Drawn by: G.Thuesen  
Field work by: J.Smith, Kenneth R. Arnold, Dennis Bauer

SPECIES OF FISH	Abundant Common Present		
	Abundant	Common	Present
Muskie			
N. Pike			X
Walleye			
L.M. Bass	X		
S.M. Bass			
Panfish	X		
Trout			

WATER AREA 58.80 ACRES  
UNDER 3 FT. 30.66 %  
OVER 20 FT. 19.33 %  
MAX. DEPTH 56 FEET.  
TOTAL ALK. 152 P.P.M.  
VOLUME 656.29 ACRE FT.  
MAIN SHORELINE 2.22 MI.  
ISLAND SHORELINE 0 MI.

ADAMS CO. MARQUETTE CO.  
R-7-E R-8-E

Source: Wisconsin Department of Natural Resources 608-266-2621  
Crooked Lake – Adams County, Wisconsin DNR Lake Map  
Date – Sep 1978 - Historical Lake Map - Not for Navigation  
A Public Document - Please Identify the Source when using it.