



B.M. 'X' Top of south retaining wall of dam
next to feed mill on east end of pond.
Assumed elevation = 100.00'
Water level = 98.5'

EQUIPMENT SONAR-POLE MAPPED AUG. 1972
MONTH YEAR

- | TOPOGRAPHIC SYMBOLS | | LAKE BOTTOM SYMBOLS | |
|-----------------------|----------------------------|---------------------|-----------------------------|
| (B) Brush | Steep slope | P. Peat | B Boulders |
| (PW) Partially wooded | - - - Indefinite shoreline | Mk. Muck | o Stumps & Snags |
| (W) Wooded | Marsh | C. Clay | ⊗ Rock danger to navigation |
| (C) Cleared | Spring | M. Marl | T Submergent vegetation |
| (P) Pastured | Intermittent stream | Sd. Sand | ⊥ Emergent vegetation |
| (A) Agricultural | Permanent inlet | St. Silt | ⊏ Floating vegetation |
| B.M. Bench Mark | Permanent outlet | Gr. Gravel | ⊕ Brush shelters |
| ■ Dwelling | Dam | R. Rubble | |
| □ Resort | D.N.R. State owned land | Br. Bedrock | |
| □ Camp | | | |



Access Access with Parking Boat Livery
 Drawn by: G. Thuesen
 Field work by: D. Boese, J. O'Brien, M. Schrage

SPECIES OF FISH	Abundance		
	Abundant	Common	Present
Muskie			
N. Pike		X	
Walleye			
L.M. Bass		X	
S.M. Bass			
Panfish		X	
Trout			X

WATER AREA 32.9 ACRES
 UNDER 3 FT. 40.03 %
 OVER 20 FT. 0 %
 MAX. DEPTH 10 FEET.
 TOTAL ALK. 102 P.P.M.
 VOLUME 127,455 ACRE FT.
 MAIN SHORELINE 1.88 MI.
 ISLAND SHORELINE 0 MI.

Source: Wisconsin Department of Natural Resources 608-266-2621
Caroline Pond – Shawano County, Wisconsin DNR Lake Map
Date – Aug 1972 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.