




Temporary
B.M. - Top of lakeside at culvert by intermittent
outlet at S.E. corner of lake
Elevation = 100.00'
Water elevation = 97.10' taken July 1969



N

Sec. 22
Sec. 23



Sec. 23
Sec. 26

EQUIPMENT RECORDING SONAR MAPPED JULY 1969

- TOPOGRAPHIC SYMBOLS
- (B) Brush
 - (PW) Partially wooded
 - (W) Wooded
 - (C) Cleared
 - (P) Pastured
 - (A) Agricultural
 - B.M. Bench Mark
 - Dwelling
 - Resort
 - Camp

- LAKE BOTTOM SYMBOLS
- P. Peat
 - Mk. Muck
 - C. Clay
 - M. Marl
 - Sd. Sand
 - St. Silt
 - Gr. Gravel
 - R. Rubble
 - Br. Bedrock
 - B Boulders
 - ⊙ Stumps & Snags
 - ⊙ Rock danger to navigation
 - T Submergent vegetation
 - ⊥ Emergent vegetation
 - ⊥ Floating vegetation
 - ⊥ Brush shelters



Access Access with Parking Boat Livery
Drawn by: T. Ginder
Field work by: J. Smith

SPECIES OF FISH	ABUNDANCE	
	Abundant	Present
Muskie		
N. Pike		X
Walleye		
L.M. Bass	X	
S.M. Bass	X	
Panfish	X	
Trout		

WATER AREA 15.2 ACRES
UNDER 3 FT. 11.7 %
OVER 20 FT. 0 %
MAX. DEPTH 21 FEET.
TOTAL ALK. 8 P.P.M.
VOLUME 165.46 ACRE FT.
SHORELINE .73 MILES

Source: Wisconsin Department of Natural Resources 608-266-2621
Indian Lake – Langlade and Oneida Counties, Wisconsin DNR Lake Map
Date Jul 1969 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.