



Department of Natural Resources Bench Mark.
Railroad spike in base of 30" oak located 20'
south of centerline of access road, 25' east
of water's edge and 120' southwest of southwest
corner of house.
Assumed Elevation 100.00'
Water Elevation 87.60'

EQUIPMENT RECORDING SONAR MAPPED JULY 1969

TOPOGRAPHIC SYMBOLS		LAKE BOTTOM SYMBOLS	
(B) Brush	Steep slope	P. Peat	B Boulders
(PW) Partially wooded	~ Indefinite shoreline	Mk. Muck	⊙ Stumps & Snags
(W) Wooded	⊕ Marsh	C. Clay	⊙ Rock danger to navigation
(C) Cleared	⊕ Spring	M. Marl	T Submergent vegetation
(P) Pastured	~ Intermittent stream	Sd. Sand	⊥ Emergent vegetation
(A) Agricultural	~ Permanent inlet	St. Silt	⊕ Floating vegetation
B.M. Bench Mark	~ Permanent outlet	Gr. Gravel	⊕ Brush shelters
■ Dwelling	⊕ Dam	R. Rubble	
■ Resort	D.N.R. State owned land	Br. Bedrock	
⊕ Camp			



◆ Access ◆ Access with Parking ◆ Boat Livery

Drawn by: J. Roth
Field work by: C. Busch, C. Belter

SPECIES OF FISH	Abundance		
	Abundant	Common	Present
Muskie			
N. Pike		X	
Walleye		X	
L. M. Bass		X	
S. M. Bass		X	
Panfish		X	
Trout			

WATER AREA 60.3 ACRES
UNDER 3 FT. 13 %
OVER 20 FT. 51 %
MAX. DEPTH 67 FEET.
TOTAL ALK. 10 P.P.M.
VOLUME 1,520.6 ACRE FT.
SHORELINE 2.30 MILES
WITHOUT ISL. 2.13 MILES

Source: Wisconsin Department of Natural Resources 608-266-2621
Spring Lake – Barron County, Wisconsin DNR Lake Map
Date – Jul 1969 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.