



B.M. 'X' Spike in base of oak tree at
 waters edge
 Assumed elev. 100.0'
 Water elev 96.0'



This body of water subject to widely
 fluctuating water levels and at time of
 survey was at a high level




SPECIES OF FISH	Abundance	
	Common	Rare
Muskie		
N. Pike		
Walleye	X	
L.M. Bass	X	
S.M. Bass		
Panfish		X
Trout		

EQUIPMENT RECORDING SONAR MAPPED JUNE 1966
 MO. YR.

- TOPOGRAPHIC SYMBOLS
- (B) Brush
 - (PW) Partially wooded
 - (W) Wooded
 - (C) Cleared
 - (P) Pastured
 - (A) Agricultural
 - B.M. Bench Mark
 - Dwelling
 - Resort

WATER ELEV. 96.0

- LAKE BOTTOM SYMBOLS
- P. Peat
 - Mk. Muck
 - C. Clay
 - M. Marl
 - Sd. Sand
 - St. Silt
 - Gr. Gravel
 - R. Rubble
 - Br. Bedrock
 - T. Submergent vegetation
 - ↓ Emergent vegetation
 - ⊠ Floating vegetation
 - Stumps & Snags



◇ Access ◇ Access with Parking ◇ Boat Livery
 Field work by: R. Chap Drawn by: C. Holt

133.2 WITH IS.
 AREA 129.2 ACRES
 UNDER 3FT. 21 %
 OVER 20FT. 22.4 %
 VOLUME 1625.9 ACRE FT.
 TOTAL ALK. 25 P.P.M.
 SHORELINE 5.6 MILES
 MAX. DEPTH 32 FEET

Source: Wisconsin Department of Natural Resources 608-266-2621
Squaw Lake – St. Croix County, Wisconsin DNR Lake Map
Date – Jun 1966 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.