

Balsam Lake Watershed Tributary Sample Sites



Balsam Branch Subwatershed




3.4 Miles


0 0.425 0.85

1.7


2.55




Harder Creek Subwatershed




Otter Creek Subwatershed




Rice Creek Subwatershed





Balsam Branch Subwatershed Flow Paths




3.4 Miles


0.425 0.85

1.7


2.55




Harder Creek Subwatershed Flow Paths





Otter Creek Subwatershed Flow Paths





Rice Creek Subwatershed Flow Paths














Harder Creek Watershed Land Use




Otter Creek Watershed Land Use




Rice Creek Watershed Land Use





Water Quality Management Area - Land Use Balsam Lake Watershed




Legend


Land Use Forest Grassland Pasture Row Crop Mixed Ag


> Barn Yard Road

Open Water


Wetland









Harder Creek Watershed Priorities for Protection





Otter Creek Watershed Priorities for Protection





Rice Creek Watershed Priorities for Protection
























































































































2015 Loveless Lake General Shoreline Condition Within 35 Feet









2015 Loveless Lake Tall Shoreland Vegetation





Present



0.1


0.05






0.4


2015 Loveless Lake Dominant Shoreland Vegetation and Ground Cover




Dominant Vegetation and Ground Condition



2015 Loveless Lake Shoreland Disturbances



2015 Loveless Lake Woody Structure



Woody Structure

Woody structure







