

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name UPPER MIDDLE INLET	Waterbody ID Code 526100	Sample ID (YYYYMMDD-CY-FD) 20161017-38-05
---	------------------------------------	---

Sampling Location	Database Key 133649798
--------------------------	----------------------------------

SWIMS Station ID 10017086	SWIMS Station Name UPPER MIDDLE INLET - NEJEDLO ROAD
-------------------------------------	--

Latitude 45.3522216	Longitude -88.0058655	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
-------------------------------	---------------------------------	---	--

Basin (WMU) GREEN BAY	Watershed Name MIDDLE INLET AND LAKE NOQUEBAY	County MARINETTE
---------------------------------	---	----------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) ANDREW HUDAK	Project Name LAKE NOQUEBAY TWA [SECTION 319] 2016
--	---

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 5	Estimated Area Sampled (m²) 5	Number of Samples in Composite 1	Replicate No. 1 of 1
---------------------------------------	--	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: TWA

Water Temp. (C) 10.2	D.O. (mg/l) 12.2	D.O. (% sat.) 108.6	pH (su) 7.9	Conductivity (umhos/cm) 381	Transparency (cm) 122
--------------------------------	----------------------------	-------------------------------	-----------------------	---------------------------------------	---------------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity → circle units m/s or f/s	Average Stream Depth of reach (m) 0.3	Average Stream Width of reach (m) 5
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 10 Gravel (ladybug to tennisball): 20

Sand: 40 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____

Aquatic Macrophytes: _____ Leaf Snags: 30 Coarse Woody Debris: _____ Other (): _____

Embeddedness of Substrate at Sample Site (%) 50
Canopy Cover at Sample Site (%) 20%

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Watershed	Factors that may be influencing Water Resource Integrity		Local	Watershed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
Physical				Point Source - Specify:			
Bank Erosion				Pasturing of Livestock			
Channelization: - Upstream				Runoff: - Barnyard			
- Downstream				- Construction			
Hydraulic Scour / Channel Incision				- Cropland			
Impoundment: - Upstream				- Urban			
- Downstream				Septic Systems			
Low Flow				Tile Drainage - Organic Soils			
Sedimentation				- Mineral Soils			
Sludge				Springs			
Thermal				Tributary(s)			
Turbidity				Wetland			
Other - Specify:				Other - Specify:			

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>McKayla Gronholm</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>13%</i>
Date Processed <i>11/13/16</i>	Specimens Saved <i>Subsample archived in ABC until Feb 2020</i>	

B3: 84
 E2: 66

162