

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name LOWER MIDDLE INLET	Waterbody ID Code 529100	Sample ID (YYYYMMDD-CY-FD) 20161017-38-07
---	------------------------------------	---

Sampling Location	Database Key 133649770
--------------------------	----------------------------------

SWIMS Station ID 10022480	SWIMS Station Name LOWER MIDDLE INLET - HWY 141 UPSTREAM
-------------------------------------	--

Latitude 45.28622	Longitude -87.99173	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
-----------------------------	-------------------------------	---	--

Basin (WMU) GREEN BAY	Watershed Name MIDDLE INLET AND LAKE NOQUEBAY	County MARINETTE
---------------------------------	---	----------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) ANDREW HUDAK	Project Name LAKE NOQUEBAY TWA [SECTION 319] 2016
--	---

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 5	Estimated Area Sampled (m²) 4	Number of Samples in Composite 1	Replicate No. 1 of 1
---------------------------------------	--	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: TWA

Water Temp. (C) 11.7	D.O. (mg/l) 10.8	D.O. (% sat.) 101.6	pH (su) 7.85	Conductivity (umhos/cm) 474	Transparency (cm) 122
--------------------------------	----------------------------	-------------------------------	------------------------	---------------------------------------	---------------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity — circle units m/s or f/s	Average Stream Depth of reach (m) 0.2	Average Stream Width of reach (m) 4
---	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 50 Gravel (ladybug to tennisball): 20

Sand: 20 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____

Aquatic Macrophytes: _____ Leaf Snags: 10 Coarse Woody Debris: _____ Other (): _____

Embeddedness of Substrate at Sample Site (%) 40 Canopy Cover at Sample Site (%) 70

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
Physical				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Cadie Olson</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>7%</i>
Date Processed <i>11/14/16</i>	Specimens Saved <i>Subsample archived in ABC until Feb 2020</i>	

B2: (116) 128