

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name BLACK RIVER		Waterbody ID Code 2836900	Sample ID (YYYYMMDD-CY-FD) 20161006-16-04
Sampling Location 40m US Milchesky Rd.			Database Key 134667175
SWIMS Station ID 10010225		SWIMS Station Name BLACK RIVER - BLACK RIVER UPSTREAM OF MILCHESKY RD.	
Latitude 46.47557	Longitude -92.13245	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS <u>WGS84</u> or NAD83
Basin (WMU) LAKE SUPERIOR		Watershed Name BLACK AND UPPER NEMADJI RIVER	County DOUGLAS

Sample and Site Descriptors

Sample Collector (Last Name, First) CRAIG P ROESLER, MADELINE E ROBERTS	Project Name BLACK RIVER TWA TALU 2016
---	--

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 0.75	Number of Samples in Composite 2	Replicate No. 1 of 1
---------------------------------------	---	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 12.9	D.O. (mg/l) 8.2	D.O. (%sat.)	pH (su) 7.2	Conductivity (umhos/cm) 73	Transparency (cm) 92
--------------------------------	---------------------------	---------------------	-----------------------	--------------------------------------	--------------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity 1.4	circle units m/s or <u>(f/s)</u>	Average Stream Depth of reach (m) 7.5	Average Stream Width of reach (m) 0.3
---------------------------------	-------------------------------------	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 20 Gravel (ladybug to tennisball): 80
 Sand: _____ Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 10 **Canopy Cover at Sample Site (%)** 0

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water- shed	Factors that may be influencing Water Resource Integrity	Local	Water- shed
Biological			Chemical		
Algae: - Diatoms / Periphyton			Chlorine		
- Filamentous Algae			Dissolved Oxygen		
- Planktonic Algae			Nutrients (P, N...)		
Iron Bacteria			Toxics: - Inorganic (Metals)		
Macrophytes			- Organic (PCBs, pesticides...)		
Slimes			Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion		
			Point Source - Specify:		
Physical			Pasturing of Livestock		
Bank Erosion			Runoff: - Barnyard		
Channelization: - Upstream			- Construction		
- Downstream			- Cropland		
Hydraulic Scour / Channel Incision			- Urban		
Impoundment: - Upstream			Septic Systems		
- Downstream			Tile Drainage - Organic Soils		
Low Flow			- Mineral Soils		
Sedimentation			Springs		
Sludge			Tributary(s)		
Thermal			Wetland		
Turbidity			Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Mekayla Gronholm</i>	Taxonomist <i>Dimick Jeffrey</i>	Estimated Percent of Sample Sorted <i>13%</i>
Date Processed <i>11/21/16</i>	Specimens Saved <i>Subsample archived in ABL until Feb 2020</i>	

*C2: 91
 A2: 59*

148