

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name Black River		Waterbody ID Code 2836900	Sample ID (YYYYMMDD-CY-FD) 20161010-16-03
Sampling Location 110m US STH 35			Database Key 134667103
SWIMS Station ID 10046991		SWIMS Station Name BLACK RIVER 410 M DS OF STH 35	
Latitude 46.44787	Longitude -92.16588	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) LAKE SUPERIOR		Watershed Name BLACK AND UPPER NEMADJI RIVER	County DOUGLAS

Sample and Site Descriptors

Sample Collector (Last Name, First) CRAIG P ROESLER, MADELINE E ROBERTS	Project Name BLACK RIVER TWA TALU 2016
---	--

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 15	Estimated Area Sampled (m²) 1.5	Number of Samples in Composite 3	Replicate No. 1 of 1
--	--	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 11.1	D.O. (mg/l) 9.8	D.O. (% sat.)	pH (su) 7.1	Conductivity (umhos/cm) 56	Transparency (cm) 100
--------------------------------	---------------------------	----------------------	-----------------------	--------------------------------------	---------------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity 1 circle units m/s or f/s	Average Stream Depth of reach (m) 0.4	Average Stream Width of reach (m) 8
---	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 10 Gravel (ladybug to tennisball): 60
 Sand: 30 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 10 **Canopy Cover at Sample Site (%)** 0

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water-shed	Factors that may be influencing Water Resource Integrity	Local	Water-shed
Biological			Chemical		
Algae: - Diatoms / Periphyton			Chlorine		
- Filamentous Algae			Dissolved Oxygen		
- Planktonic Algae			Nutrients (P, N...)		
Iron Bacteria			Toxics: - Inorganic (Metals)		
Macrophytes			- Organic (PCBs, pesticides...)		
Slimes			Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion		
			Point Source - Specify:		
Physical			Pasturing of Livestock		
Bank Erosion			Runoff: - Barnyard		
Channelization: - Upstream			- Construction		
- Downstream			- Cropland		
Hydraulic Scour / Channel Incision			- Urban		
Impoundment: - Upstream			Septic Systems		
- Downstream			Tile Drainage - Organic Soils		
Low Flow			- Mineral Soils		
Sedimentation			Springs		
Sludge			Tributary(s)		
Thermal			Wetland		
Turbidity			Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>McKayla Gironholm</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>13</i>
Date Processed <i>11/22/16</i>	Specimens Saved <i>Subsample archived in ABC until Feb 2020</i>	

*C3:44
 D1:68*

129