

ORIGINAL



Wisconsin Public Service Corporation
(a subsidiary of WPS Resources Corporation)
700 North Adams Street
P.O. Box 19002
Green Bay, WI 54307-9002

FILED
THE SECRETARY

03 OCT 23 AM 10: 07

FEDERAL ENERGY
REGULATORY COMMISSION

FERC Project No.: 2525, 2595, 2522,
2546, 2560 & 2581

Handwritten notes: 060, 081, 080, 076, 049, 046

October 21, 2003

Ms. Magalle Roman Salas, Secretary
Federal Energy Regulatory Commission
Mail Code: DTCA, HL 21.3
888 First Street, N.E.
Washington, DC 20428

Dear Secretary Salas:

Caldron Falls, High Falls, Johnson Falls, Sandstone Rapids, Potato Rapids, and Peshtigo Hydroelectric Projects

As per the order approving the Comprehensive Land and Wildlife Management Plan for the Caldron Falls Project (FERC Project No. 2525), High Falls Project (FERC Project 2595), Johnson Falls Project (FERC Project 2522), Sandstone Rapids Project (FERC Project No. 2546), Potato Rapids Project (FERC Project No. 2560) and the Peshtigo Project (FERC Project No. 2581) issued on August 20, 1998, Wisconsin Public Service Corporation (WPSC) is submitting the annual survey results for purple loosestrife and zebra mussels. Eurasian water milfoil is surveyed every three years, with the next survey scheduled for 2005.

All of the above-mentioned projects were surveyed for purple loosestrife in July or early August of 2003. The presence of purple loosestrife was only identified at the Peshtigo Project where there is a history of occurrence. A map indicating the location and colony size is located in Appendix 1.

Monthly inspections of substrate samplers for the presence of zebra mussels were conducted for all six projects for the months of May through September. Zebra mussels were not found at any of the six projects during any of the monthly 2003 inspections. A summary of the results has been included in Appendix 2.

The results from the purple loosestrife and Eurasian water milfoil surveys, and the zebra mussel monitoring have also been sent to the Wisconsin Department of Natural Resources, the U.S. Fish & Wildlife Service, and the Sea Grant Institute. Documentation of the submittal of these results can be found in Appendix 3.

If you have any questions, please do not hesitate to call Rick Moser at (920) 433-2290.



Sincerely,

David W. Harpole
Vice President - Energy Supply
Telephone: (920) 433-1264

Enc.

- cc: Ms. Peggy Harding, FERC - Chicago
- Mr. Dennis Maki, WPSC - WES
- Mr. Steve Schrickel, WPSC - CRI
- Ms. Joan Johaneck, WPSC - D2
- Mr. Randy Oswald, WPSC - A2
- Mr. Bruce Crocker, WPSC - D2

Appendix 1
Purple Loosestrife Colonies on Peshtigo



2003
PESHTIGO
PURPLE LOOSESTRIFE COLONIES

- 1-5
- 6-50
- 50+

Appendix 2
Zebra Mussel Inspection Results

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-21-03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-22-03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-22
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-29
 COMMENTS/RESULTS: NONE

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls Johnson Falls Potato Rapids
- High Falls Sandstone Rapids Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN

DATE: 9-19-3

COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN

DATE: _____

COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN

DATE: _____

COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN

DATE: _____

COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN

DATE: _____

COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls
- Johnson Falls
- Sandstone Rapids
- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4-22-03
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-20
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-18
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-17
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-28
 COMMENTS/RESULTS: None

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls
- Johnson Falls
- Sandstone Rapids
- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: 9/19/03
COMMENTS/RESULTS: none

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-23-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-11-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-14-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-19-3
 COMMENTS/RESULTS: NONE

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-18-7
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6/4/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7/14/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8/18/3
 COMMENTS/RESULTS: NONE

ATTACHMENT A

**ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS**

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: 9-18-03
COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
DATE: _____
COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-1-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-3-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-1-03
 COMMENTS/RESULTS: No zebra mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-1-03
 COMMENTS/RESULTS: NO zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-12-03
 COMMENTS/RESULTS: No Zebra Mussels Present

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-1-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-9-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-20-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-15-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-12-03
 COMMENTS/RESULTS: No Zebra Mussels Present

Appendix 3
Documentation of Submittal



Wisconsin Public Service Corporation
(a subsidiary of WPS Resources Corporation)
700 North Adams Street
P.O. Box 19007
Green Bay, WI 54307-9002

October 15, 2003

Mr. Tom Meronek
Department of Natural Resources
101 N. Ogden Road
Peshtigo, WI 54157

Dear Mr. Meronek:

FERC Project No. 2525, No. 2595, No. 2522, No. 2546, No. 2560, and No. 2581

As per the order approving the Comprehensive Land and Wildlife Management Plan for the Caldron Falls Project (FERC Project No. 2525), High Falls Project (FERC Project 2595), Johnson Falls Project (FERC Project 2522), Sandstone Rapids Project (FERC Project No. 2546), Potato Rapids Project (FERC Project No. 2560) and the Peshtigo Project (FERC Project No. 2581) issued on August 20, 1998, Wisconsin Public Service Corporation (WPSC) is submitting the survey results for purple loosestrife, and zebra mussels.

All of the above mentioned projects were surveyed for purple loosestrife in July or early August. The presence of purple loosestrife was only identified at the Peshtigo Project where there is a history of occurrence. A map indicating the location and colony size is located in Appendix A.

Monthly inspections of substrate samplers for the presence of zebra mussels were conducted for all six projects for the months of May through September. Zebra mussels were not found at any of the six projects during any of the monthly 2003 inspections. A summary of the results has been included in Appendix B.

The next Eurasian Water Milfoil survey is scheduled for 2005. If you have any questions, please do not hesitate to call.

Sincerely,

A handwritten signature in cursive script that reads "Rick Moser".

Rick J. Moser
Environmental Consultant
Telephone: (920) 433-2290

vav

Enc.

cc: Ms. Joan Johaneck, WPSC - D2



Wisconsin Public Service Corporation
(a subsidiary of WPS Resources Corporation)
700 North Adams Street
P.O. Box 19062
Green Bay, WI 54307-9002

October 15, 2003

Ms. Janet Smith
U.S. Fish and Wildlife Service
1015 Challenger Court
Green Bay, WI 54311

Dear Ms. Smith:

FERC Project No. 2525, No. 2595, No. 2522, No. 2546, No. 2560, and No. 2581

As per the order approving the Comprehensive Land and Wildlife Management Plan for the Caldron Falls Project (FERC Project No. 2525), High Falls Project (FERC Project 2595), Johnson Falls Project (FERC Project 2522), Sandstone Rapids Project (FERC Project No. 2546), Potato Rapids Project (FERC Project No. 2560) and the Peshtigo Project (FERC Project No. 2581) issued on August 20, 1998, Wisconsin Public Service Corporation (WPSC) is submitting the survey results for purple loosestrife, and zebra mussels.

All of the above mentioned projects were surveyed for purple loosestrife in July or early August. The presence of purple loosestrife was only identified at the Peshtigo Project where there is a history of occurrence. A map indicating the location and colony size is located in Appendix A.

Monthly inspections of substrate samplers for the presence of zebra mussels were conducted for all six projects for the months of May through September. Zebra mussels were not found at any of the six projects during any of the monthly 2003 inspections. A summary of the results has been included in Appendix B.

The next Eurasian Water Milfoil survey is scheduled for 2005. If you have any questions, please do not hesitate to call.

Sincerely,

Rick J. Moser
Environmental Consultant
Telephone: (920) 433-2290

vav

Enc.

cc: Ms. Joan Johaneck, WPSC - D2



Wisconsin Public Service Corporation
a subsidiary of WPS Resources Corporation
100 North Adams Street
P.O. Box 19007
Green Bay, WI 54307-9007

October 20, 2003

Mr. Phil Moy
UW Manitowoc
705 Viebahn St.
Manitowoc, WI 54220

Dear Mr. Moy:

FERC Project No. 2525, No. 2595, No. 2522, No. 2546, No. 2560, and No. 2581

As per the order approving the Comprehensive Land and Wildlife Management Plan for the Caldron Falls Project (FERC Project No. 2525), High Falls Project (FERC Project 2595), Johnson Falls Project (FERC Project 2522), Sandstone Rapids Project (FERC Project No. 2546), Potato Rapids Project (FERC Project No. 2560) and the Peshtigo Project (FERC Project No. 2581) issued on August 20, 1998, Wisconsin Public Service Corporation (WPSC) is submitting the survey results for purple loosestrife and zebra mussels.

All of the above mentioned projects were surveyed for purple loosestrife in July or early August. The presence of purple loosestrife was only identified at the Peshtigo Project where there is a history of occurrence. A map indicating the location and colony size is located in Appendix A.

Monthly inspections of substrate samplers for the presence of zebra mussels were conducted for all six projects for the months of May through September. Zebra mussels were not found at any of the six projects during any of the monthly 2003 inspections. A summary of the results has been included in Appendix B.

The next Eurasian water milfoil survey is scheduled for 2005. If you have any questions, please do not hesitate to call.

Sincerely,

A handwritten signature in black ink that reads "Rick Moser".



Rick J. Moser
Environmental Consultant
Telephone: (920) 433-2290

vav

Enc.

cc: Ms. Joan Johaneck, WPSC - D2

Appendix A
Purple Loosestrife Colonies on Peshtigo



2003
PESHTIGO
PURPLE LOOSESTRIFE COLONIES

- 1-5
- 6-50
- 50+

Appendix B
Zebra Mussel Inspection Results

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-21-03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-22-03
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-22
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-29
 COMMENTS/RESULTS: NONE

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-19-3
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4-22-03
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-20
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-18
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-17
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-28
 COMMENTS/RESULTS: None

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHITIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls
- Johnson Falls
- Sandstone Rapids
- Potato Rapids
- Peshigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9/19/3
 COMMENTS/RESULTS: None

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-23-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-11-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-14-3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-15-3
 COMMENTS/RESULTS: NONE

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-18-02
 COMMENTS/RESULTS: see

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- High Falls

- Johnson Falls
- Sandstone Rapids

- Potato Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 4/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5/23/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6/11/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7/14/3
 COMMENTS/RESULTS: NONE

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8/18/3
 COMMENTS/RESULTS: NONE

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-18-03
 COMMENTS/RESULTS: N/A

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: _____
 COMMENTS/RESULTS: _____

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-1-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-3-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-1-03
 COMMENTS/RESULTS: No zebra mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-1-03
 COMMENTS/RESULTS: No zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-12-03
 COMMENTS/RESULTS: No Zebra Mussels Present

ATTACHMENT A

ZEBRA MUSSEL INSPECTION RESULTS
PESHTIGO RIVER HYDROELECTRIC PROJECTS

HYDRO NAME

- Caldron Falls
- Johnson Falls
- Potato Rapids
- High Falls
- Sandstone Rapids
- Peshtigo

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 5-1-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 6-9-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 7-20-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 8-15-03
 COMMENTS/RESULTS: No Zebra Mussels Present

INSPECTION TYPE: MONTHLY INSPECTION INSPECTION DURING DRAWDOWN
 DATE: 9-12-03
 COMMENTS/RESULTS: No Zebra Mussels Present